

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22006917/APA3Q2**Date:** 19/04/2023REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SP2000784061-01
Claimant Vehicle No : SLT2947H **Insured Vehicle No :** SJS3060M
 Date of Loss: 17/07/2022 Nature of Claim: TP Claim No: 202222005693SL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT2947H**
 Make & Model: OPEL ASTRA ST, 1.0 AT (A) Engine No: B1170877HRXX0135
 Reg. Date: 25/10/2017 (Man. Year: 2017) Chassis No: W0LBE8EA0H8086707
 Colour: Brown Odometer: 109928 km
 Engine Capacity: 999 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,122.70	6,447.00	17,675.70	73.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,080.00	1,550.00	3,530.00	69.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,202.70	7,997.00	21,205.70	72.62
Approved Total (Overridden) (S\$)		6,400.00		
(S\$)	29,202.70	6,400.00	22,802.70	78.08
+ GST 7.00/7.00% (S\$)	2,044.19	448.00	1,596.19	78.08
Nett Amount (S\$)	31,246.89	6,848.00	24,398.89	78.08
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		38.45		
Nett Liability (S\$)		7,306.45		
Global Sum Settlement (S\$)		7,300.00		

INSPECTION

Date of Assignment: 20/07/2022
 Date Inspected: 21/07/2022 Inspected At: Xin Hua Workshop Pte Ltd (HQ)
 23 Kaki Bukit Ave 4 #04-01
 Singapore 415933
 Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 19 Apr 2023)	
Parts:	N/A	OPEL ASTRA ST 1.0 AT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT2947H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET	Not Necessary	1,534.00 FL	*- FL
2	1		*FRT BUMPER	Deformed	1,941.00 FL	*1,941.00 FL
3	1		*FRT BUMPER LOW LIP LH	Not Necessary	156.00 FL	*- FL
4	1		*FRT BUMPER SIDE RETAINER LH-GUIDE	Not Necessary	136.00 FL	*- FL
5	1		*FRT BUMPER SIDE RETAINER LH-UPP	Damaged	106.00 FL	*106.00 FL
6	1		*FRT BUMPER BRACKET LH	Not Necessary	192.00 FL	*- FL
7	1		*FRT BUMPER UNDER DUST COVER	Not Necessary	290.00 FL	*- FL
8	1		*FRT BUMPER BRACKET TOP CENTRE	Not Necessary	202.00 FL	*- FL
9	1		*FRT BRACE BRACKET LH	Not Necessary	118.00 FL	*- FL
10	1		*FRT BUMPER SPONGE	Not Necessary	282.00 FL	*- FL
11	1		*FRT BUMPER REINFORCEMENT UPP (METAL)	Not Necessary	853.00 FL	*- FL
12	1		*FRT BUMPER REINFORCEMENT LOW (FIRBE)	Not Necessary	374.00 FL	*- FL
13	1		*FRT BUMPER PARKING SENSOR	Not Necessary	272.00 FL	*- FL
14	4		*FRT BUMPER PARKING SENSOR SEAL	Not Necessary	48.00 FL	*- FL
15	1		*FRT BUMPER PARKING SENSOR WIRE HARNESS	Not Necessary	777.00 FL	*- FL
16	1		*FRT GRILLE ASSY	Not Necessary	1,380.00 FL	*- FL
17	1		*FRT GRILLE LOGO	Not Necessary	163.00 FL	*- FL
18	1		*FRT LOW CENTRE GRILLE	Not Necessary	207.00 FL	*- FL
19	1		*FRT LOW GRILLE LH	Not Necessary	132.00 FL	*- FL
20	1		*LH HEADLAMP	Cracked	913.00 FL	*913.00 FL
21	1		*LH FOG LAMP	Not Necessary	417.00 FL	*- FL
22	1		*LH FOG LAMP COVER	Not Necessary	247.00 FL	*- FL
23	1		*FRT FENDER LH	Repair	663.00 FL	*- FL
24	1		*FRT FENDER SIGNAL LAMP LH	Not Necessary	146.00 FL	*- FL
25	1		*FRT FENDER BRACKET LH	Not Necessary	192.00 FL	*- FL
26	1		*FRT FENDER INNERSHIELD LH	Not Necessary	144.00 FL	*- FL
27	1		*FRT HEADLAMP PANEL LH	Not Necessary	160.00 FL	*- FL
28	1		*RADIATOR	Not Necessary	1,424.00 FL	*- FL
29	1		*A/C CONDENSER	Not Necessary	1,222.00 FL	*- FL
30	1		*A/C CONDENSER AIR GUIDE LH	Not Necessary	138.00 FL	*- FL
31	1		*INTERCOOLER ,TURBOCHARGE AIR GUIDE	Not Necessary	1,351.00 FL	*- FL
32	1		*INTERCOOLER ,TURBOCHARGER	Not Necessary	1,060.00 FL	*- FL
33	1		*FRT WIPER WASHER TANK	Not Necessary	182.00 FL	*- FL
34	1		*FRT WIPER WASHER TANK PUMP	Not Necessary	214.00 FL	*- FL
35	1		*FRT WIPER WASHER TANK NECK	Not Necessary	158.00 FL	*- FL
36	1		*FRT HORN LH	Not Necessary	227.00 FL	*- FL
37	1		*FRT RIM LH -SIZE -7.5 JX 17	Cut	1,123.00 FL	*1,123.00 FL
38	1		*FRT WHEEL BEARING LH-WITH HUB	Damaged	868.00 FL	*868.00 FL
39	1		*FRT KNUCKLE ARM LH	Damaged	780.00 FL	*780.00 FL
40	1		*FRT LOW ARM LH	Bent	928.00 FL	*928.00 FL
41	1		*FRT SHOCK ABSORBER LH	Damaged	471.00 FL	*471.00 FL
42	1		*FRT STABILIZER LINK LH	Not Necessary	194.00 FL	*- FL
43	1		*FRT DRIVE SHALF LH	Not Necessary	2,446.00 FL	*- FL
44	1		*FRT ABS SENSOR LH -SPEED SENSOR	Not Necessary	362.00 FL	*- FL
45	1		*FRT BRAKE PIPE LH(RUBBER)	Not Necessary	311.00 FL	*- FL
46	1		*FRT SHOCK ABSORBER TOP MOUNTING LH	Not Necessary	349.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	10		*FRT BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
48	10		*FENDER INNERSHIELD CLIP	Not Necessary	60.00 FS	*- FS
49	10		*FRT GRILLE CLIP	Not Necessary	60.00 FS	*- FS
50	1		*RADIATOR COOLANT	Not Necessary	100.00 FS	*- FS
51	1		*FRT NUMBER PLATE	Not Necessary	65.00 FS	*- FS
52	1		*FRT TYRE LH	Not Necessary	350.00 FS	*- FS
53	1		*BODY SEAL	Not Necessary	100.00 FS	*- FS
54	1		*SUNDRIES (SAND PAPER ,WELDING WIRE ETC)	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	26,708.00	7,160.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,585.30	713.00
Total Parts (\$\$)	24,122.70	6,447.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,400.00	600.00
2	CARRY OUT SPRAY PAINTING ON AFFECTED AREA	New	1,400.00	500.00
3	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT	New	100.00	60.00
4	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	120.00	30.00
5	TO REMOVE AND REFIT AIRCON CONDENSOR ,VACUUM ,REFILL AND CHECK AIR CON GAS SYSTEM R1234A GAS	New	600.00	0.00
6	TO REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	100.00	0.00
7	TO REMOVE AND REPLACE LHF UNDER CARRIAGE PARTS	New	300.00	220.00
8	TO CONDUCT 4 WHEEL ALIGNMENT	New	180.00	80.00
9	TO CONDUCT RESET OF ENGINE LIGHT ON	New	350.00	0.00
10	TO CONDUCT RESET OF ABS LIGHT ON	New	350.00	0.00
11	TO REFOCUS HEADLAMP	New	80.00	0.00
12	TO REMOVE AND REFIT FRONT SENSOR	New	100.00	60.00
Gross Labour Cost (S\$)			5,080.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >