

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22006922/AVCM4**Date:** 31/10/2022**REFERENCE**

Insured/Claimant: JEFFREY NG LENG PING (JEFFREY HUANG LONGBIN) Policy No: 7210081614

Date of Loss: 07/06/2022

Nature of Claim: OD

Claim No: 3534479802SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB2328P	Engine No:	DKY015446
Make & Model:	AUDI A6 DESIGN, 2.0 TFSI (140 KW) (A)	Chassis No:	WAUZZZF24MN070259
Reg. Date:	29/07/2021 (Man. Year: 2021)	Odometer:	13032 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$217,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,304.00	11,180.32	8,123.68	42.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,972.00	3,022.00	2,950.00	49.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,276.00	14,202.32	11,073.68	43.81
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	24,676.00	13,602.32	11,073.68	44.88
+ GST 7.00/7.00% (S\$)	1,727.32	952.16	775.16	44.88
Nett Amount (S\$)	26,403.32	14,554.48	11,848.84	44.88

INSPECTION

Date of Assignment: 21/07/2022

Date Inspected: 19/07/2022 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	3,012.00 FS	*2,409.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	658.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - CENTER	Not Necessary	248.00 FS	*- FS
4	1		*FRONT BUMPER ADAPTER - RH	Not Necessary	44.00 FS	*- FS
5	1		*FRONT BUMPER REINFORCEMENT - RH	Not Necessary	125.00 FS	*- FS
6	1		*FRONT BUMPER GRILLE - LOWER CENTER	Not Necessary	171.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT - LOWER	Not Necessary	235.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	485.00 FS	*- FS
9	1		*FRONT BUMPER AIR GUIDE INNER - RH	Not Necessary	33.00 FS	*- FS
10	1		*FRONT BUMPER AIR GUIDE OUTER - RH	Not Necessary	24.00 FS	*- FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	252.00 FS	*- FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	1,076.00 FS	*- FS
13	6		*FRONT BUMPER POP RIVET	Necessary	6.00 FS	*4.32 FS
14	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	67.00 FS	*- FS
15	1		*FORNT BUMPER GUIDE SECTION - RH	Not Necessary	50.00 FS	*- FS
16	1		*FORNT BUMPER BRACKET - RH	Not Necessary	61.00 FS	*- FS
17	1		*FRONT BUMPER TOP COVER	Not Necessary	140.00 FS	*- FS
18	1		*CAUTION STICKER	Not Necessary	16.00 FS	*- FS
19	1		*FRONT PARKING AID SENSOR (TBC) (NPA)	Not Necessary	0.00 FS	*- FS
20	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
21	1		*FRONT FENDER - RH	Dented	1,649.00 FS	*1,319.20 FS
22	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	44.00 FS	*- FS
23	1		*FRONT FENDER BRACE - RH	Dented	137.00 FS	*109.60 FS
24	1		*FRONT FENDER BRACKET UPPER - RH	Not Necessary	49.00 FS	*- FS
25	1		*FRONT WHEEL HOUSING LINER - RH	Not Necessary	299.00 FS	*- FS
26	1		*FRONT WHEEL SPOILER - RH	Not Necessary	185.00 FS	*- FS
27	1		*FRONT WHEEL SPOILER STONE CHIP GUARD - RH	Not Necessary	57.00 FS	*- FS
28	1		*FRONT WHEEL SPOILER TRIM BRACKET - RH	Not Necessary	45.00 FS	*- FS
29	1		*HEADLIGHT MOUNTING - RH	Not Necessary	132.00 FS	*- FS
30	1		*HEADLIGHT MATRIX BEAM - RH	Cut	9,172.00 FS	*7,337.60 FS
31	1		*LIFT CYLINDER - RH	Not Necessary	217.00 FS	*- FS
32	1		*LIFT CYLINDER BRACKET - RH	Not Necessary	7.00 FS	*- FS
33	1		*LIFT CYLINDER HOSE	Not Necessary	204.00 FS	*- FS
34	1		*RADIATOR AIR GUIDE - RH	Not Necessary	44.00 FS	*- FS
35	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **19,304.00** **11,180.32**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,500.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,972.00	3,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >