

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22006923/ACE2**Date:** 06/12/2022**REFERENCE**

Insured/Claimant:	PASCALE BOUCHARD CANNON	Policy No:	1900166583-01
Date of Loss:	16/07/2022	Nature of Claim:	OD
		Claim No:	3103043781SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP4532S		
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Engine No:	CVK081979
Reg. Date:	26/09/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF41KA073898
Colour:	Blue	Odometer:	38299 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$143,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35 R19	Rear Tyre Size:	245/35 R19
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,242.00	5,307.04	15,934.96	75.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,332.00	3,502.00	4,830.00	57.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,574.00	8,809.04	20,764.96	70.21
- Excess (S\$)	550.00	550.00	0.00	0.00
(S\$)	29,024.00	8,259.04	20,764.96	71.54
+ GST 7.00/7.00% (S\$)	2,031.68	578.13	1,453.55	71.54
Nett Amount (S\$)	31,055.68	8,837.17	22,218.51	71.54

INSPECTION

Date of Assignment:	21/07/2022		
Date Inspected:	19/07/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	3,188.00 FS	*2,550.40 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	480.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Necessary	249.00 FS	*198.80 FS
4	1		*REAR BUMPER SPOILER - LH / RH	Cut	276.00 FS	*220.80 FS
5	1		*REAR BUMPER TRIM	Deformed	326.00 FS	*260.80 FS
6	2		*REAR BUMPER BRACKET - LH / RH	Damaged	260.00 FS	*208.00 FS
7	1		*REAR LIGHT REFLECTOR - LH / RH	N/S Cracked	92.00 FS	*36.48 FS
8	2		*REAR LED LICENCE PLATE LIGHT	Not Necessary	209.00 FS	*- FS
9	2		*REAR LED TAIL LIGHT - LH / RH	Not Necessary	2,270.00 FS	*- FS
10	2		*REAR TRIM TAIL LIGHT - LH / RH	Not Necessary	68.00 FS	*- FS
11	2		*REAR LED TAIL LIGHT - LH / RH	Not Necessary	2,270.00 FS	*- FS
12	2		*REAR TRIM TAIL LIGHT - LH / RH	Not Necessary	68.00 FS	*- FS
13	1		*REAR BUMPER BEAM	Not Necessary	1,131.00 FS	*- FS
14	2		*REAR RUBBER SEAL	Not Necessary	32.00 FS	*- FS
15	1		*REAR BUMPER GUIDE SECTION - LH	Not Necessary	49.00 FS	*- FS
16	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	51.00 FS	*- FS
17	2		*REAR BUMPER GUIDE SECTION - LH / RH	Damaged	52.00 FS	*40.32 FS
18	2		*REAR PIN	Not Necessary	6.00 FS	*- FS
19	2		*REAR BUMPER HOLDING STRIP - LH / RH	Cracked	188.00 FS	*149.60 FS
20	1		*REAR RETAINER FOR AERIAL - LH	Not Necessary	29.00 FS	*- FS
21	2		*REAR TELEPHONE AERIAL	Not Necessary	384.00 FS	*- FS
22	1		*REAR OPENEING BOOT LID CONTROL UNIT	Not Necessary	454.00 FS	*- FS
23	1		*REAR TAILGATE OPENING SENSOR LINE	Not Necessary	228.00 FS	*- FS
24	1		*REAR BUMPER CONTROL UNIT RETAINER	Not Necessary	9.00 FS	*- FS
25	1		*REAR BUMPER CROSS PANEL	Not Necessary	120.00 FS	*- FS
26	4		*REAR SENSOR - INNER / OUTER	Not Necessary	265.00 FS	*- FS
27	4		*REAR SEAL RING	Not Necessary	10.00 FS	*- FS
28	1		*SET REAR BUMPER WIRING	Snapped	745.00 FS	*595.60 FS
29	1		*REAR VENT TRIM	N/S Cracked	149.00 FS	*59.52 FS
30	1		*REAR LID	Repair	3,497.00 FS	*- FS
31	1		*REAR LID LOCK	Not Necessary	217.00 FS	*- FS
32	1		*REAR COVER CAP	Not Necessary	8.00 FS	*- FS
33	1		*REAR LID ATTACHMENT PARTS	Not Necessary	429.00 FS	*- FS
34	1		*REAR LID LOCK ACTUATOR	Not Necessary	1,478.00 FS	*- FS
35	1		*REAR LOCK STRIKER	Not Necessary	37.00 FS	*- FS
36	1		*REAR GASKET FOR FLAP	Not Necessary	229.00 FS	*- FS
37	2		*REAR CLIP	Not Necessary	4.00 FS	*- FS
38	1		*REAR PACKING ADHESIVE	Not Necessary	21.00 FS	*- FS
39	1		*AUDI EMBLEM	Necessary	144.00 FS	*114.80 FS
40	1		*INSCRIPTION	Necessary	104.00 FS	*82.80 FS
41	2		*REAR EXHAUST TAIL PIPE TRIM - LH / RH	Dented	766.00 FS	*612.00 FS
42	1		*SUNDRIES	Necessary	500.00 FS	*105.12 FS
43	1		*REAR NO PLATE	Not Necessary	60.00 FS	*- FS
44	2		*REAR BUMPER TRIM - LH / RH	Damaged	90.00 FS	*72.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **21,242.00** **5,307.04**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	0.00
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR BOTH REAR FENDER AND REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,000.00	750.00
4	TO RESPRAY REAR BUMPER, REAR LID, BOTH REAR FENDERS AND REAR END PANELLING	New	4,500.00	2,200.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			8,332.00	3,502.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >