

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**HL Assurance Pte Ltd  
11 Keppel Road, #11-01 ABI Plaza  
Singapore 089057**Our File No:** CS/HLA22006938/KQY3E2**Date:** 21/03/2023**REFERENCE**

Insured/Claimant:	Sharon Wee Hsu Oon	Policy No:	MP307483	
Date of Loss:	17/07/2022	Nature of Claim:	OD	Claim No: MPC03556/WF

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLQ1196E</b>	Engine No:	33159813B37C15A
Make & Model:	BMW 216D, 1.5 (A)	Chassis No:	WBA2E320205H45960
Reg. Date:	28/06/2017 (Man. Year: 2017)	Odometer:	58131 km
Colour:	Metallic Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$94,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/55 R17	Rear Tyre Size:	205/55 R17
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,596.50	5,407.50	189.00	3.38
Miscellaneous Items	220.00	154.00	66.00	30.00
Labour	860.00	560.00	300.00	34.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,676.50</b>	<b>6,121.50</b>	<b>555.00</b>	<b>8.31</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,400.00</b>		
<b>- Excess (S\$)</b>	0.00	300.00	-300.00	
<b>(S\$)</b>	6,676.50	4,100.00	2,576.50	38.59
<b>+ GST 7.00/8.00% (S\$)</b>	467.35	328.00	139.35	29.82
<b>Nett Amount (S\$)</b>	<b>7,143.85</b>	<b>4,428.00</b>	<b>2,715.85</b>	<b>38.02</b>

**INSPECTION**

Date of Assignment:	20/07/2022	Present Location:	S & H Motor Pte Ltd (Sin Ming)
Date Inspected:	21/07/2022	Inspected At:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	4.0 days		

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 21 Mar 2023)
<b>Parts:</b>	143	BMW 216D 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLQ1196E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*LH front wheel rim</b> (WCP)	Dented	900.00 F	*900.00 F
2	1		<b>*LH front knuckle arm</b> (WCP)	Bent	620.00 F	*620.00 F
3	1		<b>*LH front wheel bearing</b> (WCP)	Necessary	280.00 F	*280.00 F
4	1		<b>*LH front lower arm</b> (WCP)	Bent	185.00 F	*185.00 F
5	1		<b>*LH front lower arm bush</b> (WCP)	Necessary	160.00 F	*160.00 F
6	1		<b>*LH front shock absorber</b> (WCP)	Bent	380.00 F	*380.00 F
7	1		<b>*LH front shock absorber top mounting</b> (WCP)	Serviceable	180.00 F	*- F
8	1		<b>*LH steering tie rod</b> (WCP)	Distorted	160.00 F	*160.00 F
9	1		<b>*LH steering tie rod end</b> (WCP)	Distorted	230.00 F	*230.00 F
10	1		<b>*LH drive shaft</b> (WCP)	Bent	2,100.00 F	*2,100.00 F
<b><u>Supplementary #1</u></b>						
11	1		<b>*Front Left stabilizer Link</b> (WCP)	Distorted	135.00 F	*135.00 F

F=Franchise part.

<b>Sub Total (\$\$)</b>	<b>5,330.00</b>	<b>5,150.00</b>
<b>+ Margin on L,N Items 5.00/5.00% (\$\$)</b>	266.50	257.50
<b>Total Parts (\$\$)</b>	<b>5,596.50</b>	<b>5,407.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	LH front tyre (Punctured) (70%)	220.00	154.00
<b>Sub Total (\$\$)</b>			<b>220.00</b>	<b>154.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	To remove and refit front bumper, and adjust body panel alignment	New	150.00	100.00
2	To remove and check LH front suspension system and replace damaged parts	New	240.00	200.00
3	To perform computerised wheel alignment	New	60.00	60.00
4	To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality	New	60.00	0.00
5	To perform computer diagnostic on drivetrain, ABS systems, parking system, headlamp systems, and clear fault codes	New	150.00	0.00
6	To spray paint affected front and inner damaged portion inclusive of preparatory works and material	New	200.00	200.00
<b>Gross Labour Cost (\$\$)</b>			<b>860.00</b>	<b>560.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >