

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006940/KVY3Q2**Date:** 19/08/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00045142201

Claimant Vehicle No : E559D **Insured Vehicle No :** GBC802M

Date of Loss: 15/06/2022 Nature of Claim: TP Claim No: SNM22D204335/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **E559D**

Make & Model: MERCEDES-BENZ E200 (R18), 2.0 (A) Engine No: 27492030564255

Reg. Date: 24/03/2016 (Man. Year: 2015) Chassis No: WDD2120342B299076

Colour: Metallic Grey Odometer: 80352 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40Z R18 Rear Tyre Size: 265/35Z R18

Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm

Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,838.70	2,604.78	7,233.92	73.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,650.00	565.00	2,085.00	78.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,488.70	3,169.78	9,318.92	74.62
Approved Total (Overridden) (\$\$)		2,500.00		
(\$\$)	12,488.70	2,500.00	9,988.70	79.98
+ GST 7.00/7.00% (\$\$)	874.21	175.00	699.21	79.98
Nett Amount (\$\$)	13,362.91	2,675.00	10,687.91	79.98

INSPECTION

Date of Assignment: 18/08/2022

Date Inspected: 27/07/2022 Inspected At: Yee Auto Pte Ltd (HQ)
160 SIN MING DRIVE #02-17 SIN MING
AUTOCITY
Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Aug 2022)
Parts:	143	MERCEDES-BENZ E200 (R18) 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for E559D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Repair	2,630.00 F	*- FL
2	1		*REAR BOOT LID CHROME MOULDING	Serviceable	380.00 F	*- FL
3	1		*REAR BOOT LID EMBLEM -7G-TRONIC	Not Necessary	120.00 F	*- FL
4	1		*REAR BOOT LID MERCEDES STAR	Not Necessary	120.00 F	*- FL
5	1		*REAR BOOT LID WEATHERSTRIP	Serviceable	265.00 F	*- FL
6	1		*REAR BUMPER	Buckled	2,080.00 F	*1,510.00 FL
7	1		*REAR BUMPER BOTTOM BRACKET -LH	Serviceable	85.00 F	*- FL
8	1		*REAR BUMPER BOTTOM BRACKET -RH	Serviceable	85.00 F	*- FL
9	1		*SET REAR BUMPER CLIPS	Necessary	80.00 F	*80.00 FL
10	1		*REAR BUMPER INNER GARNISH	Cracked	350.00 F	*255.20 FL
11	1		*REAR BUMPER INNER IMPACT BRACKET	Serviceable	62.00 F	*- FL
12	1		*REAR BUMPER LOWER GARNISH	Buckled	285.00 F	*285.00 FL
13	1		*REAR BUMPER LOWER GARNISH CHROME MOULDING	Serviceable	295.10 F	*- FL
14	1		*REAR BUMPER OUTER IMPACT BRACKET	Repair	62.00 F	*- FL
15	1		*REAR BUMPER REINFORCEMENT	Buckled	764.50 F	*764.00 FL
16	1		*REAR END PANEL	Repair	610.10 F	*- FL
17	1		*REAR END PANEL GARNISH	Serviceable	240.00 F	*- FL
18	1		*SET REAR REVERSE SENSOR WIRE	Serviceable	395.00 FS	*- FS
19	1		*REVERSE SENSOR CENTRE -LH	Serviceable	465.00 FS	*- FS
20	1		*REVERSE SENSOR CENTRE -RH	Serviceable	465.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,838.70	2,894.20
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	289.42
Total Parts (\$\$)	9,838.70	2,604.78

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS ,PANEL BEAT WHERE NECESSARY	New	1,000.00	300.00
2	TO PUTTY ,APPLY PRIMER & SPRAY -PAINT ON THE AFFECTED PORTION	New	1,000.00	250.00
3	TO APPLY RUST-PROOFING ON REPAIRED ,REPLACED PANEL	New	200.00	0.00
4	COMPUTER DIAGNOSTIC	New	350.00	0.00
5	TO CHECK WIRING FUNCTIONS	New	100.00	15.00
Gross Labour Cost (\$)			2,650.00	565.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >