

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22006941/AYA3Q2**Date:** 13/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070122064
Claimant Vehicle No :	SLX7049X	Insured Vehicle No :	SMU5626Y
Date of Loss:	15/07/2022	Nature of Claim:	TP
		Claim No:	4765029570SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX7049X	Engine No:	3A92UGX0803
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AJH002059
Reg. Date:	06/04/2018 (Man. Year: 2018)	Odometer:	69202 km
Colour:	Grey		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,521.96	5,783.14	2,738.82	32.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,760.00	2,710.00	2,050.00	43.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,281.96	8,493.14	4,788.82	36.06
Approved Total (Overridden) (S\$)		6,800.00		
(S\$)	13,281.96	6,800.00	6,481.96	48.80
+ GST 8.00/8.00% (S\$)	1,062.56	544.00	518.56	48.80
Nett Amount (S\$)	14,344.52	7,344.00	7,000.52	48.80
+ Loss of Use (9.0 x S\$60.00/day) (S\$)		540.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,891.45		
Global Sum Settlement (S\$)		7,800.00		

INSPECTION

Date of Assignment:	18/07/2022		
Date Inspected:	18/07/2022	Inspected At:	Mg Solution Pte Ltd - Kaki Bukit (HQ) 25 Kaki Bukit Road 4 #04-01 Singapore 41800
Estimated Period of Repair:	8.0 days		

Adjuster: ADRIAN LING**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Buckled	1,080.50 FL	*828.00 FL
2	1		*BOOTLID LOGO	Necessary	62.20 FL	*62.20 FL
3	1		*BOOTLID EMBLEM ATTRAGE	Necessary	63.00 FL	*63.00 FL
4	1		*BOOTLID EMBLEM MIVEC TECHNOLOGY	Necessary	63.00 FL	*63.00 FL
5	1		*BOOTLID EMBLEM C&C	Necessary	63.00 FL	*63.00 FL
6	1		*BOOTLID TOP LOCK	Damaged	228.40 FL	*228.40 FL
7	1		*BOOTLID CATCH	Not Necessary	103.00 FL	*- FL
8	2		*BOOTLID HINGE	Not Necessary	246.40 FL	*- FL
9	1		*BOOTLID KEYLESS ANTENNA	Cracked	233.20 FL	*96.00 FL
10	1		*BOOTLID BUZZER	Cracked	203.40 FL	*91.00 FL
11	1		*BOOTLID WEATHERSTRIP	Cut	230.00 FL	*230.00 FL
12	1		*REAR BUMPER	Distorted	822.30 FL	*765.00 FL
13	1		*REAR BUMPER SIDE RETAINER	N/S Damaged	145.00 FL	*35.00 FL
14	1		*REAR BUMPER AIR VENT	Not Necessary	89.00 FL	*- FL
15	1		*REAR BUMPER AIR VENT COVER	Cracked	133.00 FL	*94.00 FL
16	1		*REAR BUMPER REFLECTOR	Cracked	90.00 FL	*90.00 FL
17	2		*REAR BUMPER INNER SIDE BRACKET	Not Necessary	260.00 FL	*- FL
18	1		*TAILLAMP LH	Cracked	530.00 FL	*335.00 FL
19	1		*TAILLAMP PANEL LH	Dented	190.00 FL	*190.00 FL
20	1		*REAR FENDER LH	Buckled	890.00 FL	*890.00 FL
21	1		*REAR FENDER INNER TRIM LH	Not Necessary	420.00 FL	*- FL
22	1		*REAR WINDSCREEN MOULDING	Necessary	155.00 FL	*155.00 FL
23	1		*REAR END PANEL	Dented	670.00 FL	*482.00 FL
24	1		*REAR END PANEL TOP GARNISH	Deformed	174.00 FL	*174.00 FL
25	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
26	1		*SET REAR BUMPER CLIP	Necessary	22.00 FS	*22.00 FS
27	1		*REAR BUMPER LOWER LID ASSY	Cracked	1,500.00 FS	*950.00 FS
28	1		*SET TAILLAMP CLIP	Necessary	20.00 FS	*20.00 FS
29	1		*TAILLAMP PANEL SEALANT	Necessary	20.00 FS	*20.00 FS
30	1		*REAR WINDSCREEN SEALANT	Necessary	120.00 FS	*60.00 FS
31	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*10.00 FS
32	1		*REAR END PANEL INSULATION SEAL	Necessary	120.00 FS	*60.00 FS
33	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,236.40	6,276.60
- List Item Discount on L Items 10.00/10.00% (\$\$)	714.44	493.46
Total Parts (\$\$)	8,521.96	5,783.14

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	New	2,000.00	1,300.00
2	TO SPRAY PAINT AFFECTED AREA	New	2,000.00	1,100.00
3	TUFF COAT	New	150.00	80.00
4	WIRING CHECK	New	150.00	30.00
5	TO REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	120.00	50.00
6	TO REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	120.00	50.00
7	TO REMOVE AND REFIX REAR WINDSCREEN	New	100.00	100.00
8	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
Gross Labour Cost (\$\$)			4,760.00	2,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >