

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22006943/UCY3M4**Date:** 22/08/2022**REFERENCE**

|                              |                                               |                             |                      |
|------------------------------|-----------------------------------------------|-----------------------------|----------------------|
| Handling Insurer:            | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:                  | DMPCSNW00058292201   |
| <b>Claimant Vehicle No :</b> | GBF5694J                                      | <b>Insured Vehicle No :</b> | SMJ8261D             |
| Date of Loss:                | 15/07/2022                                    | Nature of Claim:            | TP                   |
|                              |                                               | Claim No:                   | SNM22D204958/C02/CSC |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>GBF5694J</b>                   | Engine No:  | K9KC400D055998    |
| Make & Model:               | NISSAN NV200, 1.5 MT (M)          | Chassis No: | VSKYBAM20Z0133595 |
| Reg. Date:                  | 14/12/2016 (Man. Year: 2016)      | Odometer:   | 137716 km         |
| Colour:                     | Silver                            |             |                   |
| Engine Capacity:            | 1461 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |                |                  |                |
|-------------------|----------------|------------------|----------------|
| Front Tyre Size:  | 175/70 R14     | Rear Tyre Size:  | 175/70 R14     |
| Front Left Side:  | GREEN-MAX 6 mm | Rear Left Side:  | GREEN-MAX 6 mm |
| Front Right Side: | GREEN-MAX 6 mm | Rear Right Side: | GREEN-MAX 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                     | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                     | 8,029.59          | 3,677.28          | 4,352.31          | 54.20         |
| Miscellaneous Items                       | 0.00              | 0.00              | 0.00              |               |
| Labour                                    | 3,740.00          | 1,970.00          | 1,770.00          | 47.33         |
| Paintwork Labour                          | 0.00              | 0.00              | 0.00              |               |
| Towing                                    | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>      | <b>11,769.59</b>  | <b>5,647.28</b>   | <b>6,122.31</b>   | <b>52.02</b>  |
| <b>Approved Total (Overridden) (\$\$)</b> |                   | <b>4,500.00</b>   |                   |               |
| <b>(\$\$)</b>                             | 11,769.59         | 4,500.00          | 7,269.59          | 61.77         |
| <b>+ GST 7.00/7.00% (\$\$)</b>            | 823.87            | 315.00            | 508.87            | 61.77         |
| <b>Nett Amount (\$\$)</b>                 | <b>12,593.46</b>  | <b>4,815.00</b>   | <b>7,778.46</b>   | <b>61.77</b>  |

**INSPECTION**

|                             |                          |                                                                                                                           |
|-----------------------------|--------------------------|---------------------------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 18/08/2022               |                                                                                                                           |
| Date Inspected:             | 18/07/2022 Inspected At: | Hock Wah Motor Workshop Pte Ltd (Bedok)<br>Blk 3011, Bedok Industrial Park E., #01-<br>2008/2010/2012<br>Singapore 489977 |
| Estimated Period of Repair: | 5.0 days                 |                                                                                                                           |

**Adjuster:** MARCUS CHUA**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                           |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------|
| <b>Part Source:</b>  | (Last Synchronised: 22 Aug 2022)                                                                                                                                             |                                                           |
| <b>Parts:</b>        | N/A                                                                                                                                                                          | NISSAN NV200 1.5 MT (M) (Model not available in database) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                         |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for GBF5694J)                                                                                                                                    |                                                           |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                           |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                           |

### Recommended Parts

| No. | Qty | Part No. | Particulars                        | Condition      | Repairer's  | Amount     |
|-----|-----|----------|------------------------------------|----------------|-------------|------------|
| 1   | 1   |          | *FRONT FENDER RH                   | Buckled        | 555.20 FL   | *548.20 FL |
| 2   | 1   |          | *FRONT FENDER INNER SHIELD RH      | Torn           | 124.50 FL   | *124.50 FL |
| 3   | 6   |          | *FRONT FENDER INNER SHIELD CLIP RH | Necessary      | 30.00 FL    | *30.00 FL  |
| 4   | 1   |          | *HEADLAMP ASSEMBLY RH              | Broken         | 444.50 FL   | *444.50 FL |
| 5   | 1   |          | *HEADLAMP ASSEMBLY LH              | Holder Cracked | 444.50 FL   | *444.50 FL |
| 6   | 1   |          | *SUPPORT PANEL                     | Repair         | 708.10 FL   | *- FL      |
| 7   | 1   |          | *HEADLAMP PANEL RH                 | Bent/Twisted   | 63.50 FL    | *63.50 FL  |
| 8   | 1   |          | *FRONT FENDER WHEELHOUSING RH      | Repair         | 486.50 FL   | *- FL      |
| 9   | 1   |          | *FRONT BUMPER                      | Distorted      | 655.20 FL   | *542.00 FL |
| 10  | 1   |          | *FRONT BUMPER TOP GARNISH RH       | Missing        | 368.50 FL   | *368.50 FL |
| 11  | 1   |          | *FRONT BUMPER RETAINER RH          | Cracked        | 25.70 FL    | *25.70 FL  |
| 12  | 1   |          | *FRONT BUMPER RETAINER LH          | Not Necessary  | 25.70 FL    | *- FL      |
| 13  | 1   |          | *FRONT BUMPER REINFORCEMENT        | Bent/Twisted   | 1,183.70 FL | *503.20 FL |
| 14  | 1   |          | *FRONT GRILLE                      | Cracked        | 356.10 FL   | *356.10 FL |
| 15  | 1   |          | *FRONT GRILLE EMBLEM               | Not Necessary  | 57.50 FL    | *- FL      |
| 16  | 4   |          | *FRONT GRILLE CLIP                 | Necessary      | 20.00 FL    | *20.00 FL  |
| 17  | 1   |          | *BONNET INNER LOCK                 | Serviceable    | 51.30 FL    | *- FL      |
| 18  | 1   |          | *FRONT BUMPER FOGLAMP RH           | Not Necessary  | 321.60 FL   | *- FL      |
| 19  | 1   |          | *FRONT BUMPER FOGLAMP BRACKET RH   | Not Necessary  | 96.30 FL    | *- FL      |
| 20  | 1   |          | *AIR CON CONDENSER                 | Not Necessary  | 661.20 FL   | *- FL      |
| 21  | 1   |          | *RADIATOR                          | Not Necessary  | 716.10 FL   | *- FL      |
| 22  | 1   |          | *FRONT WIPER TANK RH               | Deformed       | 261.40 FL   | *261.40 FL |
| 23  | 1   |          | *BONNET HINGE RH                   | Not Necessary  | 43.70 FL    | *- FL      |
| 24  | 1   |          | *BONNET HINGE LH                   | Not Necessary  | 43.70 FL    | *- FL      |
| 25  | 1   |          | *ENGINE MOUNTING TOP               | Not Necessary  | 154.20 FL   | *- FL      |
| 26  | 1   |          | *ENGINE MOUNTING BOTTOM            | Not Necessary  | 182.20 FL   | *- FL      |
| 27  | 1   |          | *ENGINE MOUNTING RH                | Torn           | 287.10 FL   | *287.10 FL |
| 28  | 1   |          | *ENGINE MOUNTING LH                | Not Necessary  | 287.10 FL   | *- FL      |
| 29  | 1   |          | *BONNET - REPAIR (NPA)             | Repair         | 0.00 FS     | *- FS      |
| 30  | 1   |          | *FRONT NUMBER PLATE}               | Scratched      | 30.00 FS    | *40.00 FS  |
| 31  | 1   |          | *FRONT NUMBER PLATE HOLDER}        | Scratched      | 30.00 FS    | *- FS      |
| 32  | 1   |          | *RADIATOR COOLANT                  | Necessary      | 180.00 FS   | *20.00 FS  |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                          |                 |                 |
|----------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$)</b>                                    | <b>8,895.10</b> | <b>4,079.20</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$)</b> | 865.51          | 401.92          |
| <b>Total Parts (\$)</b>                                  | <b>8,029.59</b> | <b>3,677.28</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                              | Lab.Type | Repairer's      | Amount          |
|---------------------------------|------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                          |          |                 |                 |
| 1                               | LABOUR TO REMOVE & REFIT NECESSARY PARTS | New      | 1,800.00        | 1,000.00        |
| 2                               | SPRAY PAINT ON THE AFFECTED AREAS        | New      | 1,200.00        | 800.00          |
| 3                               | ANTI-RUST COATING                        | New      | 150.00          | 50.00           |
| 4                               | WIRING                                   | New      | 80.00           | 20.00           |
| 5                               | TO SERVICE & TOP-UP AIR-CON GAS          | New      | 180.00          | 100.00          |
| 6                               | TWO WHEEL ALIGNMENT                      | New      | 80.00           | 0.00            |
| 7                               | TO REMOVE & REFIT UNDERCARRIAGE          | New      | 250.00          | 0.00            |
| <b>Gross Labour Cost (\$\$)</b> |                                          |          | <b>3,740.00</b> | <b>1,970.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >