

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22006947/UVY3E2

**Date:** 10/08/2022

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00076042100		
<b>Claimant Vehicle No :</b>	SMP5380G	<b>Insured Vehicle No :</b>	GBL1780M		
Date of Loss:	09/07/2022	Nature of Claim:	TP	Claim No:	SNM22D204989/C02/TANCHC

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMP5380G</b>	Engine No:	2NRX474521
Make & Model:	TOYOTA SIENTA, 1.5 CVT ELEGANCE (A)	Chassis No:	MHFZ28H3800064354
Reg. Date:	30/09/2019 (Man. Year: 2019)	Odometer:	115374 km
Colour:	Brown		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/50 R16	Rear Tyre Size:	195/50 R16
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,341.67	3,199.02	2,142.65	40.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,420.00	720.00	700.00	49.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,761.67</b>	<b>3,919.02</b>	<b>2,842.65</b>	<b>42.04</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,100.00</b>		
<b>(S\$)</b>	6,761.67	3,100.00	3,661.67	54.15
<b>+ GST 7.00/7.00% (S\$)</b>	473.32	217.00	256.32	54.15
<b>Nett Amount (S\$)</b>	<b>7,234.99</b>	<b>3,317.00</b>	<b>3,917.99</b>	<b>54.15</b>

### INSPECTION

Date of Assignment:	21/07/2022	
Date Inspected:	26/07/2022	Inspected At: Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93 Singapore 528840
Estimated Period of Repair:	3.0 days	

**Adjuster:** MARCUS CHUA

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Aug 2022)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 CVT ELEGANCE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP5380G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	653.20 FL	*486.10 FL
2	1		*FRONT BUMPER SIDE RETAINER	O/S Bent	96.20 FL	*48.10 FL
3	1		*O/S FRONT BUMPER GARNISH	Grazed	89.50 FL	*89.50 FL
4	1		*O/S FRONT FENDER	Dented / Bent	725.00 FL	*525.00 FL
5	1		*O/S FRONT FENDER INNER SHIELD	Not Necessary	185.00 FL	*- FL
6	1		*O/S HEADLAMP	Scratched	3,050.00 FL	*3,050.00 FL
7	1		*O/S FRONT RIM	Not Necessary	2,190.00 FL	*- FL
8	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
9	1		*SET O/S FRONT FENDER INNER SHIELD CLIP	Not Necessary	50.00 FS	*- FS
					Sub Total (\$\$)	7,088.90 4,248.70
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,747.23 1,049.68
					Total Parts (\$\$)	5,341.67 3,199.02

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK LIGHT AND WIRING	New	50.00	20.00
2	COMPUTERIZED WHEEL ALIGNMENT	New	120.00	0.00
3	TRANSFER TYRE AND BALANCING	New	50.00	0.00
4	LABOUR / PANEL BEATING	New	600.00	300.00
5	SPRAY PAINTING	New	600.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,420.00</b>	<b>720.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >