

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22006951/ACY3Q2**Date:** 17/10/2022**REFERENCE**

|                              |                                               |                             |                          |
|------------------------------|-----------------------------------------------|-----------------------------|--------------------------|
| Handling Insurer:            | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:                  | DMCVSNW00114782100       |
| <b>Claimant Vehicle No :</b> | SKM3373E                                      | <b>Insured Vehicle No :</b> | GBG6016E                 |
| Date of Loss:                | 20/07/2022                                    | Nature of Claim:            | TP                       |
|                              |                                               | Claim No:                   | SNM22D205037/C02/KHONGLH |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SKM3373E</b>                   | Engine No:  | R16B25511170      |
| Make & Model:               | HONDA CIVIC, 1.6 (A)              | Chassis No: | MRHFC5650KT001053 |
| Reg. Date:                  | 17/10/2019 (Man. Year: 2019)      | Odometer:   | 48803 km          |
| Colour:                     | Blue                              |             |                   |
| Engine Capacity:            | 1597 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |             |                  |             |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size:  | 215/55 R16  | Rear Tyre Size:  | 215/55 R16  |
| Front Left Side:  | Dunlop 6 mm | Rear Left Side:  | Dunlop 6 mm |
| Front Right Side: | Dunlop 6 mm | Rear Right Side: | Dunlop 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                     | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                     | 15,804.56         | 7,628.88          | 8,175.68          | 51.73         |
| Miscellaneous Items                       | 0.00              | 0.00              | 0.00              |               |
| Labour                                    | 7,650.00          | 4,150.00          | 3,500.00          | 45.75         |
| Paintwork Labour                          | 0.00              | 0.00              | 0.00              |               |
| Towing                                    | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>      | <b>23,454.56</b>  | <b>11,778.88</b>  | <b>11,675.68</b>  | <b>49.78</b>  |
| <b>Approved Total (Overridden) (\$\$)</b> |                   | <b>9,400.00</b>   |                   |               |
| <b>Nett Amount (\$\$)</b>                 | <b>23,454.56</b>  | <b>9,400.00</b>   | <b>14,054.56</b>  | <b>59.92</b>  |

**INSPECTION**

|                             |            |                                                                                                                       |
|-----------------------------|------------|-----------------------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 21/07/2022 |                                                                                                                       |
| Date Inspected:             | 20/07/2022 | Inspected At: HD Perfect Autowork Pte Ltd (HQ)<br>8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit<br>Singapore 415875 |
| Estimated Period of Repair: | 13.0 days  |                                                                                                                       |

**Adjuster:** ADRIAN LING**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                       |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 17 Oct 2022)         |
| <b>Parts:</b>        | 143                                                                                                                                                                          | HONDA CIVIC 1.6 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                     |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SKM3373E)                                                                                                                                    |                                                       |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                       |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                       |

### Recommended Parts

| No. | Qty | Part No. | Particulars                         | Condition            | Repairer's  | Amount     |
|-----|-----|----------|-------------------------------------|----------------------|-------------|------------|
| 1   | 1   |          | *REAR BUMPER                        | Distorted            | 617.70 FL   | *617.70 FL |
| 2   | 1   |          | *REAR BUMPER DIFFUSER (CENTER)      | Distorted            | 452.00 FL   | *365.00 FL |
| 3   | 1   |          | *REAR BUMPER DIFFUSER CHROME        | Distorted            | 283.40 FL   | *283.40 FL |
| 4   | 2   |          | *REAR BUMPER REFLECTOR              | Not Necessary        | 172.00 FL   | *- FL      |
| 5   | 2   |          | *REAR BUMPER REFLECTOR GARNISH      | Cut                  | 39.60 FL    | *39.60 FL  |
| 6   | 2   |          | *REAR BUMPER SIDE RETAINER          | Necessary            | 34.40 FL    | *34.40 FL  |
| 7   | 1   |          | *REAR BUMPER REINFORCEMENT          | Distorted            | 260.40 FL   | *260.40 FL |
| 8   | 2   |          | *REAR BUMPER CORNER RETAINER        | Cracked              | 39.60 FL    | *39.60 FL  |
| 9   | 4   |          | *REAR REVERSE SENSOR                | Damaged (3 PCS ONLY) | 621.60 FL   | *466.20 FL |
| 10  | 4   |          | *REAR REVERSE SENSOR HOLDER         | Necessary            | 188.80 FL   | *188.80 FL |
| 11  | 1   |          | *REAR REVERSE SENSOR WIRE HARNESS   | Snapped              | 243.60 FL   | *243.60 FL |
| 12  | 1   |          | *REVERSE CAMERA                     | Damaged              | 788.96 FS   | *400.00 FS |
| 13  | 2   |          | *TAILLAMP                           | Cracked              | 596.80 FL   | *596.80 FL |
| 14  | 2   |          | *TAILLAMP PANEL                     | Buckled              | 158.60 FL   | *158.60 FL |
| 15  | 1   |          | *REAR FENDER                        | N/S Buckled          | 1,625.40 FL | *812.70 FL |
| 16  | 2   |          | *REAR FENDER COWLING                | Not Necessary        | 178.80 FL   | *- FL      |
| 17  | 2   |          | *REAR FENDER INNER TRIM             | Torn                 | 311.40 FL   | *311.40 FL |
| 18  | 1   |          | *REAR FENDER INNER SUPPORT PANEL    | N/S Buckled          | 792.60 FL   | *396.30 FL |
| 19  | 1   |          | *REAR FENDER AIR VENT LH            | Not Necessary        | 19.20 FL    | *- FL      |
| 20  | 2   |          | *REAR WHEEL HOUSE PANEL             | Repair               | 1,728.00 FL | *- FL      |
| 21  | 1   |          | *REAR QUARTER GLASS C/W MOULDING RH | Necessary            | 399.70 FL   | *58.30 FL  |
| 22  | 1   |          | *REAR WINDSCREEN MOULDING (LOWER)   | Necessary            | 196.40 FL   | *196.40 FL |
| 23  | 1   |          | *REAR SPEAKER PANEL                 | Not Necessary        | 924.00 FL   | *- FL      |
| 24  | 1   |          | *BOOTLID                            | Distorted            | 554.90 FL   | *554.90 FL |
| 25  | 1   |          | *BOOTLID CENTER GARNISH             | Cracked              | 210.90 FL   | *210.90 FL |
| 26  | 2   |          | *BOOTLID INNER STOPPER              | Not Necessary        | 37.80 FL    | *- FL      |
| 27  | 1   |          | *BOOTLID INSULATOR                  | Deformed             | 52.40 FL    | *52.40 FL  |
| 28  | 1   |          | *BOOTLID LOGO                       | Necessary            | 95.40 FL    | *95.40 FL  |
| 29  | 1   |          | *BOOTLID EMBLEM CIVIC               | Necessary            | 83.70 FL    | *83.70 FL  |
| 30  | 1   |          | *BOOTLID EMBLEM I-VTEC              | Necessary            | 86.50 FL    | *86.50 FL  |
| 31  | 2   |          | *BOOTLID HINGE                      | Bent                 | 117.80 FL   | *117.80 FL |
| 32  | 2   |          | *BOOTLID HINGE COVER GARNISH        | Deformed             | 48.60 FL    | *48.60 FL  |
| 33  | 1   |          | *BOOTLID TOP LOCK                   | Damaged              | 81.20 FL    | *81.20 FL  |
| 34  | 1   |          | *BOOTLID LOWER LOCK                 | Not Necessary        | 16.90 FL    | *- FL      |
| 35  | 1   |          | *BOOTLID WEATHERSTRIP               | Cut                  | 70.20 FL    | *70.20 FL  |
| 36  | 1   |          | *BOOTLID DETECTOR                   | Cracked              | 58.10 FL    | *58.10 FL  |
| 37  | 1   |          | *BOOTLID DETECTOR WIRE HARNESS      | Not Necessary        | 286.40 FL   | *- FL      |
| 38  | 1   |          | *BOOTLID BUZZER                     | Cracked              | 80.40 FL    | *80.40 FL  |
| 39  | 1   |          | *BOOTLID OUTER SWITCH BUTTON        | Not Necessary        | 287.10 FL   | *- FL      |
| 40  | 1   |          | *REAR END PANEL                     | Distorted            | 314.70 FL   | *314.70 FL |
| 41  | 1   |          | *REAR END PANEL TOP GARNISH         | Deformed             | 60.80 FL    | *60.80 FL  |
| 42  | 1   |          | *REAR FLOOR PANEL                   | Buckled              | 975.00 FL   | *975.00 FL |
| 43  | 1   |          | *REAR FLOOR SIDE PANEL              | N/S Distorted        | 586.00 FL   | *293.00 FL |
| 44  | 1   |          | *REAR FLOOR PANEL TOP BOARD         | Torn                 | 95.80 FL    | *95.80 FL  |
| 45  | 1   |          | *REAR CHASSIS MEMBER LH             | Repair               | 734.90 FL   | *- FL      |
| 46  | 1   |          | *REAR NUMBER PLATE                  | Bent                 | 80.00 FS    | *60.00 FS  |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                              | Condition     | Repairer's | Amount     |
|-----|-----|----------|------------------------------------------|---------------|------------|------------|
| 47  | 1   |          | *SET REAR BUMPER CLIP                    | Necessary     | 80.00 FS   | *30.00 FS  |
| 48  | 1   |          | *SET TAIL LAMP CLIP                      | Necessary     | 60.00 FS   | *20.00 FS  |
| 49  | 2   |          | *TAILLAMP PANEL SEALANT                  | Necessary     | 120.00 FS  | *40.00 FS  |
| 50  | 1   |          | *SET BOOTLID INSULATOR CLIP              | Necessary     | 80.00 FS   | *20.00 FS  |
| 51  | 1   |          | *SET BOOTLID HINGE COVER CLIP            | Necessary     | 60.00 FS   | *20.00 FS  |
| 52  | 1   |          | *SET BOOTLID CENTER GARNISH CLIP         | Necessary     | 60.00 FS   | *20.00 FS  |
| 53  | 2   |          | *REAR FENDER SEALANT                     | Not Necessary | 300.00 FS  | *- FS      |
| 54  | 1   |          | *SET REAR FENDER COWLING CLIP            | Not Necessary | 80.00 FS   | *- FS      |
| 55  | 1   |          | *SET REAR FENDER INNER TRIM CLIPS        | Necessary     | 80.00 FS   | *60.00 FS  |
| 56  | 2   |          | *REAR FENDER INNER SUPPORT PANEL SEALANT | Not Necessary | 300.00 FS  | *- FS      |
| 57  | 2   |          | *REAR FENDER QUARTER GLASS SEALANT       | Not Necessary | 160.00 FS  | *- FS      |
| 58  | 2   |          | *REAR FENDER QUARTER GLASS INNER SHIELD  | Not Necessary | 120.00 FS  | *- FS      |
| 59  | 2   |          | *REAR WHEEL HOUSE PANEL SEALANT          | Not Necessary | 300.00 FS  | *- FS      |
| 60  | 1   |          | *REAR SPEAKER PANEL SEALANT              | Not Necessary | 150.00 FS  | *- FS      |
| 61  | 1   |          | *REAR WINDSCREEN SEALANT                 | Not Necessary | 80.00 FS   | *- FS      |
| 62  | 1   |          | *REAR WINDSCREEN INNER SEAL              | Not Necessary | 60.00 FS   | *- FS      |
| 63  | 1   |          | *REAR QUARTER GLASS SOLAR FILM LH        | Not Necessary | 250.00 FS  | *- FS      |
| 64  | 1   |          | *SET REAR END PANEL TOP GARNISH CLIPS    | Necessary     | 60.00 FS   | *20.00 FS  |
| 65  | 1   |          | *REAR END PANEL INSULATION SEAL          | Necessary     | 150.00 FS  | *60.00 FS  |
| 66  | 1   |          | *REAR FLOOR PANEL INSULATION SEAL        | Necessary     | 350.00 FS  | *200.00 FS |
| 67  | 1   |          | *BRAKE OIL                               | Not Necessary | 180.00 FS  | *- FS      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                          |                  |                 |
|----------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$)</b>                                    | <b>18,768.46</b> | <b>9,298.60</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$)</b> | 2,963.90         | 1,669.72        |
| <b>Total Parts (\$)</b>                                  | <b>15,804.56</b> | <b>7,628.88</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                    | Lab.Type | Repairer's      | Amount          |
|---------------------------------|------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                                                |          |                 |                 |
| 1                               | PANEL BEATING ,REMOVAL AND REPLACING PARTS                                                     | New      | 3,200.00        | 1,800.00        |
| 2                               | TO SPRAY PAINT AFFECTED AREA                                                                   | New      | 2,000.00        | 1,500.00        |
| 3                               | TUFF COAT                                                                                      | New      | 250.00          | 120.00          |
| 4                               | WIRING CHECK                                                                                   | New      | 180.00          | 30.00           |
| 5                               | REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR                 | New      | 250.00          | 180.00          |
| 6                               | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING                                           | New      | 80.00           | 50.00           |
| 7                               | REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING                                           | New      | 80.00           | 50.00           |
| 8                               | CONDUCT WATER LEAKAGE TEST                                                                     | New      | 100.00          | 0.00            |
| 9                               | REMOVE AND REFIX REAR FENDER GLASS                                                             | New      | 200.00          | 60.00           |
| 10                              | REMOVE AND REFIX REAR WINDSCREEN GLASS                                                         | New      | 120.00          | 120.00          |
| 11                              | REMOVE AND REFIX REAR SPEAKER PANEL AND RESET AUDIO SYSTEM                                     | New      | 150.00          | 0.00            |
| 12                              | TRANSFER BOOTLID MECHANISM                                                                     | New      | 80.00           | 60.00           |
| 13                              | REALIGNMENT REAR CHASSIS MEMBER                                                                | New      | 250.00          | 180.00          |
| 14                              | REMOVE AND REFIX REAR UNDER CARRIAGE                                                           | New      | 450.00          | 0.00            |
| 15                              | CONDUCT WATER LEAKAGE TEST                                                                     | New      | 80.00           | 0.00            |
| 16                              | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC | New      | 180.00          | 0.00            |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                |          | <b>7,650.00</b> | <b>4,150.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >