

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS3/SMO22006953/Kcy3e2
	50 RAFFLES PLAC SINGAPORE LAND	E #03-03 O TOWERSINGAPORE 048623		Date:	17/08/2022
				Code:	SMO
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	GBD 2485B	Veh. Inspected		GBD 4912Y
	Policy No.	D21MTPCVE002126	Coverage (\$)		0.00
	Claim No.	CMTD2202475/THE	Excess (\$)		0.00
	Assign From	GRACE TEO	Assign Date		21/07/2022
2.	Vehicle Particulars & Condition				
	Make & Model	NISSAN NV350 (M)	c.c		2488
	Engine No.	HIDDEN	Year of Reg.		2014
	Chassis No.	JN1MC2E26Z0003444	Colour		METALLIC GREY
	Odometer	162242 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195 R15X8	BRIDGESTONE		2 mm
	L/H Front Tyre	195 R15X8	BRIDGESTONE		2 mm
	R/H Rear Tyre	195 R15X8	BRIDGESTONE		9 mm
	L/H Rear Tyre	195 R15X8	BRIDGESTONE		9 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.				
5.	General Information				
	Accident Date	14/07/2022	Inspect Date / 7	Time	26/07/2022 ( 10:55 AM )
	Survey held at GUAN AUTO SERVICE				
	BLK12 #01-59 SIN MING INDUSTRIAL ESTATE SECTOR B SINGAPORE 575656				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/SMO22006953/Kcy3e2

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

**REGD Auto Consultant-SAE, Licensed Appraiser**