8/16/22, 10:49 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22006959/UQY3Q2

16/08/2022 Date:

REFERENCE

No:

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMPCSNA00160742201

TP

Claimant Vehicle

SKV7765J

Insured Vehicle No:

SKB9258Z

Date of Loss: 19/07/2022 Nature of Claim:

Claim

SNM22D205060/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

SKV7765J Reg No:

NISSAN SYLPHY, 1.6 (A) HR16973691B Make & Model: Engine No:

Reg. Date: 30/09/2015 (Man. Year: 2015) Chassis No: MNTBBAB17Z0024715

Colour: Black Odometer: 174519 km

Engine Capacity: 1598 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16 Front Left Side: Pirelli 7 mm Rear Left Side: Pirelli 7 mm Front Right Side: Pirelli 7 mm Rear Right Side: Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,043.68	811.44	232.24	22.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,928.00	633.00	1,295.00	67.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,971.68	1,444.44	1,527.24	51.39
+ GST 7.00/7.00% (S\$)	208.02	101.11	106.91	51.39
Nett Amount (S\$)	3,179.70	1,545.55	1,634.15	51.39

INSPECTION

Date of Assignment: 21/07/2022

> Autolution Industrial Pte Ltd (Ubi) 25/07/2022 Inspected At: 19 Ubi Road 4

Date Inspected:

Singapore 408623

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Aug 2022)

Parts: 143 NISSAN SYLPHY 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKV7765J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*RH STAY RR BUMPER	Not Necessary	53.50 FN	*- FN
1		*LH STAY RR BUMPER	Not Necessary	50.50 FN	*- FN
1		*LH SIDE BRACKET RR BUMPER	Not Necessary	41.10 FN	*- FN
1		*RH SIDE BRACKET RR BUMPER	Not Necessary	41.10 FN	*- FN
1		*ENERGY ABSORBER REAR BUMPER	Not Necessary	41.60 FN	*- FN
1		*REAR BUMPER	Deformed	701.80 FN	*701.80 FN
1		*SUNDRIES	Not Necessary	50.00 FS	*-FS
1		*SET SENSOR -REVERSE	Shorted	250.00 FS	*250.00 FS
nchise	part. S=SpcN	ett. N=NettItemDisc.	_		
			Sub Total (S\$)	1,229.60	951.80
	- Nett Item Discount on N Items 20.00/20.00% (S\$)		185.92	140.36	
			Total Parts (S\$)	1,043.68	811.44
	1 1 1 1 1 1 1	1 1 1 1 1	1 *RH STAY RR BUMPER 1 *LH STAY RR BUMPER 1 *LH SIDE BRACKET RR BUMPER 1 *RH SIDE BRACKET RR BUMPER 1 *ENERGY ABSORBER REAR BUMPER 1 *REAR BUMPER 1 *SUNDRIES 1 *SET SENSOR -REVERSE nchise part. S=SpcNett. N=NettlitemDisc.	1 *RH STAY RR BUMPER Not Necessary 1 *LH STAY RR BUMPER Not Necessary 1 *LH SIDE BRACKET RR BUMPER Not Necessary 1 *RH SIDE BRACKET RR BUMPER Not Necessary 1 *ENERGY ABSORBER REAR BUMPER Not Necessary 1 *ENERGY ABSORBER REAR BUMPER Not Necessary 1 *REAR BUMPER Deformed 1 *SUNDRIES Not Necessary 1 *SET SENSOR -REVERSE Shorted nchise part. S=SpcNett. N=NettItemDisc. Sub Total (S\$) - Nett Item Discount on N Items 20.00/20.00% (S\$)	1 *RH STAY RR BUMPER Not Necessary 53.50 FN 1 *LH STAY RR BUMPER Not Necessary 50.50 FN 1 *LH SIDE BRACKET RR BUMPER Not Necessary 41.10 FN 1 *RH SIDE BRACKET RR BUMPER Not Necessary 41.10 FN 1 *ENERGY ABSORBER REAR BUMPER Not Necessary 41.60 FN 1 *REAR BUMPER Deformed 701.80 FN 1 *SUNDRIES Not Necessary 50.00 FS 1 *SET SENSOR -REVERSE Shorted 250.00 FS nchise part. S=SpcNett. N=NettItemDisc. Sub Total (S\$) 1,229.60 - Nett Item Discount on N Items 20.00/20.00% (S\$) 185.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	LABOR CHARGES TO REPAIR REAR ENE PANEL AND RENEW REAR BUMPER	New	840.00	280.00
2	CHARGES TO SPRAY PAINTING & REAR BUMPER	New	750.00	250.00
3	REMOVE AND INSTALL BOTH RR COMB LAMP AND CHECK REAR WIRING SYSTEM	New	48.00	48.00
4	RENEW REVERSE SENSOR	New	110.00	55.00
5	COMPUTER CHECK DIAGNOSIS	New	180.00	0.00
	Gross Labour	Cost (S\$)	1,928.00	633.00
	Report was unsubmitted during this	orint-out		

< END OF ESTIMATES >