

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006960/ACY3Q2**Date:** 21/09/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00039752202	
Claimant Vehicle No :	SLH4554H	Insured Vehicle No :	GBB6282D	
Date of Loss:	19/07/2022	Nature of Claim:	TP	Claim No: SNM22D205061/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH4554H		Engine No:	2NR8537344
Make & Model:	TOYOTA SIENTA, 1.5 X CVT (A)		Chassis No:	NSP1707009231
Reg. Date:	03/11/2016 (Man. Year: 2015)		Odometer:	291477 km
Colour:	Black			
Engine Capacity:	1496 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,230.95	4,609.75	3,621.20	43.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,530.00	1,980.00	1,550.00	43.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,760.95	6,589.75	5,171.20	43.97
Approved Total (Overridden) (\$\$)		5,200.00		
(\$\$)	11,760.95	5,200.00	6,560.95	55.79
+ GST 7.00/7.00% (\$\$)	823.27	364.00	459.27	55.79
Nett Amount (\$\$)	12,584.22	5,564.00	7,020.22	55.79

INSPECTION

Date of Assignment:	22/07/2022	
Date Inspected:	21/07/2022 Inspected At:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Sep 2022)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH4554H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	750.00 FL	*678.00 FL
2	1		*REAR BUMPER CENTER PROTECTOR GARNISH	Deformed	207.00 FL	*207.00 FL
3	2		*REAR BUMPER REFLECTOR L/R	Not Necessary	170.00 FL	*- FL
4	2		*REAR BUMPER SIDE END PANEL COVER L/R	Not Necessary	162.00 FL	*- FL
5	2		*REAR BUMPER SIDE PROTECTOR GARNISH L/R	Deformed	302.00 FL	*302.00 FL
6	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	180.00 FL	*- FL
7	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	25.00 FL	*- FL
8	1		*REAR END INNER PANEL	Repair	696.30 FL	*- FL
9	1		*REAR END OUTER PANEL	Dented	433.60 FL	*433.60 FL
10	1		*REAR END PANEL KEY ANTENNA SENSOR	Cracked	127.00 FL	*127.00 FL
11	1		*REAR END PANEL TOP GARNISH	Deformed	207.00 FL	*207.00 FL
12	1		*REAR FENDER INNER TRIM BOARD L/R	O/S Cracked	1,418.00 FL	*709.00 FL
13	1		*REAR LUGGAGE COMPARTMENT TRAY	Deformed	423.10 FL	*423.10 FL
14	1		*REAR LUGGAGE COMPARTMENT TRAY TOP COVER	Deformed	255.60 FL	*255.60 FL
15	1		*REAR TAILGATE	Dented	1,131.90 FL	*1,131.90 FL
16	1		*REAR TAILGATE LOGO EMBLEM	Necessary	79.40 FL	*79.40 FL
17	1		*REAR BUMPER INNER PULL HANDLE	Not Necessary	38.00 FL	*- FL
18	2		*REAR BUMPER INNER RUBBER GUIDE STOPPER L/R	Not Necessary	38.00 FL	*- FL
19	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	208.00 FL	*- FL
20	1		*REAR TAILGATE MECHANISM LOCK	Damaged	265.00 FL	*265.00 FL
21	2		*REAR TAILGATE NUMBER PLATE LAMP L/R	Not Necessary	136.00 FL	*- FL
22	1		*REAR TAILGATE OUTER GARNISH	Cut	229.40 FL	*229.40 FL
23	1		*REAR TAILGATE OUTER OPENER SENSOR	Not Necessary	179.10 FL	*- FL
24	2		*REAR TAILGATE REFLECTOR L/R	Not Necessary	562.00 FL	*- FL
25	1		*REAR TAILGATE WEATHERSTRIP	Cut	385.00 FL	*385.00 FL
26	2		*REAR TAILGATE WINDSCREEN MOULDING L/R	Necessary	90.00 FL	*90.00 FL
27	2		*REAR TAILGATE WINDSCREEN SEAL (TOP & LOWER)	Necessary	90.00 FL	*90.00 FL
28	2		*REAR TAILLAMP LOWER BRACKET L/R	Not Necessary	166.20 FL	*- FL
29	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
30	1		*REAR BUMPER REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
31	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
32	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
33	2		*SET REAR FENDER INNER SHIELD CLIPS L/R	Not Necessary	80.00 FS	*- FS
34	2		*SET REAR FENDER INNER TRIM BOARD CLIPS L/R	Necessary	100.00 FS	*30.00 FS
35	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	80.00 FS	*- FS
36	1		*REAR TAILGATE NUMBER PLATE	Not Necessary	25.00 FS	*- FS
37	1		*REAR TAILGATE NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
38	1		*SET REAR TAILGATE OUTER GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
39	1		*REAR TAILGATE REVERSE CAMERA	Not Necessary	600.00 FS	*- FS
40	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
41	2		*SET REAR TAILLAMP CLIPS L/R	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

	Sub Total (\$)	10,469.60	6,013.00
- List Item Discount on L Items 25.00/25.00% (\$)		2,238.65	1,403.25

Total Parts (S\$)	8,230.95	4,609.75
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	60.00	60.00
2	TO REMOVE ,REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
3	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	140.00	60.00
4	TO RE-SPRAY PAINTING ON THE REAR BOOTLID ,REAR END PANEL,REAR FENDER (L/R) ,SPARE TYRE PANEL AND REAR BUMPER	New	1,500.00	800.00
5	TO REMOVE AND REINSTALL EXHAUST PIPE	New	100.00	0.00
6	TO PROVIDE LABOUR WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENT AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,400.00	800.00
7	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	60.00
8	TO REMOVE ,REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION	New	80.00	80.00
Gross Labour Cost (\$\$)			3,530.00	1,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >