

ASS. REC. BY:

REF:

A/G/22009691/Kc

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S1TB 161A

Yr Regn:

12, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

c.c

1798

Colour

M. Brown

A/C:

Insured / Std / NI / NA

Sp. Reading

102301

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU703080731

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / RIm or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

21/7/22

Rear

R/Bal.

8

mm

L/Bal.

8

mm

D.O.I.

22/7/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/8 @ 5205.87 Cash

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$



Case Details

Not Authorized
Repair B & paint

Case Reference Number : TAX/07/22/2063

Type of Repair : Accident Repair

Vehicle Registration Number : SHB161M

Company Type : Strides Taxi Pte Ltd

Estimation ID : EST-18874-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd

Accident Date and Time : 21/07/2022 03:45 AM

Vehicle Age(In Months) : -

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Surveyor Approval

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/Replace	Surveyor Approval			Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)		Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			COVER, FR BUMPER	1	521.00	521.00	25.00	390.75	Replace	0	0	Not Give	
Standard	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	0	0	Not Give	
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.50	45.00	25.00	33.75	Replace	0	0	Not Give	
Standard	Main			FENDER SUB-ASSY, FR , LH	1	977.80	977.80	25.00	733.35	Replace	0	0	Not Give	
Standard	Main			EMBLEM, SIDE PANEL (HYBRID)	1	54.60	54.60	25.00	40.95	Replace	0	0	Not Give	
Standard	Main			LINER, FR FENDER, LH	1	210.30	210.30	25.00	157.73	Replace	0	0	Not Give	
Standard	Main			COVER, OUTER MIRROR, LH	1	108.60	108.60	25.00	81.45	Replace	1	0	Repair	
Standard	Main			MIRROR ASSY, OUTER REAR VIEW , LH	1	1,339.30	1,339.30	10.00	1,205.37	Replace	1	1,205.	Replace	Not Give
Standard	Main			MOULDING ASSY, BODY ROCKER PANEL , LH	1	594.80	594.80	25.00	446.10	Replace	0	0	Not Give	
Standard	Main			PILLAR, FRONT BODY, LH	1	350.00	350.00	25.00	262.50	Replace	0	0	Not Give	
Standard	Main			BRACKET, FRONT FENDER MOUNTING , RH & LH	1	9.50	9.50	25.00	7.13	Replace	0	0	Not Give	
Standard	Main			PILLAR, CENTER BODY, OUTER LH	1	323.10	323.10	25.00	242.33	Replace	0	0	Not Give	
Standard	Main			PANEL SUB-ASSY, FRONT DOOR LH	1	1,300.70	1,300.70	25.00	975.53	Replace	1	975.53	Replace	Not Give

Total Spare Part Cost 10,995.20

Surveyor Total 3,505.03

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 10,995.20

Final Sur Total 3,505.03

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			CHECK ASSY, FRONT DOOR	1	183.80	183.80	25.00	137.85	Replace	0	0	Not Give	
Standard	Main			WEATHERSTRIP, FRONT DOOR LH	1	231.30	231.30	25.00	173.48	Replace	0	0	Not Give	
Standard	Main			MOULDING, FRONT DOOR WINDOW FRAME , REAR LH	1	56.50	56.50	25.00	42.38	Replace	0	0	Not Give	
Standard	Main			COVER, FRONT DOOR SERVICE HOLE , LH	1	23.90	23.90	25.00	17.92	Replace	0	0	Not Give	
Standard	Main			PROTECTOR, FRONT DOOR PANEL , LH	1	50.70	50.70	25.00	38.03	Replace	0	0	Not Give	
Standard	Main			SEAL, FRONT DOOR VENT, LH	1	17.30	17.30	25.00	12.98	Replace	0	0	Not Give	
Standard	Main			COVER, FRONT DOOR SERVICE HOLE , LH	1	188.10	188.10	25.00	141.08	Replace	0	0	Not Give	
Standard	Main			WEATHERSTRIP, FRONT DOOR FIX WINDOW , LH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give	
Standard	Main			FRAME SUB-ASSY, FRONT DOOR , FRONT LOWER LH	1	144.60	144.60	25.00	108.45	Replace	0	0	Not Give	
Standard	Main			RUN, FRONT DOOR GLASS , LH	1	153.60	153.60	25.00	115.20	Replace	0	0	Not Give	
Standard	Main			FRAME SUB-ASSY, FRONT DOOR , REAR LOWER LH	1	88.50	88.50	25.00	66.38	Replace	0	0	Not Give	
Standard	Main			GARNISH, DOOR FRAME, LH	1	13.10	13.10	25.00	9.83	Replace	0	0	Not Give	
Standard	Main			WEATHERSTRIP, FR LH	1	138.00	138.00	25.00	103.50	Replace	0	0	Not Give	
Standard	Main			LOCK ASSY, FRONT DOOR LH	1	561.90	561.90	10.00	505.71	Replace	0	0	Check	
Standard	Main			DOOR LOCK STRIKER	1	39.30	39.30	25.00	29.47	Replace	0	0	Not Give	
Standard	Main			DOOR OUTER HANDLE FRONT , LH	1	390.60	390.60	25.00	292.95	Replace	1	292.95	Replace	Not
Standard	Main			DOOR FRONT CABLE ASSY, LOCK REMOTE CONTROL , RH & LH	1	49.90	49.90	25.00	37.43	Replace	0	0	Not Give	
Standard	Main			HINGE ASSY, FRONT DOOR , UPPER LH	1	97.50	97.50	25.00	73.13	Replace	0	0	Not Give	

Total Spare Part Cost 10,995.20

Surveyor Total 3,505.03

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 10,995.20

Final Sur Total 3,505.03

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			HINGE ASSY, FRONT DOOR , LOWER LH	1	110.60	110.60	25.00	82.95	Replace	0	0	Not Give	
Standard	Main			DOOR FRONT WINDOW REGULATOR SUB-ASSY, LH	1	238.30	238.30	25.00	178.73	Replace	0	0	Not Give	
Standard	Main			DOOR FRONT MOTOR ASSY, POWER WINDOW REGULATOR , LH	1	926.00	926.00	10.00	833.40	Replace	0	0	Not Give	
Standard	Main			STICKER STRIDES TAXI (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	Ma
Standard	Main			WIRE, FRONT DOOR, LH	1	474.80	474.80	10.00	427.32	Replace	0	0	Not Give	
Standard	Main			PANEL SUB-ASSY, REAR DOOR , LH	1	1,294.90	1,294.90	25.00	971.18	Replace	1	971.18	Replace	Bt
Standard	Main			MEMBER SUB-ASSY, RAIL ROOT SIDE REAR LH	1	288.50	288.50	25.00	216.38	Replace	0	0	Not Give	
Standard	Main			CHECK ASSY, REAR DOOR	1	183.80	183.80	25.00	137.85	Replace	0	0	Not Give	
Standard	Main			WEATHERSTRIP, REAR DOOR LH	1	180.10	180.10	25.00	135.08	Replace	0	0	Not Give	
Standard	Main			HINGE ASSY, REAR DOOR , UPPER LH	1	98.90	98.90	25.00	74.18	Replace	0	0	Not Give	
Standard	Main			HINGE ASSY, REAR DOOR , LOWER LH	1	87.10	87.10	25.00	65.32	Replace	0	0	Not Give	
Standard	Main			DOOR REAR MOTOR ASSY, POWER WINDOW REGULATOR , LH	1	926.00	926.00	10.00	833.40	Replace	0	0	Not Give	
Standard	Main			DOOR REAR WINDOW REGULATOR SUB-ASSY, LH	1	206.70	206.70	25.00	155.02	Replace	0	0	Not Give	
Standard	Main			WIRE, REAR DOOR, LH	1	247.40	247.40	10.00	222.66	Replace	0	0	Not Give	
Total Spare Part Cost									10,995.20		Surveyor Total		3,505.03	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)		0	
Final Spare Part Cost									10,995.20		Final Sur Total		3,505.03	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LH PORTION	1,014.00	400	
Total:			1,014.00	400.00	

Spray Cost Detail


S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	378.00	0	
2	Main	TO RESPRAY FRONT FENDER LH	378.00	0	
3	Main	TO RESPRAY FRONT DOOR LH	378.00	200	
4	Main	TO RESPRAY VIEW MIRROR	180.00	50	
5	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	0	
6	Main	TO RESPRAY CENTRE PILLAR LH	180.00	0	
7	Main	TO RESRAY REAR DOOR LH	378.00	200	
Total:			2,052.00	450.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	20	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	60	
4	Main	TO TRANSFER DOOR MECHANISM	240.00	120	
5	Main	TO REPLACE SUNDRY PARTS	100.00	0	
Total:			720.00	200.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	10,995.20	3,505.03
Total Labour Cost	1,014.00	400.00
Total Spray Painting	2,052.00	450.00
Other	720.00	200.00
Overall Total	14,781.20	4,555.03
Lump Sum Repair Option	☐	☐
Lump Sum Total	0.00	4,555.03

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Surveyor Approved Amount		4,555.03
No of Repair Days*	6	4
Remarks	-	PRAT BY PART REPAIR / BEFORE PAINT PHOTO / FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) HP : 9691 0663 / Email
Surveyor Name		Kenneth Kong (LKK)
Signature		
		Save Clear
Survey Date	22/07/2022	