11/4/22, 1:05 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd. Our File No: CS/MSG22006962/TVY3M4

4 Shenton Way, #21-01 SGX Centre 2 Date: 04/11/2022 Singapore 068807

REFERENCE

Insured/Claimant: HOCK WAH CONSTRUCTION & ENTERPRISE PTE LTD Policy No: 1001481237

Date of Loss: 08/07/2022 Nature of Claim: OD Claim No: 278618

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YK3288M

Make & Model: ISUZU NPR75UH5A, 5.2 D (M) 4HK1981726 Engine No:

Reg. Date: 23/10/2013 (Man. Year: 2012) JAANPR75HC7103585 Chassis No:

Colour: White Odometer: 141048 km

Engine Capacity: 5193 cc S\$20,000.00 Market Value/New Car Price:

Sum Insured (S\$): 0.00

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/75 R17 Rear Tyre Size: 215/75 R17 (D/D) Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 8/8 mm Front Right Side: Rear Right Side: Bridgestone 8/8 mm Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,753.40	1,193.50	559.90	31.93
Miscellaneous Items		50.00	30.00	20.00	40.00
Labour		530.00	330.00	200.00	37.74
Paintwork Labour		450.00	300.00	150.00	33.33
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	2,783.40	1,853.50	929.90	33.41
	- Excess (S\$)	600.00	600.00	0.00	0.00
	(S\$)	2,183.40	1,253.50	929.90	42.59
	+ GST 7.00/7.00% (S\$)	152.84	87.75	65.09	42.59
	Nett Amount (S\$)	2,336.24	1,341.25	994.99	42.59

INSPECTION

Date of Assignment: 21/07/2022 Present Location: Kan Fook Sing Motor Workshop (Defu)

Kan Fook Sing Motor Workshop (Defu)

No. 61 Defu Lane 12 Date Inspected: 22/07/2022 Inspected At:

Singapore 539147

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 04 Nov 2022)

Parts: N/A ISUZU NPR75UH5A 5.2 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YK3288M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Torn	370.00 F	*140.00 F
		(WCP)			
2	1	*FRONT BUMPER BRACKE (WCP)	ET RH Bent	90.00 F	*65.00 F
3	1	*FRONT BUMPER BRACKE (WCP)	ET LH Bent	90.00 F	*65.00 F
4	1	*FRONT GRILLE (WCP)	Cracked	305.00 F	*305.00 F
5	1	*FRONT GRILLE CLIP (6PCS) (WCP)	Necessary	24.00 F	*20.00 F
6	1	*HEADLAMP RH (WCP)	Not Necessary	225.00 F	*-F
Sup	plementary #1	· · · ·			
7	1	*FRONT BONNET PANEL (WCP)	Bent	490.00 F	*490.00 F
F=Fra	anchise part.				
			Sub Total (S\$)	1,594.00	1,085.00
			+ Margin on L,N Items 10.00/10.00% (S\$)	159.40	108.50
			Total Parts (S\$)	1,753.40	1,193.50
		Report w	ras unsubmitted during this print-out.		

Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount
<u>Mis</u> 1	<mark>scella:</mark> 1	neous Items FRONT NUMBER PLATE (Bent)		50.00	30.00
			Sub Total (S\$)	50.00	30.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount	
<u>Pair</u>	twork Labour				
1	SPRAYPAINTING CHARGES	New	450.00	300.00	
Lab	our Items				
2	TO CHECK WIRING SYSTEM	New	50.00	30.00	
3	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	480.00	300.00	
	Gross Labour	r Cost (S\$)	980.00	630.00	
	Report was unsubmitted during this print-out.				

< END OF ESTIMATES >