4/12/23, 9:44 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG22006963/KEA3Q2

12/04/2023 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle SJV671D Insured Vehicle No: SJR2909C No:

Date of Loss: 20/07/2022 Nature of Claim: TP Claim No: 9115519228SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJV671D**

Make & Model: HONDA VEZEL, 1.5 X CVT (A) L15B4030885 Engine No: Reg. Date: 26/02/2016 (Man. Year: 2015) Chassis No: RU11110880 Metallic Pearl White Odometer: 150706 km Colour:

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes

CONDITION OF TYRES

215/60 R16 Front Tyre Size: 215/60 R16 Rear Tyre Size: Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm Front Right Side: Rear Right Side: Michelin 5 mm Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,095.20	2,132.24	1,962.96	47.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,730.00	1,140.00	1,590.00	58.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,825.20	3,272.24	3,552.96	52.06
Approved Total (Overridden) (S\$)		2,600.00		
Nett Amount (S\$)	6,825.20	2,600.00	4,225.20	61.91
+ Car Rental (5.0 x S	\$100.00/day) (S\$)	500.00		
+ Doc	/Search Fee (S\$)	7.45		
1	Nett Liability (S\$)	3,107.45		

INSPECTION

Date of Assignment: 25/07/2022

Tropical Success Auto Care (HQ)

BLK 5032 Ang Mo Kio Avenue 3, #01-303 Industrial Date Inspected: 25/07/2022 Inspected At:

Park 2

Singapore 569535

Estimated Period of Repair: 4.0 days

KENNETH KONG Adjuster: Manager: **CHEW HSIAO TONG**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent	1,565.00 FL	*953.00 FL
2	1		*REAR BOOT VEZEL DESIGNATION	Necessary	76.00 FL	*76.00 FL
3	2		*REAR BOOT DAMPER	Serviceable	460.00 FL	*- FL
4	1		*REAR BOOT RUBBER	Serviceable	122.00 FL	*- FL
5	2		*REAR FENDER WHEEL ARCH	Serviceable	270.00 FL	*- FL
6	1		*REAR LH TAIL LAMP (OUTER)	Serviceable	675.00 FL	*- FL
7	1		*REAR END PANEL	Bent	724.00 FL	*575.30 FL
8	1		*REAR BUMPER	Buckled	513.00 FL	*513.00 FL
9	2		*REAR BUMPER SIDE COVER (LH)	Buckled	176.00 FL	*176.00 FL
10	1		*REAR BUMPER REFLECTOR (LH)	Cracked	122.00 FL	*122.00 FL
11	2		*REAR BUMPER SIDE RETAINER	Serviceable	66.00 FL	*- FL
12	1		*SET REAR BUMPER PARKTRONIC SENSOR KIT	Dented	280.00 FS	*200.00 FS
F=Fra	nchise	part. S=SpcN	lett. L=ListItemDisc.	-		
				Sub Total (S\$)	5,049.00	2,615.30
			- List Item Discount on L Items	20.00/20.00% (S\$)	953.80	483.06
				Total Parts (S\$)	4,095.20	2,132.24
			Report was unsubmitted during this prir	nt-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	REMOVE & REFIT REAR WINDSCREEN	New	250.00	120.00
2	HEAT /WELD /CUT /RENEW REAR END PANEL ,HEAT /WELD /BEATING /PULL /STRAIGHTEN /ALIGN REAR CHASSIS FRAME BY CHASSIS ALIGNMENT JACK }	New	900.00	600.00
3	REMOVE AND TRANSFER REAR BOOT NECESSARY ATTACHMENT SPART PART ITEMS}	New	0.00	0.00
4	REMOVE AND TRANSFER REAR BUMPER NECESSARY ATTACHMENT SPART PART ITEMS }	New	0.00	0.00
5	REMOVE AND REFIT REAR BOOT ,REAR BOOT VEZEL DESIGNATION ,REAR BOOT DAMPERS ,REAR BOOT RUBBER ,REAR FENDER WHEEL ARCHS,REAR LH TAIL LAMP (OUTER),REAR BUMPER ,REAR BUMPER SIDE COVER (LH),REAR BUMPER PARKTRONIC SENSOR KITS ,REAR BUMPER REFLECTOR (LH),REAR BUMPER SIDE RETAINERS }		0.00	0.00
6	DIAGNOSTIC AND RESET REAR BUMPER PARKTRONIC SENSOR FAULT ERROR BY HHT	New	100.00	50.00
7	TO CHECK AND REFIT REAR TAIL LAMP WIRING HARNESS	New	80.00	20.00
8	UNDER, COATING ON REAR DAMAGED PORTION	New	200.00	30.00
9	PUTTY /PRIMER APPLICATION ,SPRAY PAINTING REAR BOOT ,REAR END PANEL,REAR BUMPER SIDE COVER (LH) ,REAR BUMPER PARKTRONIC SENSOR KIT	New	1,200.00	320.00
	Gross Labour	2,730.00	1,140.00	
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >