

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDX 8112J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	SERVICEABLE	1,350.50	-
1	SET FRONT BUMPER CLIPS	NOT NECESSARY	60.00	-
1	FRONT BUMPER SIDE RETAINER - LH	SERVICEABLE	83.50	-
1	FRONT BUMPER SIDE RETAINER - RH	SERVICEABLE	83.50	-
1	FRONT HEADLAMP - LH	SERVICEABLE	2,650.50	-
1	FOG LAMP - LH	SERVICEABLE	315.00	-
1	FOG LAMP COVER - LH	SERVICEABLE	115.20	-
1	REAR BUMPER	BUCKLED/CUT	1,450.10	876.40
1	REAR BUMPER REINFORCEMENT	BENT	520.50	454.30
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR BUMPER REFLECTOR - LH	SERVICEABLE	141.39	-
1	REAR BUMPER REFLECTOR - RH	SERVICEABLE	141.39	-
1	REAR BUMPER SIDE RETAINER- LH	SERVICEABLE	70.50	-
1	REAR BUMPER SIDE RETAINER- RH	SERVICEABLE	70.50	-
1	REAR BUMPER TOWING COVER	SERVICEABLE	60.00	-
1	REAR BUZZER SENSOR	DENTED	170.00	122.00
1	REAR END PANEL OUTER	BENT	792.05	541.00
1	REAR END PANEL INNER GARNISH	SERVICEABLE	253.71	-
1	REAR END PANEL TOP GARNISH	SERVICEABLE	288.90	-
1	REAR EXHAUST MUFFLER	TO REPAIR SEE LABOUR	1,890.20	-
1	REAR TAILGATE	TO REPAIR SEE LABOUR	1,625.49	-
1	REAR TAILGATE EMBLEM 'LOGO'	NOT NECESSARY	85.60	-
1	REAR TAILGATE EMBLEM 'QASHQAI'	NOT NECESSARY	113.31	-
	LESS 10% DISCOUNT		-	-204.37
			12,381.84	1,839.33
	SPECIAL NETT ITEMS			
1	SET REVERSE SENSORS (SN)	TORN	400.00	400.00
			400.00	400.00

Report Ref No. CS/SMR22006965/Kcy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR			
	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY. INCLUSIVE OF THE REPAIR OF REAR EXHAUST MUFFLER AND REAR TAILGATE.		1,200.00	500.00
	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.		1,200.00	400.00
	TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	NOT NECESSARY	200.00	-
	TO CHECK WIRING FUNCTIONS.		80.00	20.00
	COMPUTER DIAGNOSTIC RESET.	NOT NECESSARY	280.00	-
			2,960.00	920.00
	GRAND TOTAL		15,741.84	3,159.33

RECOMMENDED COST OF LUMP SUM REPAIRS		2,500.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SMR22006965/Kcy3m4

KONG SENG CHEONG

Licensed Appraiser