LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22006966/KCY3E2

10/08/2022 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNW00080902204

Claimant Vehicle

SLM1714G

Insured

GBG3074G

No:

Vehicle No:

Date of Loss:

19/07/2022

Nature of Claim: TP

Claim

SNM22D205057/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLM1714G Reg No:

TOYOTA COROLLA ALTIS, 1.6 (A) Make & Model:

23/03/2017 (Man. Year: 2016)

Engine No: Chassis No: Odometer:

1ZRY343455 MR053REH104561450

Yes

92892 km

Reg. Date: Colour:

Engine Capacity:

White

1598 cc

Market Value/New Car Price: Sum Insured (S\$):

N/A

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable):

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 215/45Z R17 Rear Tyre Size: 215/45Z R17 Front Left Side: Rear Left Side: Kumho 8 mm Kumho 8 mm Front Right Side: Kumho 8 mm Rear Right Side: Kumho 8 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|------------|------------|------------|--------|
| Parts | 9,834.37 | 5,518.05 | 4,316.32 | 43.89 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,500.00 | 1,050.00 | 1,450.00 | 58.00 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 12,334.37 | 6,568.05 | 5,766.32 | 46.75 |
| Approved Total (Overridden) (S\$) | | 5,200.00 | | |
| Nett Amount (S\$) | 12,334.37 | 5,200.00 | 7,134.37 | 57.84 |

INSPECTION

Date of Assignment: 21/07/2022

TSR AUTOMOTIVE PTE LTD (HQ)

160 SIN MING DRIVE, #06-01 SIN MING Date Inspected: 21/07/2022 Inspected At:

AUTOCITY

Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: **KENNETH KONG** Manager: **CELINE FONG**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Aug 2022)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLM1714G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| | Part No. | Particulars | Condition | Repairer's | Amount |
|----------------|--|--|--|--|------------------------------------|
| 1 | | *FRONT BUMPER | Buckled | 680.00 FL | *539.30 FL |
| 1 | | *FRONT BUMPER REINFORCEMENT | Repair | 580.00 FL | *- FL |
| 1 | | *FRONT BUMPER SPONGE | Cracked | 348.00 FL | *133.50 FL |
| 1 | | *FRONT BUMPER BRACKET RH | Repair | 220.00 FL | *- FL |
| 1 | | *FRONT BUMPER SIDE RETAINER RH | Serviceable | 180.00 FL | *- FL |
| 1 | | *FRONT BUMPER LOWER COVER | Serviceable | 480.00 FL | *- FL |
| 1 | | *RADIATOR PANEL | Buckled | 850.00 FL | *525.10 FL |
| 2 | | *HEADLAMPS | Mtg Cracked | 6,580.00 FL | *5,633.40 FL |
| 1 | | *HEADLAMP PANEL RH | Repair | 325.00 FL | *- FL |
| 1 | | *HEADLAMP LOWER BRACKETS | Repair | 168.00 FL | *- FL |
| 1 | | *FRONT FENDER RH | Repair | 580.00 FL | *- FL |
| 1 | | *FRONT FENDER UNDERSHIELD RH | Serviceable | 343.50 FL | *- FL |
| 1 | | *FOG LAMP GARNISH RH | Serviceable | 298.00 FL | *- FL |
| 1 | | *FRONT GRILLE | Cracked | 620.00 FL | *466.10 FL |
| 1 | | *BONNET (NPA) | Repair | 0.00 FL | *- FL |
| 10 | | *FRONT BUMPER CLIPS | Necessary | 45.00 FS | *45.00 FS |
| 1 inchise p | art. S=SpcN | *FRONT BUMPER LOWER SPOILER RH ett. L=ListItemDisc. | Serviceable | 600.00 FS | *-FS |
| | | | Sub Total (S\$) | 12.897.50 | 7,342.40 |
| | | - List Item Discount on L | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | 3,063.13 | 1,824.35 |
| | | | Total Parts (S\$) | 9,834.37 | 5,518.05 |
| | 1 1 1 1 1 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 | 1 1 1 1 1 1 1 2 1 1 1 1 1 1 1 1 1 1 | 1 *FRONT BUMPER REINFORCEMENT 1 *FRONT BUMPER SPONGE 1 *FRONT BUMPER BRACKET RH 1 *FRONT BUMPER SIDE RETAINER RH 1 *FRONT BUMPER LOWER COVER 1 *RADIATOR PANEL 2 *HEADLAMPS 1 *HEADLAMP PANEL RH 1 *HEADLAMP LOWER BRACKETS 1 *FRONT FENDER RH 1 *FRONT FENDER UNDERSHIELD RH 1 *FRONT GRILLE 1 *BONNET (NPA) 10 *FRONT BUMPER CLIPS 1 *FRONT BUMPER LOWER SPOILER RH Inchise part. S=SpcNett. L=ListItemDisc. | 1 *FRONT BUMPER REINFORCEMENT Repair 1 *FRONT BUMPER SPONGE Cracked 1 *FRONT BUMPER BRACKET RH Repair 1 *FRONT BUMPER SIDE RETAINER RH Serviceable 1 *FRONT BUMPER LOWER COVER Serviceable 1 *RADIATOR PANEL Buckled 2 *HEADLAMPS Mtg Cracked 1 *HEADLAMP PANEL RH Repair 1 *HEADLAMP LOWER BRACKETS Repair 1 *FRONT FENDER RH Repair 1 *FRONT FENDER UNDERSHIELD RH Serviceable 1 *FRONT FENDER UNDERSHIELD RH Serviceable 1 *FRONT GRILLE Cracked 1 *BONNET (NPA) Repair 10 *FRONT BUMPER CLIPS Necessary 1 *FRONT BUMPER CLIPS Serviceable 1 *FRONT BUMPER LOWER SPOILER RH Serviceable 1 *Inchise part. S=SpcNett. L=ListItemDisc. Sub Total (S\$) - List Item Discount on L Items 25.00/25.00% (S\$) | *FRONT BUMPER REINFORCEMENT Repair |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-----|--|-----------|------------|----------|
| Lab | <u>our Items</u> | | | |
| 1 | LABOUR CHARGE TO REPAIR, REPLACE, ALIGN ADJUST, REMOVE & REFIX ACCIDENT AFFECTED AREA | New | 800.00 | 500.00 |
| 2 | TO DO ANTI RUST | New | 90.00 | 30.00 |
| 3 | TO CHECK WIRING SYSTEM, FORCUS HEADLAMPS ETC | New | 120.00 | 20.00 |
| 4 | TO DO SPRAY PAINTING ON BONNET, BUMPER, SUPPORT PANEL, RADIATOR PANEL, LAMPS PANELS, FRONT FENDERS ETC (INNER AND OUTER) | New | 1,000.00 | 500.00 |
| 5 | LABOUR TO REMOVE REFIX RADIATOR, A/C CONDENSER, FILL GAS & REFILL RADIATOR COOLANT, SO AS TO REPLACE RADIATOR TOP PANEL AND REPAIR SUPPORT PANEL | New | 240.00 | 0.00 |
| 6 | TO DO COMPUTER SETTING, DIAGNOSE DELETE FAULT CODE AFTER REPAIR | New | 250.00 | 0.00 |
| | Gross Labour Cost (S\$) | | 2,500.00 | 1,050.00 |
| | Report was unsubmitted during this | print-out | | |

< END OF ESTIMATES >