

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006968/ACY3Q2**Date:** 26/09/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00037442200	
Claimant Vehicle No :	GBB6282D	Insured Vehicle No :	YQ3477C	
Date of Loss:	19/07/2022	Nature of Claim:	TP	Claim No: SNM22D205063/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB6282D		Engine No:	1KD1952982
Make & Model:	TOYOTA HIACE, 3.0 D (M)		Chassis No:	JTFHT02P200047946
Reg. Date:	22/09/2009 (Man. Year: 2009)		Odometer:	268823 km
Colour:	Silver			
Engine Capacity:	2982 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,026.97	10,839.89	5,187.08	32.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,900.00	3,320.00	1,580.00	32.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,926.97	14,159.89	6,767.08	32.34
Approved Total (Overridden) (\$\$)		11,300.00		
(\$\$)	20,926.97	11,300.00	9,626.97	46.00
+ GST 7.00/7.00% (\$\$)	1,464.89	791.00	673.89	46.00
Nett Amount (\$\$)	22,391.86	12,091.00	10,300.86	46.00

INSPECTION

Date of Assignment:	21/07/2022	
Date Inspected:	21/07/2022 Inspected At:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	12.0 days	

Adjuster: ADRIAN LING**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Sep 2022)	
Parts:	N/A	TOYOTA HIACE 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB6282D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*AIR CLEANER BOX	Cracked	780.80 FL	*780.80 FL
2	1		*AIR CLEANER DUCT	Not Necessary	112.00 FL	*- FL
3	1		*AIRCON CONDENSER	Dented	1,949.80 FL	*1,522.00 FL
4	1		*FRONT BONNET	Dented	896.72 FL	*896.72 FL
5	1		*FRONT BONNET LOGO EMBLEM	Necessary	86.52 FL	*86.52 FL
6	1		*FRONT BONNET MECHANISM LOCK	Not Necessary	96.37 FL	*- FL
7	1		*FRONT BRACE PANEL	Bent	64.60 FL	*64.60 FL
8	1		*FRONT BUMPER	Deformed	548.37 FL	*548.37 FL
9	1		*FRONT BUMPER CENTER BEAM	Bent	187.61 FL	*187.61 FL
10	1		*FRONT BUMPER GRILLE	Not Necessary	178.10 FL	*- FL
11	1		*FRONT BUMPER REINFORCEMENT	Dented	357.10 FL	*357.10 FL
12	2		*FRONT BUMPER REINFORCEMENT BRACKET L/R	Not Necessary	164.80 FL	*- FL
13	2		*FRONT BUMPER SIDE RETAINER L/R	Not Necessary	285.60 FL	*- FL
14	2		*FRONT BUMPER TOW HOOK COVER L/R	Not Necessary	57.80 FL	*- FL
15	1		*FRONT GRILLE	Cracked	568.60 FL	*568.60 FL
16	2		*FRONT HEADLAMP L/R	Cracked	1,488.00 FL	*1,488.00 FL
17	1		*FRONT SUPPORT PANEL	Not Necessary	395.30 FL	*- FL
18	1		*FRONT SUPPORT PANEL GARNISH	Not Necessary	88.50 FL	*- FL
19	1		*REAR BUMPER	Distorted	506.00 FL	*506.00 FL
20	4		*REAR BUMPER LOWER BRACKET	Bent	180.40 FL	*100.00 FL
21	2		*REAR BUMPER SIDE RETAINER L/R	Damaged	132.20 FL	*132.20 FL
22	1		*REAR END PANEL (INNER)	Dented	926.50 FL	*845.00 FL
23	1		*REAR END PANEL (OUTER)	Dented	563.00 FL	*563.00 FL
24	1		*REAR END PANEL INNER TOP MOULDING	Bent	198.10 FL	*198.10 FL
25	2		*REAR END PANEL SIDE RUBBER STOPPER L/R	Not Necessary	136.20 FL	*- FL
26	1		*REAR END SIDE PANEL L/R	O/S Dented	1,140.60 FL	*570.30 FL
27	1		*REAR EXHAUST GASKET	Not Necessary	18.00 FL	*- FL
28	1		*REAR EXHAUST PIPE	Not Necessary	538.20 FL	*- FL
29	2		*REAR EXHAUST RUBBER MOUNTING	Not Necessary	50.00 FL	*- FL
30	1		*REAR SPARE TYRE CARRIAGE BRACKET	Not Necessary	243.10 FL	*- FL
31	1		*REAR TAILGATE	Distorted	1,950.00 FL	*1,855.00 FL
32	1		*REAR TAILGATE LOGO EMBLEM	Necessary	71.60 FL	*71.60 FL
33	2		*REAR TAILGATE DAMPER L/R	Not Necessary	575.80 FL	*- FL
34	2		*REAR TAILGATE DUST SEAL COVER	Not Necessary	43.40 FL	*- FL
35	2		*REAR TAILGATE INNER RUBBER SIDE GUIDE STOPPER L/R	Not Necessary	57.00 FL	*- FL
36	1		*REAR TAILGATE INNER TRIM BOARD	Torn	244.10 FL	*165.00 FL
37	1		*REAR TAILGATE LOCK STRIKER	Not Necessary	70.20 FL	*- FL
38	2		*REAR TAILGATE LOWER JOINT MOULDING L/R	Not Necessary	43.20 FL	*- FL
39	1		*REAR TAILGATE MECHANISM LOCK	Damaged	263.00 FL	*263.00 FL
40	1		*REAR TAILGATE REMOTE CONTROL LOCK	Damaged	485.80 FL	*485.80 FL
41	1		*REAR TAILGATE WEATHERSTRIP	Cut	387.60 FL	*387.60 FL
42	1		*REAR TAILGATE WINDSCREEN GLASS	Not Necessary	1,340.00 FL	*- FL
43	1		*REAR TAILGATE WINDSCREEN SEAL	Necessary	100.00 FL	*100.00 FL
44	2		*REAR TAILLAMP L/R	Cracked	709.60 FL	*709.60 FL
45	2		*REAR TAILLAMP LOWER GARNISH L/R	Deformed	314.00 FL	*314.00 FL
46	2		*REAR TAILLAMP LOWER GARNISH SIDE RETAINER L/R	Not Necessary	106.00 FL	*- FL

Report was unsubmitted during this print-out.

9/26/22, 12:07 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*WASHER TANK	Not Necessary	69.10 FL	*- FL
48	1		*SET FRONT GRILLE CLIPS	Necessary	30.00 FS	*20.00 FS
49	1		*FRONT NUMBER PLATE	Cracked	25.00 FS	*25.00 FS
50	1		*FRONT NUMBER PLATE HOLDER	Deformed	50.00 FS	*30.00 FS
51	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
52	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
53	1		*SET REAR END PANEL INNER TOP MOULDING CLIPS	Necessary	30.00 FS	*20.00 FS
54	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
55	1		*REAR FLOOR TOP TRIM CARPET	Not Necessary	400.00 FS	*- FS
56	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
57	1		*REAR TAILGATE NUMBER PLATE	Not Necessary	25.00 FS	*- FS
58	1		*REAR TAILGATE NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
59	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
60	2		*SET REAR TAILLAMP CLIPS L/R	Necessary	40.00 FS	*20.00 FS
61	2		*SET REAR TAILLAMP LOWER GARNISH CLIPS L/R	Necessary	40.00 FS	*20.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					20,969.29	14,281.52
- List Item Discount on L Items 25.00/25.00% (S\$)					4,942.32	3,441.63
Total Parts (S\$)					16,026.97	10,839.89
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHARGE AIR CON PARTS ,VACUUM ,REFILL AIR CON GAS	New	150.00	100.00
2	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	80.00	80.00
3	TO REMOVE ,REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
4	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY CUSHION SEAT ,TRIM GARNISH TRIM LINER CARPET (TO FR)	New	100.00	60.00
5	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION AND WHERE CONSISTENT TO THE ACCIDENT	New	1,900.00	1,200.00
6	TO REMOVE AND CHARGE EXHAUST SILENCER BOX WITH PIPE ,RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	New	120.00	0.00
7	TO PROVIDE LABOUR WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENT AND DAMAGED CONSISTENT TO THE ACCIDENT	New	2,200.00	1,600.00
8	TO APPLY ANTI -RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	80.00
9	TO REMOVE ,REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION	New	80.00	80.00
Gross Labour Cost (\$\$)			4,900.00	3,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >