

TwinCar AUTOMOTIVE PTE LTD

sale / Admin

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SG LEASING PTE LTD
15 YISHUN INDUSTRIAL ST 1 #01-18 WIN 8
SINGAPORE 768091

Contact : 84211426, 98893879

T? Chiam.
celine.

TAX INVOICE

Repair Code : CLM15598

Date in : 20/07/2022

Vehicle Num. : GBB6282D

Model : TOYOTA HIACE MANUAL

Chassis/Eng# : JTFHT02P200047946/1KD1952982

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIR CLEANER BOX <i>Cracked</i>	1	780.80	780.80 ✓
AIR CLEANER DUCT <i>new</i>	1	112.00	112.00 x.
AIRCON CONDENSER <i>Dented.</i>	1	1949.80	1522 1949.80 ✓
FRONT BONNET <i>Dented</i>	1	896.72	896.72 ✓
FRONT BONNET 'LOGO' EMBLEM <i>new.</i>	1	86.52	86.52 ✓
FRONT BONNET MECHANISM LOCK <i>new</i>	1	96.37	96.37 x.
FRONT BRACE PANEL <i>Bent.</i>	1	64.60	64.60 ✓
FRONT BUMPER <i>Deformed</i>	1	548.37	548.37 ✓
FRONT BUMPER CENTER BEAM <i>Bent.</i>	1	187.61	187.61 ✓
FRONT BUMPER GRILLE <i>new</i>	1	178.10	178.10 x.
FRONT BUMPER REINFORCEMENT <i>Dented</i>	1	357.10	357.10 ✓
FRONT BUMPER REINFORCEMENT BRACKET L/R <i>new</i>	2	82.40	164.80 x.
FRONT BUMPER SIDE RETAINER L/R <i>new</i>	2	142.80	285.60 x.
FRONT BUMPER TOW HOOK COVER L/R <i>new</i>	2	28.90	57.80 x.
FRONT GRILLE <i>Cracked</i>	1	568.60	568.60 ✓
FRONT HEADLAMP L/R <i>Cracked</i>	2	744.00	1,488.00 ✓
FRONT SUPPORT PANEL <i>new</i>	1	395.30	395.30 x.
FRONT SUPPORT PANEL GARNISH <i>new</i>	1	88.50	88.50 x.

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

SG LEASING PTE LTD
 15 YISHUN INDUSTRIAL ST 1 #01-18 WIN 8
 SINGAPORE 768091

Contact : 84211426, 98893879

TAX INVOICE

Repair Code : CLM15598

Date in : 20/07/2022

Vehicle Num. : GBB6282D

Model : TOYOTA HIACE MANUAL

Chassis/Eng# : JTFHT02P200047946/1KD1952982

REAR BUMPER <i>Distorted</i>	1	506.00	506.00 ✓
REAR BUMPER LOWER BRACKET <i>Best</i>	4	45.10	180.40 <i>100</i>
REAR BUMPER SIDE RETAINER L/R <i>Best</i>	2	66.10	132.20 ✓
REAR END PANEL (INNER) <i>Distorted</i>	1	926.50	<i>845</i> 926.50 <i>x</i>
REAR END PANEL (OUTER) <i>Distorted</i>	1	563.00	563.00 ✓
REAR END PANEL INNER TOP MOULDING <i>Best</i>	1	198.10	198.10 ✓
REAR END PANEL SIDE RUBBER STOPPER L/R <i>Ne m</i>	2	68.10	136.20 <i>x</i>
REAR END SIDE PANEL L/R <i>PH Distorted</i>	2	570.30	1,140.60 <i>520.30</i>
REAR EXHAUST GASKET <i>Ne m</i>	1	18.00	18.00 <i>x</i>
REAR EXHAUST PIPE <i>Ne m</i>	1	538.20	538.20 <i>x</i>
REAR EXHAUST RUBBER MOUNTING <i>Ne m</i>	2	25.00	50.00 <i>x</i>
REAR SPARE TYRE CARRIAGE BRACKET <i>Ne m</i>	1	243.10	243.10 <i>x</i>
REAR TAILGATE <i>Distorted</i>	1	1950.00	<i>1855</i> 1,950.00
REAR TAILGATE 'LOGO' EMBLEM <i>Ne m</i>	1	71.60	71.60 ✓
REAR TAILGATE DAMPER L/R <i>Ne m</i>	2	287.90	575.80 <i>x</i>
REAR TAILGATE DUST SEAL COVER <i>Ne m</i>	2	21.70	43.40 <i>x</i>
REAR TAILGATE INNER RUBBER SIDE GUIDE STOPPER L/R <i>Ne m</i>	2	28.50	57.00 <i>x</i>
REAR TAILGATE INNER TRIM BOARD <i>torn</i>	1	244.10	<i>165</i> 244.10 ✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

SG LEASING PTE LTD
 15 YISHUN INDUSTRIAL ST 1 #01-18 WIN 8
 SINGAPORE 768091

Contact : 84211426, 98893879

TAX INVOICE

Repair Code : CLM15598

Date in : 20/07/2022

Vehicle Num. : GBB6282D

Model : TOYOTA HIACE MANUAL

Chassis/Eng# : JTFHT02P200047946/1KD1952982

REAR TAILGATE LOCK STRIKER <i>new</i>	1	70.20	70.20 <i>x</i>
REAR TAILGATE LOWER JOINT MOULDING L/R <i>new</i>	2	21.60	43.20 <i>x</i>
REAR TAILGATE MECHANISM LOCK <i>Damaged</i>	1	263.00	263.00 <i>✓</i>
REAR TAILGATE REMOTE CONTROL LOCK <i>Damaged</i>	1	485.80	485.80 <i>✓</i>
REAR TAILGATE WEATHER STRIP <i>lit</i>	1	387.60	387.60 <i>✓</i>
REAR TAILGATE WINDSCREEN GLASS <i>new</i>	1	1340.00	1,340.00 <i>x</i>
REAR TAILGATE WINDSCREEN SEAL <i>new</i>	1	100.00	100.00 <i>✓</i>
REAR TAILLAMP L/R <i>cracked</i>	2	354.80	709.60 <i>✓</i>
REAR TAILLAMP LOWER GARNISH L/R <i>Deformed.</i>	2	157.00	314.00 <i>✓</i>
REAR TAILLAMP LOWER GARNISH SIDE RETAINER L/R <i>new</i>	2	53.00	106.00 <i>x</i>
WASHER TANK <i>Not new</i>	1	69.10	69.10 <i>x</i>
Subtotal before discount			19,769.29
Percentage discount 25%			4,942.32
Sub-total 1			14,826.97
FRONT GRILLE CLIPS - SET <i>new</i>	1	30.00	30.00 <i>20</i>
FRONT NUMBER PLATE <i>cracked</i>	1	25.00	25.00 <i>✓</i>
FRONT NUMBER PLATE HOLDER <i>Dehd</i>	1	50.00	50.00 <i>30</i>
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	50.00 <i>30</i>

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

SG LEASING PTE LTD
 15 YISHUN INDUSTRIAL ST 1 #01-18 WIN 8
 SINGAPORE 768091

Contact : 84211426, 98893879

TAX INVOICE

Repair Code : CLM15598

Date in : 20/07/2022

Vehicle Num. : GBB6282D

Model : TOYOTA HIACE MANUAL

Chassis/Eng# : JTFHT02P200047946/1KD1952982

REAR BUMPER REVERSE SENSOR - SET <i>Damaged</i>	1	250.00	250.00 <i>200.</i>
REAR END PANEL INNER TOP MOULDING CLIPS - SET <i>Neu</i>	1	30.00	30.00 <i>20.</i>
REAR END PANEL SEALANT <i>Neu</i>	1	100.00	100.00 <i>60</i>
REAR FLOOR TOP TRIM CARPET <i>Neu Neu</i>	1	400.00	400.00 <i>X</i>
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>Neu</i>	1	50.00	50.00 <i>30.</i>
REAR TAILGATE NUMBER PLATE <i>3 NE</i>	1	25.00	25.00 <i>X</i>
REAR TAILGATE NUMBER PLATE HOLDER <i>ma</i>	1	50.00	50.00 <i>X</i>
REAR TAILGATE WINDSCREEN SEALANT <i>Neu</i>	1	60.00	60.00 <i>✓</i>
REAR TAILLAMP CLIPS L/R - SET <i>Neu</i>	2	20.00	40.00 <i>20</i>
REAR TAILLAMP LOWER GARNISH CLIPS L/R - SET <i>Neu</i>	2	20.00	40.00 <i>20.</i>
Subtotal before discount			1,200.00
Percentage discount 0%			0.00
Sub-total 2			1,200.00
Parts-total			16,026.97

LABOUR

To remove, change air con parts, vacuums, refill air con gas.

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

~~150.00~~ *100.*

~~80.00~~ *✓*

~~150.00~~ *120.*

~~100.00~~ *60.*

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SG LEASING PTE LTD
15 YISHUN INDUSTRIAL ST 1 #01-18 WIN 8
SINGAPORE 768091

Contact : 84211426, 98893879

TAX INVOICE

Repair Code : CLM15598

Date in : 20/07/2022

Vehicle Num. : GBB6282D

Model : TOYOTA HIACE MANUAL

Chassis/Eng# : JTFHT02P200047946/1KD1952982

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

1,900.00 ~~12w~~

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

120.00 ~~X.~~

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

2,200.00 ~~16w~~

To apply anti-rust chemical on repaired and replaced panel.

120.00 ~~8w.~~

To remove, reinstall tailgate mechanism and check for function

80.00 ~~✓~~

3320

Labour Total

4,900.00

Parts & Labour Total

20,926.97

*** This is a computer-generated document which requires no signature.***

page 5

Admining.
w/s. 12 Days

total: 14,5866

h/s: 11.3K ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: