

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006970/KCY3Q2**Date:** 28/11/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00262722100		
Claimant Vehicle No :	SMM1743K	Insured Vehicle No :	SKF1637U		
Date of Loss:	19/07/2022	Nature of Claim:	TP	Claim No:	SNM22D205036/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM1743K		Engine No:	LEB6447807
Make & Model:	HONDA GRACE HYBRID, 1.5 DX (A)		Chassis No:	GM41207782
Reg. Date:	20/06/2019 (Man. Year: 2018)		Odometer:	47402 km
Colour:	White			
Engine Capacity:	1496 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	INTERTRAC 7 mm	Rear Left Side:	INTERTRAC 8 mm
Front Right Side:	INTERTRAC 7 mm	Rear Right Side:	INTERTRAC 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,004.08	7,517.28	16,486.80	68.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,190.00	3,640.00	3,550.00	49.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,194.08	11,157.28	20,036.80	64.23
Approved Total (Overridden) (S\$)		8,900.00		
(S\$)	31,194.08	8,900.00	22,294.08	71.47
+ GST 7.00/7.00% (S\$)	2,183.59	623.00	1,560.59	71.47
Nett Amount (S\$)	33,377.67	9,523.00	23,854.67	71.47

INSPECTION

Date of Assignment:	29/09/2022	
Date Inspected:	22/07/2022 Inspected At:	My Car Consultant Pte Ltd (Jalan Lam Huat) (HQ) 60 Jalan Lam Huat, Carros Centre #05-21 Singapore 737869
Estimated Period of Repair:	12.0 days	

Adjuster: KENNETH KONG**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Nov 2022)
Parts: 143	HONDA GRACE HYBRID 1.5 DX (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM1743K)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	978.20 FL	*978.20 FL
2	1		*BOOTLID LOCK	Dented	287.30 FL	*287.30 FL
3	1		*BOOTLID LOCK CATCH	Distorted	35.30 FL	*35.30 FL
4	2		*BOOTLID HINGE	Distorted / Bent	249.60 FL	*210.00 FL
5	1		*BOOTLID EMBLEM LOGO	Necessary	37.50 FL	*37.50 FL
6	1		*BOOTLID EMBLEM GARCE	Necessary	44.70 FL	*44.70 FL
7	1		*BOOTLID EMBLEM HYBRIDE	Necessary	57.40 FL	*57.40 FL
8	1		*BOOTLID CHROME MOULDING	Cut	258.20 FL	*216.10 FL
9	2		*BOOTLID LAMP	Cracked	705.80 FL	*652.00 FL
10	1		*BOOTLID INNER TRIM BOARD	Deformed	181.70 FL	*181.70 FL
11	1		*REAR BUMPER	Bent	816.20 FL	*585.60 FL
12	2		*REAR BUMPER SIDE RETAINER	Cracked	122.40 FL	*122.40 FL
13	1		*REAR BUMPER CENTER GRILLE	Cracked	112.20 FL	*112.20 FL
14	1		*REAR BUMPER REFLECTOR	N/S Missing	136.00 FL	*68.00 FL
15	2		*REAR BUMPER REFLECTOR OUTER GARNISH	Dented	144.80 FL	*144.80 FL
16	1		*REAR BUMPER UNDERCOVER	Bent	398.20 FL	*210.60 FL
17	1		*REAR END PANEL OUTER	Bent	598.30 FL	*395.00 FL
18	1		*REAR END PANEL INNER	No such part	489.00 FL	*- FL
19	1		*REAR END PANEL TOP GARNISH	Distorted	212.50 FL	*170.00 FL
20	1		*REAR WEATHERSTRIPE	Distorted / Dented	198.80 FL	*198.80 FL
21	2		*TAILLAMP	Cracked	1,174.40 FL	*763.40 FL
22	2		*TAILLAMP INNER PANEL	Bent	596.60 FL	*196.00 FL
23	1		*REAR SPARE TYRE TOP COVER BOARD	Cracked	325.00 FL	*168.50 FL
24	1		*REAR SPARE TYRE PANEL COMPARTMENT	Bent	1,452.00 FL	*858.00 FL
25	1		*REAR TOOLS SPONGE	Cracked	529.00 FL	*352.50 FL
26	2		*REAR FENDER	Repair	2,269.90 FL	*- FL
27	2		*REAR FENDER INNER PANEL	Repair	1,249.00 FL	*- FL
28	2		*RH REAR INNER COWLING	Serviceable	318.00 FL	*- FL
29	2		*RH REAR FENDER INNER TRIM BOARD	Deformed	974.40 FL	*576.00 FL
30	1		*REAR HYBRID BATTERY	Serviceable	9,850.00 FL	*- FL
31	1		*REAR CHASSIS EXTENSION	N/S Bent	624.00 FL	*312.00 FL
32	1		*REAR DOOR LOCK	Repair	312.00 FL	*- FL
33	1		*RH REAR DOOR WEATHERSTRIPE	Serviceable	119.20 FL	*- FL
34	1		*REAR AXLE BEAM	Serviceable	877.20 FL	*- FL
35	1		*RH REAR SHOCK ABSORBER	Serviceable	256.80 FL	*- FL
36	1		*REAR EXHAUST MUFFLER	Bent	1,259.00 FL	*688.10 FL
37	1		*REAR EXHAUST MUFFLER ALUMINIUM	Dented	298.00 FL	*162.00 FL
38	2		*REAR EXHAUST MRFFLER RUBBER	Serviceable	44.00 FL	*- FL
39	1		*REAR REVERSE SENSOR	Dented	250.00 FS	*200.00 FS
40	1		*REAR REVERSE CAMERA	Serviceable	400.00 FS	*- FS
41	1		*REAR BUMPER CLIP	Necessary	80.00 FS	*50.00 FS
42	1		*REAR END PANEL GARNISH CLIP	Necessary	30.00 FS	*30.00 FS
43	1		*FLOOR PANEL SEALANT	Necessary	80.00 FS	*30.00 FS
44	1		*END PANEL SEALANT	Necessary	80.00 FS	*30.00 FS
45	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	60.00 FS	*- FS
46	2		*REAR FENDER INNER TRIM CLIPS	Necessary	100.00 FS	*100.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
47	1		*BOOTLID CLIPS	Necessary	50.00 FS	*50.00 FS	
			F=Franchise part. S=SpcNett. L=ListItemDisc.				
					Sub Total (\$)	29,722.60	9,274.10
					- List Item Discount on L Items 20.00/20.00% (\$)	5,718.52	1,756.82
					Total Parts (\$)	24,004.08	7,517.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	160.00	60.00
2	TO CHECK ELECTRICAL WIRING	New	80.00	20.00
3	TO REMOVE AND REFIT REVERSE SENSOR /CAMERA	New	150.00	80.00
4	REMOVE AND REFIX REAR UPHOLSTERY	New	150.00	120.00
5	REMOVE AND RENEW RH REAR UNDERCARRIAGE	New	200.00	160.00
6	REPAIR AND STRAIGHTEN REAR CHASSIS FRAME	New	300.00	200.00
7	RENEW /REPAIR AND STRAIGHTEN EXHAUST PIPE	New	250.00	60.00
8	RESET HYBRID BATTERY CODE	New	500.00	200.00
9	REMOVE AND TRANSFER REAR BOOTLID FITTING	New	150.00	50.00
10	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	150.00	0.00
11	CHECK AND RESET FAULT CODE LIGHT ON	New	150.00	0.00
12	TO RESPRAY UNDERCOATING }	New	150.00	90.00
13	APPLY ANTI RUST ON AFFECTED AREAS }	New	200.00	0.00
14	SPRAY PAINTING ON AFFECTED AREAS	New	2,200.00	1,200.00
15	PANEL BEATING ON AFFECTED AREAS	New	2,400.00	1,400.00
Gross Labour Cost (\$\$)			7,190.00	3,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >