

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22006972/AVCE2**Date:** 21/11/2022REFERENCE

Insured/Claimant:	DAVID LOO WENG YEOW	Policy No:	7210151146	
Date of Loss:	15/07/2022	Nature of Claim:	OD	Claim No: 9327260061SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNG8100P		
Make & Model:	AUDI A6, 2.0 TFSI (A)	Engine No:	DKY016209
Reg. Date:	23/12/2021 (Man. Year: 2021)	Chassis No:	WAUZZZF29NN002959
Colour:	Grey	Odometer:	10526 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$260,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	43,901.00	18,111.28	25,789.72	58.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,352.00	3,652.00	10,700.00	74.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	58,253.00	21,763.28	36,489.72	62.64
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	57,453.00	20,963.28	36,489.72	63.51
+ GST 7.00/7.00% (S\$)	4,021.71	1,467.43	2,554.28	63.51
Nett Amount (S\$)	61,474.71	22,430.71	39,044.00	63.51

INSPECTION

Date of Assignment:	22/07/2022	
Date Inspected:	20/07/2022	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	3,012.00 FS	*2,409.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	658.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - CENTER	Cracked	248.00 FS	*198.40 FS
4	2		*FRONT BUMPER ADAPTER - LH / RH	Damaged	88.00 FS	*70.24 FS
5	2		*FRONT BUMPER REINFORCEMENT - LH / RH	Not Necessary	250.00 FS	*- FS
6	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Not Necessary	171.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT - LOWER	Not Necessary	235.00 FS	*- FS
8	1		*FRONT BUMPER SPOILER	Not Necessary	282.00 FS	*- FS
9	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	970.00 FS	*- FS
10	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	66.00 FS	*- FS
11	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	48.00 FS	*- FS
12	1		*RADIATOR GRILLE	Cracked	2,460.00 FS	*1,968.00 FS
13	1		*COVER 360 CAMERA COVER	Not Necessary	61.00 FS	*- FS
14	1		*COVER CAP 360 CAMERA REAR COVER	Not Necessary	55.00 FS	*- FS
15	1		*BRACKET 360 CAMERA BRACKET	Damaged	104.00 FS	*82.80 FS
16	1		*360 CAMERA	Not Necessary	1,003.00 FS	*- FS
17	1		*CAMERA ADAPTER CABLE	Not Necessary	460.00 FS	*- FS
18	2		*FRONT PARKING AID SENSOR	Not Necessary	292.00 FS	*- FS
19	4		*FRONT PARKING SEAL RING	Not Necessary	10.00 FS	*- FS
20	1		*SET FRONT BUMPER WIRING	Not Necessary	642.00 FS	*- FS
21	1		*FRONT LOW TONE HORN - LH	Not Necessary	230.00 FS	*- FS
22	1		*FRONT HIGH TONE HORN - RH	Not Necessary	154.00 FS	*- FS
23	2		*FRONT HORN BRACKET - LH / RH	Not Necessary	106.00 FS	*- FS
24	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	252.00 FS	*201.60 FS
25	1		*FRONT BUMPER REINFORCEMENT BEAM	Bent	1,076.00 FS	*860.80 FS
26	2		*FRONT BUMPER REINFORCEMENT BEAM SUPPORT - LH / RH	Not Necessary	67.00 FS	*- FS
27	6		*FRONT POP RIVET REINFORCEMENT BEAM	Not Necessary	6.00 FS	*- FS
28	2		*FRONT BUMPER BRACKET - LH / RH	Not Necessary	122.00 FS	*- FS
29	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	100.00 FS	*- FS
30	1		*FRONT BUMPER TOP COVER	Deformed	140.00 FS	*112.00 FS
31	1		*CAUTION SIGN STICKER	Necessary	16.00 FS	*12.40 FS
32	1		*AIR CONDITIONAL STICKER	Necessary	34.00 FS	*26.96 FS
33	1		*BONNET	Dented	5,846.00 FS	*4,676.80 FS
34	2		*BONNET LID HINGE - LH / RH	Not Necessary	382.00 FS	*- FS
35	1		*BONNET IMPACT PROTECTION - LH	Necessary	21.00 FS	*16.40 FS
36	1		*BONNET IMPACT PROTECTION - CENTER	Necessary	50.00 FS	*39.36 FS
37	1		*BONNET ATTACHMENT PARTS	Not Necessary	243.00 FS	*- FS
38	2		*BONNET STRIKER - LH / RH	Not Necessary	246.00 FS	*- FS
39	2		*BONNET MICRO - SWITCH LID LOCK	Not Necessary	477.00 FS	*- FS
40	1		*BONNET RELEASE ELEMENT	Not Necessary	64.00 FS	*- FS
41	1		*BONNET RELEASE LEVER	Not Necessary	15.00 FS	*- FS
42	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	64.00 FS	*- FS
43	1		*BONNET HOOD-LOCK CABLE COVER	Not Necessary	11.00 FS	*- FS
44	2		*HEADLIGHT MOUNTING - LH / RH	Not Necessary	264.00 FS	*- FS
45	1		*MATRIX BEAM LED HEADLIGHT - LH / RH	N/s cracked	18,344.00 FS	*7,337.60 FS
46	2		*LIFT CYLINDER - LH / RH	Not Necessary	434.00 FS	*- FS
47	2		*LIFT CYLINDER BRACKET - LH / RH	Not Necessary	14.00 FS	*- FS
48	1		*LIFT CYLINDER HOSE	Not Necessary	204.00 FS	*- FS
49	1		*FRONT LOCK CARRIER	Not Necessary	1,368.00 FS	*- FS
50	1		*DRYER A/C CONDENSER	Not Necessary	683.00 FS	*- FS
51	1		*BRACKET	Damaged	26.00 FS	*20.40 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	2		*CHARGE AIR COOLER	Not Necessary	654.00 FS	*- FS
53	6		*READY-MIX COOLANT	Not Necessary	282.00 FS	*- FS
54	2		*RADIATOR AIR GUIDE - LH / RH	Not Necessary	88.00 FS	*- FS
55	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	34.00 FS	*- FS
56	1		*RADIATOR AIR GUIDE - LOWER	Not Necessary	38.00 FS	*- FS
57	2		*FRONT BONNET HINGE COVER - LH / RH	Not Necessary	98.00 FS	*- FS
58	1		*SUNDRIES	Not Necessary	450.00 FS	*- FS
59	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
60	1		*BONNET IMPACT PROTECTION - RH	Necessary	23.00 FS	*17.92 FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	43,901.00 18,111.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	400.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM	New	1,600.00	0.00
4	TO CARRY OUT VACUUM AND REGAS FOR R1234	New	1,200.00	0.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, AND BOTH HEADLIGHT. TO REPAIR BOTH FRONT FENDER. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	1,000.00
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES AND BOTH FRONT FENDER	New	4,000.00	1,100.00
7	TO CARRY OUT CALIBRATION FOR FRONT BUMPER RADAR SENSOR AND DISTANCE REGULATION	New	480.00	480.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			14,352.00	3,652.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >