11/1/22, 1:15 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd. Our File No: CC3/AIG22006974/ACM4 AIG Building, 78 Shenton Way, #09-16

01/11/2022 Date: Singapore 079120

**REFERENCE** 

Insured/Claimant: AW WEI KENG KELVIN Policy No: 2070122616

Date of Loss: 16/07/2022 Nature of Claim: OD Claim No: 3371864502SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMU9734S

Make & Model: AUDI A4, 2.0 TFSI S-TRONIC (A) Engine No: DEM024244

Reg. Date: 25/08/2020 (Man. Year: 2020) WAUZZZF41LN014697 Chassis No:

Colour: Bronze Odometer: 56809 km

**Engine Capacity:** 1984 cc S\$161,000.00 Market Value/New Car Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

**CONDITION OF TYRES** 

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17 Rear Left Side: Front Left Side: Pirelli 6 mm Pirelli 6 mm Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		6,500.00	3,893.44	2,606.56	40.10
Miscellaneous Items		0.00	0.00	0.00	
Labour		5,852.00	2,452.00	3,400.00	58.10
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	12,352.00	6,345.44	6,006.56	48.63
	- Excess (S\$)	1,100.00	1,100.00	0.00	0.00
	(S\$)	11,252.00	5,245.44	6,006.56	53.38
	+ GST 7.00/7.00% (S\$)	787.64	367.18	420.46	53.38
	Nett Amount (S\$)	12,039.64	5,612.62	6,427.02	53.38

**INSPECTION** 

Date of Assignment: 22/07/2022

Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Date Inspected: 21/07/2022 Inspected At:

Singapore 408699

Estimated Period of Repair: 5.0 days

**CELINE FONG** Adjuster: **ADRIAN LING** Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR - RH	Dented	3,431.00 FS	*2,744.80 FS
2	1		*REAR OUTER DOOR SEAL - RH	Necessary	229.00 FS	*182.80 FS
3	1		*BONDING AGENT	Not Necessary	51.00 FS	*- FS
4	1		*CLEANING SOLUTION	Not Necessary	74.00 FS	*- FS
5	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
6	1		*REAR SEALING STRIP	Not Necessary	19.00 FS	*- FS
7	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	943.00 FS	*- FS
8	1		*REAR DOOR CATCH - RH	Not Necessary	134.00 FS	*- FS
9	2		*REAR OVAL HEXAGON SOCKET HEAD BOLT	Not Necessary	3.00 FS	*- FS
10	1		*REAR DOOR HANDLE PRIMED TRIM PLATE - RH	Repair	98.00 FS	*- FS
11	1		*REAR HOUSING - RH	Not Necessary	9.00 FS	*- FS
12	1		*WING MIRROR MOUNTING - RHS	Cut	1,201.00 FS	*960.80 FS
13	1		*SUNDRIES	Necessary	300.00 FS	*5.04 FS
F=Fra	ınchise	part. S=Spcl	Nett.	-		
				Total Parts (S\$)	6,500.00	3,893.44
			Report was unsubmitted during this	nrint out		

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO REMOVE AND TRANSFER BOTH DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	560.00	560.00
2	TO DISMANTLE AND RENEW RHS REAR DOOR. TO REPAIR RHS REAR FENDER AND RHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,100.00	500.00
3	TO RESPRAY RHS REAR DOOR, DOOR HANDLE, RHS REAR FENDER AND RHS SILL PANEL	New	3,000.00	1,200.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labour Cost (S\$)		5,852.00	2,452.00
	Report was unsubmitted during thi	s print-out.		

< END OF ESTIMATES >