12/9/22, 12:08 PM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI22006977/RVY3Q2

09/12/2022 Date:

**REFERENCE** 

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No: DMCG21008475

**Claimant Vehicle** SJL1858D Insured Vehicle No: YN7274K No:

Date of Loss: 12/07/2022 Nature of Claim: TP Claim No: CDMCG22001395

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SJL1858D** 

Make & Model: L13A4092213 HONDA FIT, 1.3 G (A) Engine No: Reg. Date: 18/11/2008 (Man. Year: 2008) Chassis No: GE61081697 Colour: Odometer: 245575 km Blue

**Engine Capacity:** 1339 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes

CONDITION OF TYRES

195/60 R15 195/60 R15 Front Tyre Size: Rear Tyre Size: Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm Front Right Side: Rear Right Side: Bridgestone 5 mm Bridgestone 5 mm

The above values represent the remaining tyre treads depth

Repairer's	Adjuster's	Difference	Diff %
2,817.04	1,306.24	1,510.80	53.63
0.00	0.00	0.00	
1,230.00	780.00	450.00	36.59
0.00	0.00	0.00	
0.00	0.00	0.00	
\$) 4,047.04	2,086.24	1,960.80	48.45
\$)	1,650.00		
\$) 4,047.04	1,650.00	2,397.04	59.23
\$) 283.29	115.50	167.79	59.23
\$) 4,330.33	1,765.50	2,564.83	59.23
	\$) 4,047.04 \$) 283.29	2,817.04 1,306.24 0.00 0.00 1,230.00 780.00 0.00 0.00 0.00 0.00 \$  4,047.04 2,086.24 \$ 1,650.00 \$  4,047.04 1,650.00 \$  283.29 115.50	2,817.04 1,306.24 1,510.80 0.00 0.00 0.00 1,230.00 780.00 450.00 0.00 0.00 0.00 0.00 0.00 0.0

**INSPECTION** 

Date of Assignment: 22/07/2022

My Car Consultant Pte Ltd ( Jalan Lam Huat ) (HQ) Date Inspected: 10/10/2022 Inspected At:

60 Jalan Lam Huat, Carros Centre #05-21

Singapore 737869

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL **VERON CHEN** Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Dec 2022)

Parts: 144 HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJL1858D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	698.00 FL	*495.00 FL
2	1		*FRONT BUMPER SIDE RETAINER LH	Not Necessary	35.20 FL	*- FL
3	1		*HEADLAMP LH	Cut	1,420.00 FL	*649.00 FL
4	2		*HEADLAMP LOWER BRACKET	Not Necessary	118.60 FL	*- FL
5	1		*FRONT FENDER LH	Repair	598.00 FL	*- FL
6	1		*SIDE MIRROR LH	Cracked	589.00 FL	*451.30 FL
7	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
F=Fra	inchise	part. S=SpcN	ett. L=ListItemDisc.	Sub Total (S\$)	3,508.80	1,625.30
			- List Item Discount	on L Items 20.00/20.00% (S\$)	691.76	319.06
				Total Parts (S\$)	2,817.04	1,306.24
			Report was unsubmitted	during this print-out		

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen\_printrpt&caseid=1148717&extid=397790&CFID=10187...

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			*
1	SPRAY PAINTING ON AFFECTED AREAS	New	500.00	450.00
2	PANEL BEATING ON AFFECTED AREAS	New	500.00	300.00
3	REALIGN HEADLAMP	New	50.00	0.00
4	TO CHECK ELECTRICAL WIRING	New	80.00	30.00
5	APPLY ANTI RUST ON AFFECTED AREAS	New	100.00	0.00
		Gross Labour Cost (S\$)	1,230.00	780.00
	Renort was ur	nsubmitted during this print-out.		

< END OF ESTIMATES >