

## Vehicle Damage Assessment Report for [SJL1858D]

Estimate Created: 08/12/2022 04:07 by Insurlogic 1 (Insurlogic\_Pte\_Ltd)

Owned: 08/12/2022 04:14 by Insurlogic 1 (Insurlogic\_Pte\_Ltd)

### General Information

|                   |                              |                  |
|-------------------|------------------------------|------------------|
| Insurance Company | ERGO INSURANCE               | Claim Number     |
| Claim Type        | TP                           |                  |
| Workshop          | LKK_Auto_Consultants_Pte_Ltd | Reference Number |

### Vehicle Information

|                      |          |                    |     |
|----------------------|----------|--------------------|-----|
| Brand                | Honda    | Model              | Fit |
| Engine Type          |          |                    |     |
| License Plate Number | SJL1858D | VIN (or Chassis #) |     |

### Vehicle Condition

|                 |                 |         |
|-----------------|-----------------|---------|
| Damaged Diagram | Odometer        | 0.00 Km |
|                 | Tyres Condition |         |
|                 | Front Left      | mm      |
|                 | Front Right     | mm      |
|                 | Rear Left       | mm      |
|                 | Rear Right      | mm      |

### Comments

- Final review base on information provide by LKK: Concluded the cost of repair at lump sum \$1650.00 with 3 days for repair

Insurlogic 1 (08/12/2022 04:11)

**Parts**

| Description     | Number/Type | Qty | Cost   | Markup/Disc. % | Sum      |
|-----------------|-------------|-----|--------|----------------|----------|
| FRONT BUMPER    |             | 1   | 495.00 | -20.00 %       | 396.00   |
| HEADLAMP LH     |             | 1   | 649.00 | -20.00 %       | 519.20   |
| SIDE EMIRROR LH |             | 1   | 451.30 | -20.00 %       | 361.04   |
| Parts Subtotal  |             |     |        |                | 1,276.24 |

**Materials**

| Description        | Number/Type | Qty | Cost  | Markup/Disc. % | Sum   |
|--------------------|-------------|-----|-------|----------------|-------|
| FRONT BUMPER CLIPS |             | 1.0 | 30.00 | 0.00 %         | 30.00 |
| Materials Subtotal |             |     |       |                | 30.00 |

**Labor****Replace/RnR**

| Description                                       | Type | Cost   | Markup/Disc % | Price  |
|---------------------------------------------------|------|--------|---------------|--------|
| REPLACE/ REPAIR ACCIDENT AFFECTED ITEMS AND AREAS | RnR  | 450.00 | 0.00 %        | 450.00 |
| CHECK WIRE                                        | RnR  | 30.00  | 0.00 %        | 30.00  |

**Paint**

| Description                      |               | Paint Type | Cost   | Markup/Disc %          | Price  |
|----------------------------------|---------------|------------|--------|------------------------|--------|
| PAINT ON ACCIDENT AFFECTED AREAS |               | Full spray | 300.00 | 0.00 %                 | 300.00 |
| Labor Rate                       | S\$ 50 / Hour |            |        | General Labor Subtotal | 480.00 |
|                                  |               |            |        | Paint Labor Subtotal   | 300.00 |
|                                  |               |            |        | Labor Subtotal         | 780.00 |

**Summary**

|                |          |
|----------------|----------|
| Repair Cost    | 2,086.24 |
| Discount(21 %) | (436.24) |
|                | 1,650.00 |
| Excess         | (0.00)   |
| GST(0.00 %)    | 0.00     |
| Grand Subtotal | 1,650.00 |