

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22006979/ENY3Q2**Date:** 02/11/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00085502201
<b>Claimant Vehicle No :</b>	GBG3825G	<b>Insured Vehicle No :</b>	GBL2376R
Date of Loss:	19/07/2022	Nature of Claim:	TP
		Claim No:	SNM22D205067/C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBG3825G</b>		
Make & Model:	FIAT DOBLO, 1.6 D CARGO MJ (M)	Engine No:	198A30008093574
Reg. Date:	27/07/2017 (Man. Year: 2017)	Chassis No:	ZFA26300006G92612
Colour:	Grey	Odometer:	164542 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,942.44	6,050.41	3,892.03	39.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,820.00	2,100.00	720.00	25.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,762.44</b>	<b>8,150.41</b>	<b>4,612.03</b>	<b>36.14</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,500.00</b>		
<b>(S\$)</b>	12,762.44	6,500.00	6,262.44	49.07
<b>+ GST 7.00/7.00% (S\$)</b>	893.37	455.00	438.37	49.07
<b>Nett Amount (S\$)</b>	<b>13,655.81</b>	<b>6,955.00</b>	<b>6,700.81</b>	<b>49.07</b>

**INSPECTION**

Date of Assignment:	21/07/2022		
Date Inspected:	02/08/2022	Inspected At:	Wah Hong Motors & Credit Pte Ltd (HQ) 38 Toh Guan Road East, #01-57, Enterprise Hub Singapore 608581
Estimated Period of Repair:	6.0 days		

**Adjuster:** CHEN TSUE YEE**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 01 Nov 2022)	
<b>Parts:</b>	N/A	FIAT DOBLO 1.6 D CARGO MJ (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBG3825G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR LH	Dented	2,640.00 FL	*1,069.00 FL
2	1		*REAR DOOR LOWER HINGE LH	Bent	154.00 FL	*97.00 FL
3	1		*REAR DOOR RH	Dented	2,090.00 FL	*1,978.00 FL
4	1		*REAR DOOR LOWER HINGE RH	Bent	154.00 FL	*97.00 FL
5	1		*REAR DOOR CAR PLATE BASE GARNISH LH	Crushed	440.00 FL	*367.00 FL
6	1		*REAR DOOR LOGO BASE GARNISH RH	Cut	420.00 FL	*87.00 FL
7	1		*REAR DOOR RH EMBLEM DOBLO MAX	Necessary	264.00 FL	*80.00 FL
8	1		*REAR DOOR RH EMBLEM 10S MULTIJET2	Necessary	308.00 FL	*60.00 FL
9	1		*REAR DOOR LH EMBLEM PROFESSIONAL	Necessary	330.00 FL	*85.00 FL
10	1		*REAR DOOR LH LOGO BADGE FIAT	Necessary	264.00 FL	*85.00 FL
11	1		*REAR BUMPER	Crushed	616.00 FL	*616.00 FL
12	2		*REAR BUMPER SIDE RETAINER LH /RH	Not Necessary	132.00 FL	*- FL
13	1		*REAR REINFORCEMENT	Bent	484.00 FL	*484.00 FL
14	1		*END PANEL	Dented	1,056.00 FL	*430.00 FL
15	1		*END PANEL TOP GARNISH	Crushed	660.00 FL	*347.00 FL
16	1		*BOOT LID WEATHERSTRIP	Crushed	440.00 FL	*378.86 FL
17	1		*REAR BUMPER REFLECTOR RH	Broken	39.60 FL	*39.60 FL
18	1		*REAR BUMPER CLIPS	Necessary	35.00 FS	*30.00 FS
19	1		*REAR CARPLATE WITH HOLDER	Not Necessary	35.00 FS	*- FS
20	1		*REAR REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
21	1		*REAR DOOR WINDSCREEN SEALANT LH	Necessary	60.00 FS	*35.00 FS
22	1		*REAR DOOR WINDSCREEN SEALANT RH	Necessary	60.00 FS	*35.00 FS
23	1		*6 PAX STICKER	Necessary	25.00 FS	*25.00 FS
24	1		*70KM/H STICKER	Necessary	25.00 FS	*25.00 FS
25	1		*END PANEL SEALANT	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>10,991.60</b>	<b>6,680.46</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	1,049.16	630.05
<b>Total Parts (S\$)</b>	<b>9,942.44</b>	<b>6,050.41</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,200.00	1,000.00
2	TO SUPPLY PAINT MATERIALS EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	1,000.00	800.00
3	TO REMOVE /REFIX /REPLACE WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION	New	90.00	30.00
4	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	90.00	30.00
5	TO REMOVE AND REFIT /REPLACE REAR COMPARTMENT FITTING ,TRIMMING ,GARNISH ,REAR SPARE TYRE WITH BRACKET AND ETC	New	100.00	50.00
6	TO REMOVE AND REPLACE REAR WINDSCREEN LH	New	120.00	80.00
7	TO REMOVE AND REPLACE REAR WINDSCREEN RH	New	120.00	80.00
8	TO REMOVE AND REPLACE REAR REVERSE SENSOR	New	100.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,820.00</b>	<b>2,100.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >