

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22006980/DVY3E2**Date:** 21/12/2022REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 30001959845

Claimant Vehicle No : SHA9348M**Insured Vehicle No :** SLH4255X

Date of Loss: 20/07/2022

Nature of Claim: TP

Claim No: 279720

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHA9348M**

Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)

Engine No: D4FDEU461711

Reg. Date: 22/12/2016 (Man. Year: 2016)

Chassis No: KMHLEB41UMHU097784

Colour: Blue

Odometer: 478615 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: West Lake 5 mm

Rear Left Side: West Lake 5 mm

Front Right Side: West Lake 5 mm

Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,550.18	8,839.02	17,711.16	66.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,970.00	1,510.00	3,460.00	69.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,520.18	10,349.02	21,171.16	67.17
Approved Total (Overridden) (S\$)		7,650.00		
(S\$)	31,520.18	7,650.00	23,870.18	75.73
+ GST 7.00/7.00% (S\$)	2,206.41	535.50	1,670.91	75.73
Nett Amount (S\$)	33,726.59	8,185.50	25,541.09	75.73

INSPECTION

Date of Assignment: 22/07/2022

Date Inspected: 25/07/2022 Inspected At:

Bifrost Auto Pte Ltd (sin Ming) (HQ)
Blk 9 Sector C, #01-42 Sin Ming Industrial Estate
Singapore 575644

Estimated Period of Repair: 7.0 days

Adjuster: BRYAN TANI**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Dec 2022)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA9348M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	2,174.90 FL	*2,174.90 FL
2	1		*BOOTLID RUBBER	Serviceable	96.50 FL	*- FL
3	2		*BOOTLID HINGE (LH/RH)	Not Necessary	569.20 FL	*- FL
4	1		*BOOTLID LOCK UPPER	Not Necessary	114.90 FL	*- FL
5	1		*BOOTLID LOCK LOWER	Not Necessary	31.70 FL	*- FL
6	1		*BOOTLID I40 EMBLEM (I40)	Necessary	67.90 FL	*67.90 FL
7	1		*BOOTLID H EMBLEM	Necessary	63.10 FL	*63.10 FL
8	1		*BOOTLID CRDI EMBLEM	Necessary	52.40 FL	*52.40 FL
9	2		*BOOTLID LAMP (LH/RH)	Not Necessary	2,262.40 FL	*- FL
10	2		*LICENSE LAMP (LH/RH)	Not Necessary	112.20 FL	*- FL
11	1		*BOOTLID TRIMBOARD	Not Necessary	343.90 FL	*- FL
12	11		*BOOTLID TRIMBOARD CLIPS	Not Necessary	11.00 FL	*- FL
13	1		*BOOTLID LOWER GARNISH CHROME (I40)	Mtg Broken	385.30 FL	*385.30 FL
14	1		*REAR BUMPER	Distorted / Dented	1,106.00 FL	*553.00 FL
15	2		*REAR BUMPER REINFORCEMENT BRACKET LH / RH	Bent	321.20 FL	*321.20 FL
16	1		*REAR BUMPER REINFORCEMENT	Cracked	428.40 FL	*428.40 FL
17	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
18	1		*REAR BUMPER BRACKET	Serviceable	35.60 FL	*- FL
19	1		*REAR BUMPER SPONGE	Torn	119.50 FL	*119.50 FL
20	1		*REAR BUMPER UNDER COVER	Distorted / Dented	228.00 FL	*228.00 FL
21	2		*REAR BUMPER REFLECTOR LAMP (I40)	Not Necessary	64.00 FL	*- FL
22	2		*TAIL LAMP (LH/RH)	Not Necessary	1,395.60 FL	*- FL
23	2		*TAIL LAMP QUARTER PANEL (LH/RH)	Not Necessary	906.00 FL	*- FL
24	1		*REAR PANEL	Repair	526.70 FL	*- FL
25	1		*REAR PANEL LOWER	Not Necessary	495.50 FL	*- FL
26	1		*REAR PANEL GARNISH	Not Necessary	57.70 FL	*- FL
27	1		*BONNET	Not Necessary	2,508.80 FL	*- FL
28	1		*BONNET RUBBER (LH)	Not Necessary	35.70 FL	*- FL
29	1		*BONNET RUBBER (RH)	Not Necessary	35.70 FL	*- FL
30	2		*BONNET HINGE (LH/RH)	Not Necessary	253.40 FL	*- FL
31	1		*BONNET LOCK	Not Necessary	142.40 FL	*- FL
32	1		*BONNET INSULATOR	Not Necessary	202.50 FL	*- FL
33	10		*BONNET INSULATOR CLIP	Not Necessary	36.80 FL	*- FL
34	1		*BONNET SEAL	Not Necessary	31.90 FL	*- FL
35	1		*RADIATOR GRILLE H EMBLEM	Necessary	129.50 FL	*129.50 FL
36	1		*RADIATOR GRILLE	Mtg Cracked	1,480.00 FL	*1,110.10 FL
37	1		*FRONT BUMPER COVER	Cracked / Bent	1,052.20 FL	*1,052.20 FL
38	1		*FRONT BUMPER SPONGE	Torn	379.20 FL	*379.20 FL
39	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	588.40 FL	*- FL
40	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	178.60 FL	*- FL
41	2		*FRONT BUMPER GRILLE (LH/RH)	Not Necessary	298.40 FL	*- FL
42	1		*FRONT BUMPER LIP	Not Necessary	152.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	89.60 FL	*- FL
44	2		*FRONT BUMPER BRACKET (LH/RH)	Not Necessary	98.40 FL	*- FL
45	2		*FRONT BUMPER GRILLE AIR DUCT (LH/RH)	Not Necessary	252.40 FL	*- FL
46	1		*HEADLAMP SUPPORT PANEL ASSY	Not Necessary	907.40 FL	*- FL
47	2		*HEADLAMP (LH/RH)	Mtg Cracked	5,552.00 FL	*2,776.00 FL
48	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	*- FL
49	1		*RADIATOR	Not Necessary	1,637.20 FL	*- FL
50	2		*RADIATOR GUARD (LH/RH)	Not Necessary	153.00 FL	*- FL
51	2		*RADIATOR BRACKET (LH/RH)	Not Necessary	26.00 FL	*- FL
52	1		*RADIATOR FAN BLADE, COWLING, MOTOR ASSY	Not Necessary	1,194.20 FL	*- FL
53	2		*HORN UNIT (LH/RH)	Not Necessary	147.60 FL	*- FL
54	1		*AIRCON CONDENSER	Not Necessary	947.80 FL	*- FL
55	2		*FRONT BUMPER RETAINER MOUNTING LH / RH	Not Necessary	152.40 FL	*- FL
56	1		*EXHAUST SILENCER (RH)	Bent	1,935.40 FL	*967.70 FL
57	1		*BOOTLID CITYCAB LOGO & TEL NO. STICKER	Necessary	39.00 FS	*39.00 FS
58	1		*REAR NO. PLATE	Not Necessary	25.00 FS	*- FS
59	1		*REAR BUMPER REVERSE SENSOR	Damaged	135.70 FS	*135.70 FS
60	1		*FRONT NUMBER PLATE	Not Necessary	25.00 FS	*- FS
61	1		*FRONT NO. PLATE TRIM COVER	Not Necessary	30.00 FS	*- FS
62	1		*COOLANT	Not Necessary	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	33,112.80	11,005.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	6,562.62	2,166.08
Total Parts (\$\$)	26,550.18	8,839.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,000.00	700.00
2	SPRAY PAINTING CHARGE	New	1,800.00	700.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE / REFIX REVERSE SENSOR	New	120.00	40.00
7	REMOVE / REFIX RADIATOR	New	90.00	0.00
8	REMOVE / REFIX AIRCON & REFILL GAS	New	130.00	0.00
9	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
Gross Labour Cost (S\$)			4,970.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >