

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22006983/DVY3Q2**Date:** 05/01/2023REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SHC3418Z **Insured Vehicle No :** SLV3186U

Date of Loss: 21/07/2022 Nature of Claim: TP Claim No: DMCF2200144H.02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC3418Z**

Make & Model: ADIVA AD1 200, 190cc 3W Engine No: G4LEKU211724

Reg. Date: 30/04/2019 (Man. Year: 2019) Chassis No: KMHC851CVKU146291

Colour: Blue Odometer: 496507 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm

Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,471.38	10,845.08	10,626.30	49.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,060.00	1,920.00	3,140.00	62.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,531.38	12,765.08	13,766.30	51.89
Approved Total (Overridden) (S\$)		11,400.00		
(S\$)	26,531.38	11,400.00	15,131.38	57.03
+ GST 8.00/8.00% (S\$)	2,122.51	912.00	1,210.51	57.03
Nett Amount (S\$)	28,653.89	12,312.00	16,341.89	57.03

INSPECTION

Date of Assignment: 22/07/2022

Date Inspected: 25/07/2022 Inspected At: 8 KAKI BUKIT AVENUE 4
#01-49 PREMIER @ KAKI BUKIT
SINGAPORE 415875
Repairer: Bifrost Auto Pte Ltd (sin Ming) (HQ)

Estimated Period of Repair: 8.0 days

Adjuster: BRYAN TANI**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 Jan 2023)	
Parts:	N/A	ADIVA AD1 200 190cc 3W (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC3418Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Repair	481.10 FL	*- FL
2	1		*FRONT BUMPER BRACKET (LH)	Not Necessary	28.00 FL	*- FL
3	1		*FRONT BUMPER RETAINER MOUNTING (LH)	Not Necessary	65.30 FL	*- FL
4	10		*FRONT BUMPER CLIPS	Not Necessary	25.00 FL	*- FL
5	1		*FRONT FENDER (LH)	Dented	490.70 FL	*490.70 FL
6	1		*FRONT FENDER APRON PANEL SIDE SUPPORT (LH)	Not Necessary	238.80 FL	*- FL
7	1		*FRONT FENDER APRON PANEL (LH)	Not Necessary	756.20 FL	*- FL
8	1		*FRONT FENDER APRON PANEL UPPER(LH)	Not Necessary	329.00 FL	*- FL
9	1		*FRONT FENDER SHIELD (LH)	Not Necessary	164.70 FL	*- FL
10	1		*FRT DOOR (LH)	Dented	1,797.20 FL	*1,797.20 FL
11	1		*FRT DOOR RUBBER	Necessary	250.00 FL	*250.00 FL
12	1		*FRONT DOOR REGULATOR (LH)	Not Necessary	750.40 FL	*- FL
13	1		*FRONT DOOR POWER MOTOR ,LH	Not Necessary	689.20 FL	*- FL
14	1		*FRONT DOOR HINGE UPPER (LH)	Not Necessary	165.76 FL	*- FL
15	1		*FRONT DOOR HINGE LOWER (LH)	Not Necessary	153.70 FL	*- FL
16	1		*FRONT DOOR CHECK (LH)	Not Necessary	72.98 FL	*- FL
17	1		*FRONT DOOR INNER LOCK (LH)	Not Necessary	385.60 FL	*- FL
18	1		*FRONT DOOR OUTER HANDLE (LH)	Not Necessary	234.80 FL	*- FL
19	1		*FRONT DOOR MIRROR ASSY (LH)	Broken	1,691.70 FL	*1,691.70 FL
20	1		*FRONT DOOR PROTECTOR (LH)	Bent	186.20 FL	*186.20 FL
21	1		*FRONT DOOR OUTER MOULDING (LH)	Not Necessary	110.10 FL	*- FL
22	1		*REAR DOOR (LH)	Dented	2,147.90 FL	*2,147.90 FL
23	1		*REAR DOOR RUBBER (LH)	Necessary	280.00 FL	*280.00 FL
24	1		*REAR DOOR OUTER MOULDING (LH)	Not Necessary	125.30 FL	*- FL
25	1		*REAR DOOR GEAR /REGULATOR (LH)	Not Necessary	367.84 FL	*- FL
26	1		*REAR DOOR POWER MOTOR (LH)	Not Necessary	256.80 FL	*- FL
27	1		*REAR DOOR HINGE UPPER(LH)	Not Necessary	173.88 FL	*- FL
28	1		*REAR DOOR HINGE LOWER (LH)	Not Necessary	170.50 FL	*- FL
29	1		*REAR DOOR CHECK (LH)	Not Necessary	85.92 FL	*- FL
30	1		*REAR DOOR PROTECTOR (LH)	Cut	166.20 FL	*166.20 FL
31	1		*ROCKER PANEL OUTER GARNISH (LH)	Bent / Mtg Broken	715.60 FL	*715.60 FL
32	1		*ROCKER PANEL STEP GARNISH (FRONT) (LH)	Not Necessary	156.50 FL	*- FL
33	1		*ROCKER PANEL STEP GARNISH (REAR) (LH)	Not Necessary	178.30 FL	*- FL
34	1		*FRONT WHEEL RIM (LH)	Distorted	1,124.20 FL	*1,124.20 FL
35	1		*FRONT WHEEL HUB ASSY (LH)	Not Necessary	678.50 FL	*- FL
36	1		*FRONT WHEEL HUB CAP	Cut	346.40 FL	*346.40 FL
37	1		*FRONT SHOCK ABSORBER (ASSY) (LH)	Not Necessary	372.50 FL	*- FL
38	1		*FRONT SHOCK ABSORBER MOUNTING (LH)	Not Necessary	372.50 FL	*- FL
39	1		*FRONT DRIVE SHAFT (LH)	Not Necessary	1,136.70 FL	*- FL
40	1		*RACK & PINION ASSY	Not Necessary	2,387.40 FL	*- FL
41	1		*STG TIE ROD	Not Necessary	125.60 FL	*- FL
42	1		*STG TIE END	Not Necessary	94.70 FL	*- FL
43	1		*STABILIZER BAR	Not Necessary	326.80 FL	*- FL
44	1		*STABILIZER BAR LINK	Not Necessary	92.10 FL	*- FL
45	1		*FRONT SUSPENSION LOWER ARM (LH)	Not Necessary	596.80 FL	*- FL
46	1		*KNUCKLE ARM (LH)	Not Necessary	663.60 FL	*- FL

Report was unsubmitted during this print-out.

1/5/23, 1:39 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FRONT FENDER ADVERTISEMENT LOGO (LH)	Necessary	100.00 FS	*100.00 FS
48	1		*EMBLEM -BLUE DRIVE (LH)	Necessary	26.60 FL	*26.60 FL
49	1		*FRONT DOOR COMFORT LOGO (LH)	Necessary	75.00 FS	*75.00 FS
50	1		*FRONT DOOR ADVERTISEMENT LOGO (LH)	Necessary	100.00 FS	*100.00 FS
51	1		*REAR DOOR ADVERTISEMENT LOGO (LH)	Necessary	100.00 FS	*100.00 FS
52	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (LH)	Necessary	80.00 FS	*80.00 FS
53	1		*FRONT TYRE (LH)	Not Necessary	216.00 FS	*- FS
54	1		*DOOR CENTRE PILLAR OUTER (LH)	Dented	3,764.90 FL	*3,764.90 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					26,671.48	13,442.60
- List Item Discount on L Items 20.00/20.00% (S\$)					5,200.10	2,597.52
Total Parts (S\$)					21,471.38	10,845.08
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,600.00	700.00
2	SPRAY PAINTING CHARGE	New	1,400.00	700.00
3	WIRING CHARGE	New	100.00	0.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	TRANSFER OF DOOR MECHANISM FRONT	New	80.00	60.00
7	RE-SET FRT POWER WINDOW SYSTEM	New	200.00	0.00
8	TRANSFER OF DOOR MECHANISM REAR	New	80.00	60.00
9	RE-SET REAR POWER WINDOW SYSTEM	New	200.00	0.00
10	FOUR WHEEL ALIGNMENT	New	120.00	60.00
11	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	400.00	150.00
12	REMOVE/REFIX STEERING RACK /WHEEL/DR SHAFT	New	150.00	0.00
13	DIAGNOSTIC & RESETTING TO ERASE FAUL CODE	New	550.00	150.00
Gross Labour Cost (S\$)			5,060.00	1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >