

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5899E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COVER, REAR BUMPER	CRACKED	485.60	485.60
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	TO REPAIR SEE LABOUR	332.70	-
1	GUARD, REAR BUMPER, CENTER	DENTED / CUT	374.50	374.50
1	SEAL, REAR BUMPER SIDE, RH	SERVICEABLE	118.30	-
1	RETAINER, REAR BUMPER SIDE, RH	SERVICEABLE	132.60	-
1	COVER, REAR BUMPER, LOWER	CUT	22.00	22.00
1	COVER, DECK TRIM, REAR	SERVICEABLE	126.70	-
1	PANEL SUB-ASSY, BODY LOWER BACK	TO REPAIR SEE LABOUR	651.00	-
1	REFLECTOR ASSY, REFLEX, RH	SERVICEABLE	39.00	-
1	LENS & BODY, REAR COMBINATION LAMP, RH (UPPER)	SERVICEABLE	339.60	-
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 RH (LOWER)	SERVICEABLE	261.00	-
1	COVER, REAR COMBINATION LAMP, RH	SERVICEABLE	69.90	-
1	PANEL SUB-ASSY, BACK DOOR	TO REPAIR SEE LABOUR	1,147.80	-
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	NOT NECESSARY	54.60	-
1	PLATE, BACK DOOR NAME, NO.1	NOT NECESSARY	54.60	-
1	ORNAMENT SUB-ASSY, BACK DOOR	NOT NECESSARY	47.90	-
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	SERVICEABLE	913.60	-
1	BOARD ASSY, BACK DOOR TRIM	SERVICEABLE	259.20	-
1	WEATHERSTRIP, BACK DOOR	SERVICEABLE	372.30	-
1	STAY ASSY, BACK DOOR, LH	SERVICEABLE	242.50	-
1	STAY ASSY, BACK DOOR, RH	SERVICEABLE	242.50	-
1	HINGE ASSY, BACK DOOR, LH	SERVICEABLE	61.00	-
1	HINGE ASSY, BACK DOOR, RH	SERVICEABLE	61.00	-
	LESS 25% DISCOUNT		-1,602.48	-220.53
			4,807.42	661.57
	SPECIAL NETT ITEMS			
1	REAR BUMPER SIDE CLIP (SN)	NECESSARY	60.00	60.00
1	BOOT STICKER TRANSCAB (SN)	NOT NECESSARY	100.00	-

Report Ref No. CS/AGI22006991/Kvy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	BOOT STICKER TEL NO (SN)	NOT NECESSARY	100.00	-
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	85.00	-
1	REAR BUMPER RETAINER CLIP (SN)	NOT NECESSARY	75.00	-
			1,120.00	60.00
	<u>LABOUR</u>			
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.	NOT NECESSARY	240.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REINFORCEMENT SUB-ASSY, REAR BUMPER, PANEL SUB-ASSY, BODY LOWER BACK AND PANEL SUB-ASSY, BACK DOOR.		1,600.00	200.00
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,600.00	220.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	50.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	10.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO REMOVE AND REFIT OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			5,100.00	480.00
	GRAND TOTAL		11,027.42	1,201.57

RECOMMENDED COST OF REPAIRS			1,201.58
-----------------------------	--	--	----------

Report Ref No. CS/AGI22006991/Kvy3m4

KONG SENG CHEONG

Licensed Appraiser