



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 35A

| Qty | Description of Parts   | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|----------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>   |                      |                           |                   |
| 1   | REAR BUMPER (CONSISTENT)   | TO REPAIR SEE LABOUR | 470.80                    | -                 |
| 1   | REAR BUMPER REINFORCEMENT (CONSISTENT)   | SERVICEABLE          | 294.80                    | -                 |
| 1   | REAR REINFORCEMENT TOP BRACKET (CONSISTENT)  | NECESSARY            | 15.00                     | 15.00             |
| 1   | REAR REINFORCEMENT LOWER BRACKET (CONSISTENT)  | NECESSARY            | 10.00                     | 10.00             |
| 2   | REAR BUMPER SIDE BRACKET @\$28.00 (CONSISTENT)   | NECESSARY            | 56.00                     | 56.00             |
| 1   | REAR BOOT WEATHER STRIP (CONSISTENT)   | DENTED               | 108.30                    | 108.30            |
| 2   | REAR REVERSE SENSOR @\$169.20 (CONSISTENT)   | SHORTED              | 338.40                    | 250.00            |
| 2   | REAR LICENCE PLATE LAMP @\$32.30 (CONSISTENT)  | SERVICEABLE          | 64.60                     | -                 |
| 2   | REAR TAILLAMPS LEFT & RIGHT @\$590.80 (CONSISTENT)   | CRACKED              | 1,181.60                  | 1,181.60          |
| 2   | REAR BOTTOM LIGHT REFLECTOR @\$50.20 (CONSISTENT)  | SERVICEABLE          | 100.40                    | -                 |
| 1   | REAR BUMPER BOTTOM CENTER BRAKE FOG LAMP (CONSISTENT)  | SERVICEABLE          | 201.50                    | -                 |
| 1   | REAR BUMPER LOWER PANEL (CONSISTENT)   | SCRATCHED            | 340.60                    | 340.60            |
|     | LESS 20% DISCOUNT  |                      | -                         | -392.30           |
|     |  |                      | 3,182.00                  | 1,569.20          |
|     | <b><u>LABOUR</u></b>   |                      |                           |                   |
|     | LABOUR (GENERAL)   |                      | 550.00                    | 200.00            |
|     | -SUPPLY LABOUR TO REMOVE AND REPLACE ITEM(S) LISTED. INCLUSIVE OF THE REPAIR OF REAR BUMPER. |                      |                           |                   |
|     | LABOUR (RE-SPRAYING WORKS)   |                      | 450.00                    | 200.00            |
|     | REAR BUMPER.   |                      |                           |                   |
|     | CAR WRAP   |                      | 600.00                    | 400.00            |
|     | REAR BUMPER.   |                      |                           |                   |
|     |  |                      | 1,600.00                  | 800.00            |
|     | <b>GRAND TOTAL</b>   |                      | <b>4,782.00</b>           | <b>2,369.20</b>   |

Report Ref No. CS/ASM22006992/Vqy3m4



|   |  |  |                 |
|---|--|--|-----------------|
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS<br/>(TO ITS PRE-ACCIDENT CONDITION)</b> |  |  | <b>1,900.00</b> |
|---|--|--|-----------------|

Report Ref No. CS/ASM22006992/Vqy3m4

**THEVAN THOMAS KARTHIKESAVAN**

**Asst. Automotive Assessor**

**ADRIAN LING WAI PING**

**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**