



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: HO WINNIE			Ref: CS/ASM22006992/Vqy3m4 Date: 31/08/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHA 9348M	Veh. Inspected	SKR 35A	
Policy No.	VFX/P2419140	Coverage (\$)	0.00	
Claim No.	S2M04772	Excess (\$)	0.00	
Assign From	HO WINNIE	Assign Date	22/07/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HYUNDAI AVANTE	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	KMHLN41ETNU184737	Colour	WHITE	
Odometer	9245 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	206/60 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	206/60 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	206/60 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	206/60 R16	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	20/07/2022	Inspection Date	25/07/2022	
Survey held at	M-TECH MOTOR SERVICES BLK 9005 TAMPINES STREET 93 #01-252, TAMPINES INDUSTRIAL PARK A SINGAPORE 528839			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>4 Working Days</b>	