

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22006996/APA3Q2**Date:** 27/12/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SKG1527Z**Insured Vehicle No :** GBC3567Y

Date of Loss: 12/07/2022

Nature of Claim: TP

Claim No: 6760833022SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKG1527Z**

Make & Model: BMW 530I, 2.0 LED NAV HUD MSPT (A)

Engine No: 17425246B48B20B

Reg. Date: 21/03/2018 (Man. Year: 2018)

Chassis No: WBAJA52060B177522

Colour: Silver

Odometer: 50203 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/35 R20

Rear Tyre Size: 255/35 R20

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,011.00	4,644.81	3,366.19	42.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	750.00	230.00	520.00	69.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	8,761.00	4,874.81	3,886.19	44.36
+ Loss of Use (2.0 x S\$120.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,122.26		
Global Sum Settlement (S\$)		5,000.00		

INSPECTION

Date of Assignment: 19/07/2022

Date Inspected: 19/07/2022 Inspected At:

YSK Auto Workshop (HQ)
1 Kaki Bukit Avenue 6 @ AutoBay, #01-71
Singapore 417883

Estimated Period of Repair: 1.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	1,800.00 FS	*- FS
2	1		*FRONT BUMPER SENSOR	Not Necessary	285.00 F	*- FL
3	1		*FRONT BUMPER STICKER WRAP	Not Necessary	400.00 FS	*- FS
4	1		*HEADLAMP LH	Cut	4,960.90 F	*4,960.90 FL
5	1		*HEADLAMP CONTROL MODULE	Not Necessary	285.10 F	*- FL
6	1		*HEADLAMP PROTECTIVE FILM	Necessary	280.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,011.00	5,140.90
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	496.09
Total Parts (\$)	8,011.00	4,644.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	200.00
2	SPRAY PAINTING	New	300.00	0.00
3	WIRING	New	50.00	30.00
Gross Labour Cost (\$)			750.00	230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >