

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22006997/ECY3Q2**Date:** 17/10/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSNA00012282101

**Claimant Vehicle
No :** SMV5541C**Insured Vehicle
No :** SLR9430X

Date of Loss: 19/07/2022

Nature of Claim: TP

Claim
No: SNM22D205086/C02/TANKL**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMV5541C**

Make & Model: BMW 520I, 2.0 (A)

Engine No: B2040493N20B20B

Reg. Date: 26/07/2013 (Man. Year: 2013)

Chassis No: WBAXG12070D291678

Colour: Silver

Odometer: 201545 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R16

Rear Tyre Size: 215/55 R16

Front Left Side: Michelin 4 mm

Rear Left Side: Michelin 4 mm

Front Right Side: Michelin 4 mm

Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,591.00	2,316.50	2,274.50	49.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,240.00	790.00	1,450.00	64.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,831.00	3,106.50	3,724.50	54.52
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	6,831.00	2,500.00	4,331.00	63.40
+ GST 7.00/7.00% (S\$)	478.17	175.00	303.17	63.40
Nett Amount (S\$)	7,309.17	2,675.00	4,634.17	63.40

INSPECTION

Date of Assignment: 22/07/2022

Date Inspected: 25/07/2022 Inspected At:

39 WOODLANDS CLOSE #01-34/35

WOODLANDS @ MEGA

Repairer: Af & Cars Pte Ltd (HQ)

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Oct 2022)
Parts:	143	BMW 520I 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMV5541C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	1,580.00 FL	*1,580.00 FL
2	1		*REAR BUMPER TOWING COVER	Crushed	50.00 FL	*50.00 FL
3	1		*REAR BUMPER SKID PLATE	Crushed	150.00 FL	*150.00 FL
4	1		*REAR BUMPER BRACKET	Crushed	210.00 FL	*210.00 FL
5	2		*REAR BUMPER MOUNTING RH/LH	Not Necessary	310.00 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENTS	Not Necessary	800.00 FL	*- FL
7	2		*REAR BUMPER COVER REFLECTOR LH/RH	Not Necessary	90.00 FL	*- FL
8	1		*REAR END PANEL	Not Necessary	890.00 FL	*- FL
9	2		*SET REAR BUMPER REVERSE SENSOR	Shorted	650.00 FS	*396.00 FS
10	1		*SET REAR BUMPER CLIPS	Necessary	65.00 FS	*30.00 FS
					Sub Total (\$\$)	
					4,795.00	2,416.00
					- List Item Discount on L Items 5.00/5.00% (\$\$)	
					204.00	99.50
					Total Parts (\$\$)	
					4,591.00	2,316.50

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX PARKING SENSOR ASSY AND RETIFY FOR PROPER FUNCTIONING	New	160.00	30.00
2	TO DIAGNOSE ,REPLACE /OR REPAIR ON THE FRONT PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING AND WHERE CONSISTENT TO THE ACCIDENT	New	200.00	80.00
3	TO RESPRAY ,PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION AND WHERE CONSISTENT TO THE ACCIDENT	New	800.00	400.00
4	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE DAMAGED BODYPARTS ,REPAIR ,ALIGN BODY STRUCTURE & DAMAGED AND WHERE CONSISTENT TO THE ACCIDENT	New	800.00	250.00
5	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED & REPLACED PANEL AND WHERE CONSISTENT TO THE ACCIDENT	New	280.00	30.00
Gross Labour Cost (\$)			2,240.00	790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >