# **AUTOMAX SURVEY**

Blk 110 Bedok Reservoir Road, #07-280, Singapore 470110 Email: automaxsurvey@gmail.com Mobile: 9855 6879

Registration No. 53110062J

Billing To:

Lee Yong Nee

Invoice no.:

TP21020037

c/o Hup Ley Huat Motor Spray Painting Services

Date:

15 JUN 2021

Blk 1, #01-35

Kaki Bukit Ave 6 Singapore 417883

Vehicle no: SMR3153Z

Model: TOYOTA HARRIER

ITEM	DESCRIPTION		AMOUNT
1	Date of Inspection : 03 FEB 2021 Copies of the inspection / survey report Correspondence, postages and etc.	\$	750.00
2	Photography Services Develop photographs Storage of digital photographs		
3	To submit report by hand.		
4	Charges on photocopies, posting, faxes and others incidental works entrusted.		
5	Transportation Charges		
6	Reinspection Charges		
	TOTAL	: \$	750.00

Notes:

N1A XAII cheque payment should be "crossed" and made payable to "Automax Survey".

Please contact us if there are further enquiries on the invoice.

Official Stamp

# **AUTOMAX SURVEY**

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110 Mobile : 9855 6879 Email : automaxsurvey@gmail.com Registration No. 53110062J

Report Ref: TP21020037

Date:

15 JUN 2021

Lee Yong Nee c/o Hup Ley Huat Motor Spray Painting Services Blk 1, #01- 35 Kaki Bukit Ave 6 Singapore 417883

THIRD PARTY SURVEY
ACCIDENT OCCCURED ON 01 FEB 2021

Workshop Name and Address

Hup Ley Huat Motor Spray Painting Services

Blk 1, #01- 35 Kaki Bukit Ave 6 Singapore 417883

Mada

As per your instruction dated

03 FEB 2021

with regard to the above matter.

m.

We have carried out a physicial inspection on the said

SMR3153Z

D-I---

We enclosed herewith our report and findings as follows:

Cino

## 1. VEHICLE PARTICULARS

Registration No: SMR3153Z Engine No: 8ARZ091401

Model: TOYOTA HARRIER Mileage: 022 821 km

Year / Capacity: DEC 2019 / 1986 cc Colour: MetallicPurple

Chassis No : ASU600004745

### 2. TYRES CONDITION

	Size	iviade	Balance	Rim
FRONT O/S:	235/55/R18	Bridgestone	9.00 mm	Sport
REAR O/S:	235/55/R18	Bridgestone	9.00 mm	Sport
FRONT N/S:	235/55/R18	Bridgestone	9.00 mm	Sport
REAR N/S:	235/55/R18	Bridgestone	9.00 mm	Sport



Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110 Mobile : 9855 6879 Email : automaxsurvey@gmail.com Registration No. 53110062J

#### 3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the <u>side</u> portion(s). For more detail of the damages, please see photograph attached.

- 4. Estimated normal period of repair: 05 working days to complete
- In accordance to your instruction, we have <u>Not Authorised</u> repair to the vehicle and the survey done on a <u>"Without Prejudice"</u> basis. We hope that this report will be of assistance to you in dealing with the matter.
- Should you discover any discrepancy in the report, please kindly notify us <u>within 1 week</u>, or the report will be treated as correct.

### Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comprarison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number: SMR3153Z

# **SPARE PARTS**

QTY	PARTS DESCRIPTION	MODERN DO SALVANINA MARIA DA TIGO ANTONIO	CONDITION	Workshop Estimation		Our Revised Estimation	
	L				(S\$)		(S\$)
	List Items						
1 pc	Bonnet		bent	\$	952.80	\$	952.80
1 pc	Front bumper side retainer		deformed	\$	65.00	\$	65.00
1 pc	Front burner side sponge		distorted	\$	102.00	\$	102.00
1 pc	Front bumper sub frame upper		distorted	\$	250.00	\$	250.00
1 pc	Front fender		bent	\$	781.45	\$	781.45
1 pc	Front fender side panel protector		distorted	\$	105.00	\$	105.00
1 pc	Front fender splash shield		bent	\$	252.80	\$	252.80
8 pcs	Front fender splash shield clips		necessary	\$	80.00	\$	80.00
1 pc	Front fender inner panel		distorted	\$	525.00	\$	525.00
1 pc	Headlamp assy		dent/distorted	\$	1,980.00	\$	1,980.00
1 pc	Front door assy		dent/distorted	\$	1,345.00	\$	1,345.00
2 pcs	Front door hinge		bent/distorted	\$	163.00	\$	163.00
1 pc	Front door checker		bent/distorted	\$	105.00	\$	105.00
2 pcs	Front door stopper		wraped/deformed	\$	92.00	\$	92.00
1 pc	Front door weatherstrip		wraped/deformed	\$	182.10	\$	182.10
1 pc	Front door protector		grazed/deformed	\$	174.40	\$	174.40
1 pc	Front door protector chrome		grazed/deformed	\$	132.10	\$	132.10
1 pc	Front door window frame black sticker		wraped/deformed	\$	132.10	\$	132.10
1 pc	Front door fame moulding		deformed	\$	78.70	\$	78.70
1 pc	Side mirror housing assy		grazed/deformed	\$	1,579.80	\$	1,579.80
1 pc	Front door pillar iner garnish		deformed	\$	160.00	\$	160.00
			Dorto Cub Total	Φ.	0.000.05	•	0.000.05
		Discount	Parts Sub-Total	\$	9,238.25	\$	9,238.25
		Discount	25.00%	\$	2,309.56	\$	2,309.56
				\$	6,928.69	\$	6,928.69

Vehicle Number : SMR3153Z


# SPARE PARTS


QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)		Our Revised Estimation (S\$)	
	Special Nett Items					
1 pc	Door window glass solar flim	necessary	\$	300.00	\$	300.00
1 pc	Sound clad	deformed	\$	250.00	\$	250.00
1 pc	Rim Assembly	damaged	\$	650.00	\$	650.00
1 pc	Tyre	grazed/distorted	\$	450.00	\$	400.00
~		Special Nett Sub-Total	\$	1,650.00	\$	1,600.00
		Spare Parts Total	\$	8,578.69	\$	8,528.69

# **LABOUR COST**


S/No	JOB DESCRIPTIONS		Workshop Estimation (S\$)		Our Revised Estimation (S\$)	
	Spare PartsTotal c/f	\$	8,578.69	\$	8,528.69	
1	To tuff coat affected areas	\$	180.00	\$	150.00	
2	To remove replace interior upholstery	\$	180.00	\$	150.00	
3	To respray affected areas	\$	1,200.00	\$	1,000.00	
4	To renew damaged parts, straighten and repair door center pillar (inner), rear fender inner panel and aligned all parts.	\$	1,600.00	\$	1,400.00	
5	To remove & replace door assy	\$	180.00	\$	150.00	
6	To check and adjust computer wheel alignment	\$	180.00	\$	150.00	
7	To apply paint coating protection	\$	1,200.00	\$	1,200.00	
8	To supply & install wrap on replacement parts	\$	1,800.00	\$	1,800.00	
	Total	\$	15,098.69	\$	14,528.69	
	The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of :	\$	12,150.00			


Fong Kok Heng Qualified Appraiser


































MA









10,

PNO

