



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMY 6316P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	BUCKLED	536.23	536.23
1	REAR BUMPER RH REFLECTOR	SCRATCHED	78.00	78.00
1	SET REAR BUMPER REVERSE SENSOR	SHORTED	509.10	509.10
1	REAR BUMPER RH TOW COVER	DENTED	45.30	45.30
1	REAR BUMPER INNER RH SIDE BRACKET	SERVICEABLE	156.10	-
2	REAR BUMPER SIDE RETAINER	SERVICEABLE	130.60	-
1	SET REAR BUMPER CLIPS	NECESSARY	40.00	40.00
1	REAR BUMPER INNER FOAM	SERVICEABLE	110.20	-
1	REAR BUMPER INNER REINFORCEMENT	BENT	397.10	397.10
1	RH TAILLAMP	SERVICEABLE	818.10	-
1	REAR BOOT TOP TOYOTA LOGO	NECESSARY	65.10	65.10
1	REAR BOOT LH COROLLA EMBLEM	NECESSARY	44.20	44.20
1	REAR BOOT LH ALTIS EMBLEM	NECESSARY	57.10	57.10
	LESS 25% DISCOUNT		-746.78	-443.03
			2,240.35	1,329.10
	<b><u>LABOUR</u></b>			
	LABOUR CHARGES FOR REMOVE/REFIT, CUTTING/WELDING AND REPLACEMENT OF DAMAGES.		600.00	400.00
	TO PUTTY AND SPRAY PAINTINGS CHARGES.		800.00	400.00
	TO CHECK WIRINGS AND LIGHTINGS.		50.00	15.00
	TO REMOVE, REFIT & RESET REVERSES SENSORS.		80.00	50.00
	TO SUPPLY AND APPLY ANTI RUST TREATMENT.	NOT NECESSARY	80.00	-
			1,610.00	865.00
	<b>GRAND TOTAL</b>		<b>3,850.35</b>	<b>2,194.10</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>2,194.10</b>

Report Ref No. CS/SMR22006999/Kqy3m4

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.