



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGU 1000A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER REAR XC (SN)	CRUSHED	3,334.80	3,001.32
1	BUMPER SPOILER REAR (SN)	CRUSHED	1,154.90	1,039.41
1	BUMPER BRACKET LHR X (SN)	NOT NECESSARY	96.20	-
1	BUMPER BRACKET RHR X (SN)	NOT NECESSARY	96.20	-
1	BUMPER REFLECTOR LH (SN)	CRACKED	95.50	85.95
1	BUMPER REFLECTOR RH (SN)	NOT NECESSARY	95.50	-
1	PROTECTING PLATE REA (SN)	CRUSHED	780.10	702.09
1	ABSORBER BUMPER LH X (SN)	NOT NECESSARY	143.20	-
1	ABSORBER BUMPER RH X (SN)	NOT NECESSARY	143.20	-
1	TOW COVER REAR XC90 (SN)	NOT NECESSARY	89.80	-
10	SCREW M05x25 (SN)	NECESSARY	48.00	43.20
10	NUT (SN)	NECESSARY	47.00	42.30
10	SIX POINT SCREW M05X (SN)	NECESSARY	48.00	43.20
1	PARK HOLDER CTR LH X (SN)	NECESSARY	47.90	43.11
1	PARK HOLDER CTR RH X (SN)	NECESSARY	47.90	43.11
1	BUMPER RAIL REAR XC9 (SN)	NOT NECESSARY	1,651.20	-
10	BLIND RIVET 4.0*21 P (SN)	NECESSARY	50.00	45.00
10	BUMPER CLIP 8x8,5 (SN)	NECESSARY	82.00	73.80
1	END PIPE LH T5 T6 MO (SN)	BENT	246.70	222.03
1	END PIPE RH T5 MOM X (SN)	BENT	246.70	222.03
1	EXHAUST CLAMP 65mm S (SN)	NECESSARY	180.00	162.00
1	SILENCER REAR T5 XC9 (SN)	BENT	1,166.80	1,050.12
1	END PIPE RIM KIT T5 (SN)	NOT NECESSARY	585.90	-
2	END PIPE CHROME T5 X (SN)	CUT (1PIECE ONLY)	403.00	181.35
1	BUMPER INSTALLING MT (SN)	NECESSARY	101.40	91.26
1	PLASTIC ADHESIVE WUR (SN)	NECESSARY	70.00	63.00
1	EMBLEM 'VOLVO' REAR (SN)	NECESSARY	121.80	109.62
1	EMBLEM 'XC 90' XC90 (SN)	NECESSARY	138.40	124.56
1	EMBLEM 'T5' XC60 S80 (SN)	NECESSARY	117.00	105.30

Report Ref No. CS/SMR22007001/Evy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	EMBLEM 'AWD' XC90 16 (SN) <u>LABOUR</u> TO REPLACE REAR BUMPER,REAR LOWER SPOILER,REAR SKDI PLATE ETC. TO PUTTY SPRAY PAINT ON REAR BUMPER,REAR LOWER SPOILER, REAR BOOT LID,ETC. TO REPLACE REAR EXHUST. TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.	NECESSARY	112.30	101.07
			11,541.40	7,594.83
			2,550.00	1,275.00
			3,000.00	2,250.00
			850.00	850.00
			555.00	555.00
		6,955.00	4,930.00	
GRAND TOTAL			18,496.40	12,524.83
RECOMMENDED COST OF REPAIRS				12,524.83

Report Ref No. CS/SMR22007001/Evy3m4

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.