Blk 495-E Tampines Street 43, #04-368 Singapore 524495 Tel: 97859520

Reg.No.: 53436440C Insurance Loss Adjuster Licensed Appraiser

(Member Of Singapore Automobile Appraisers Assocation)

AUTOMOBILE INSPEC	HO	N	REP	ORT
--------------------------	----	---	-----	-----

m/s

KST Auto Rental Pte Ltd

Block 3021-A Ubi Road 1, #01-42

Singapore 408715.

Date:

24/6/2022

Our Ref:

TP/2022/00605

Claim No:

Policy No:

Date of Accident: Survey Held At : 9/5/2022

Kim Seng Teck Motor Works

Blk 3020A Ubi Road 1 #01-36

Singapore 408715.

Date of Inspection: 9/5/2022

As Requested By: Miss Lee

On: 9/5/2022

PARTICULARS OF VEHICLE

Reg No:

GBH4016M

Make/Model:

Toyota Dyna Lorry

Year:

16/5/2018

Engine No:

1KD2795890

Chassis No:

JTFAT35Y20K210252

Colour:

White Yes

Mileage: Aircon:

281364 Km

Yes

Engine Cap:

Radio/Cassette: Yes

2982 cc

Seat Belt: Rims:

Standard

VEHICLE CONDITION (Static Test Only)

Good

Brakes:

Serviceable

Handbrakes:

Serviceable

Steering:

Serviceable

General Body Works:

TYRE CONDITIONS

Front O/S:

Rear O/S:

5\5

Make: Travia Van \ Yokohama

Front N/S:

Rear N/S:

5\5

Size: 195R15 \ 155R12

(Remaining Estimated Life Of Tyre in num)

GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained an impact on its rear portion resulting in the rear composite container bent/distorted; container rear doors, rear chassis, dhollandia hydraulic power gate, hydraulic power arms, cross member safety bumper assy, n/s taillamp panel bent dented; n/s taillamp broken. (see attached schedule for other damages)

ADJUSTMENT AND RECOMMENDATION COST OF REPAIR

Repairer's Estimate:

\$19,148.01

Revised Amount:

\$15,686.84

Less Excess:

N.A

Nett Total:

\$15,686.84

Estimated Period Required For Repair:

Nine

Days

Survey was conducted in accordance to your instructions. We have / have not authorised repairs. photos were taken at the time of inspection and attched.

Remarks:

The Survey was conducted strictly without prejudice.

We had conducted a re-inspection of this vehicle after repair.

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

QTY	DESCRIPTION OF PARTS AND LABOUR	CONDITION	REPAIRER EST	OUR REVISED	
			(\$)	(\$)	
	TO SUPPLY				
рс	n/s taillamp	broken	235.78	sna 235.78	
рс	n/s tailamp panel	bent (repair)	172.25	1 -	
рс	front cabin back frame	bent (repair)	589.32	2:	
			997.35	235.7	
	Less 25%		249.34		
			748.01	176.8	
рс	rear number plate	bent	NH 20.00	20.0	
	Total Spare Parts		768.01	196.8	
	LABOUR CHARGE				
	To jack out, straighten and knock n/s taillamp panel, rear				
	chassis, front cabin back vetical frame, carrier platform				
	panel and renew recommended parts.		1,000.00	600 800.0	
	To re-write company logo and advertisement wording				
	on affected panel including supply of materials.		900.00	600.0	
	To rustproofing on affected areas.		1 200.00	100.0	
	To check wiring and lighting after repairs.		80.00	40.0	
	To dismantle damaged power gate, hydraulic power arm,				
	cross member safety bumper, hydraulic cable, control			1	
	panel unit. To supply and install one 750 kg power tail				
	gate, power hydraulic power arm, control unit and				
	cross member safety bumper including labour and			(100)	
	LTA inspection.		9,750.0	6500 8,450.0	
	To supply and renew aluminium chq plate on deck all			0 (00) 1,498.1	
	round.		1,650.0	0 (000 1,498.0	

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

Veh.No : QTY	DESCRIPTION OF PARTS AND LABOUR	CONDITION	REPAIRER EST (\$)	OUR REVISED (\$)
	To dismantle damaged rear composite container, to supply and renew one 10 ft composite container with two sliding door, 4 side interior plywood, 1 row tightening bar, 4 pc roof top stainless steel round bar, led lights, horn (including labour and LTA inspection) Total Labour Charge GRAND TOTAL		4,800.00 18,380.00 19,148.01	4,100.00 15,490.00 15,686.84
Note	The repairer had agreed to undertake the repair base on our recommendation to reinstate this vehicle to its pre-accident condition.	End of Reports		
				13016.83

TNECNIV SERVICES

Vincent Ng Seow Gim

Blk 495-E Tampines Street 43, #04-368 Singapore 524495 Tel: 97859520

To:

KST Auto Rental Pte Ltd

Date: 24/6/2022

Block 3021-A Ubi Road 1, #01-42

Singapore 408715.

Invoice No: TP/2022/00605

PARTICULARS		AMOUNT		
RE:	GBH4016M	_		
	SURVEY FEE	: \$	\$	887.00
	PHOTOGRAPHS	: \$		
	TRANSPORT	: \$		
	RESURVEY	: \$		

For TNECNIV SERVICES

-anmany

E.&O.E.

LICENSED APPRAISER

KIM SENG TECK MOTOR WORKS

Blk 3021 A Ubi Road 1 #01-42

Singapore 408715

Tel No.: 6741 5520 / 6741 1339 Fax No.: 6741 5808 E-Mail: kimsengteck_motorworks@yahoo.com.sg

Website: kstteam@singnet.com.sg

Tax Reg. No.: M9-0002075-E Buss. Reg. No.: 27157400/C

KST AUTO RENTAL PTE LTD Blk 3021 A # 01 - 42 Ubi Road 1 408715

Attention: Motor Claim Department

Contact: 6741 5520 Fax No.: 67415808

Tax Invoice: TP200820

Date: 29/06/2022

Vehicle Num.: GBH 4016M Make/Model: Toyota Dyna JTFAT35Y-16 / 05 / 201 Chassis/Eng#: JTFAT35Y20K210252/1KD2795890

Accident Date: 09/05/2022

Claim No.:

Reference:

Policy No.: C220000348

Amount S\$ Unit Price S/N Quantity Particular LIST ITEMS : 15,686.84 The repair as per surveyor recommended 1. 1 15,686.84 List TotalS\$:

E. & O.E.

Total S\$:

15,686.84

GST @ 7% S\$:

1,098.08

Amount Due S\$:

16,784.92



for KIM SENG TECK MOTOR WORKS