

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 4016M

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|-------------------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | N/S TAILLAMP | BROKEN | 235.78 | 235.78 |
| 1 | N/S TAILLAMP PANEL | TO REPAIR SEE LABOUR | 172.25 | - |
| 1 | FRONT CABIN BACK FRAME | TO REPAIR SEE LABOUR | 589.32 | - |
| | LESS 25% DISCOUNT | | -249.34 | -58.94 |
| | | | 748.01 | 176.84 |
| | SPECIAL NETT ITEMS | | | |
| 1 | REAR NUMBER PLATE (SN) | NOT CHANGED | 20.00 | - |
| | | | 20.00 | - |
| | <u>LABOUR</u> | | | |
| | TO JACK OUT, STRAIGHTEN AND KNOCK N/S TAILLAMP PANEL, REAR CHASSIS, FRONT CABIN BACK VETICAL FRAME, CARRIER PLATFORM PANEL AND RENEW RECOMMENDED PARTS. INCLUSIVE OF THE REPAIR OF N/S TAILLAMP PANEL AND FRONT CABIN BACK FRAME. | | 1,000.00 | 600.00 |
| | TO RE-WRITE COMPANY LOGO AND ADVERTISEMENT WORDING ON AFFECTED PANEL INCLUDING SUPPLY OF MATERIALS. | | 900.00 | 600.00 |
| | TO RUSTPROOFING ON AFFECTED AREAS. | NOT NECESSARY | 200.00 | - |
| | TO CHECK WIRING AND LIGHTING AFTER REPAIRS. | | 80.00 | 40.00 |
| | TO DISMANTLE DAMAGED POWER GATE, HYDRAULIC POWER ARM, CROSS MEMBER SAFETY BUMPER, HYDRAULIC CABLE, CONTROL PANEL UNIT. TO SUPPLY AND INSTALL ONE 750 KG POWER TAIL GATE, POWER HYDRAULIC POWER ARM, CONTROL UNIT AND CROSS MEMBER SAFETY BUMPER INCLUDING LABOUR AND LTA INSPECTION. | | 9,750.00 | 6,500.00 |
| | TO SUPPLY AND RENEW ALUMINIUM CHQ PLATE ON DECK ALL ROUND. | | 1,650.00 | 1,000.00 |



RECOMMENDED COST OF REPAIRS

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

13,016.84

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|-----------|-------------------------------|-------------------|
| | TO DISMANTLE DAMAGED REAR COMPOSITE CONTAINER, TO SUPPLY AND RENEW ONE 10 FT COMPOSITE CONTAINER WITH TWO SLIDING DOOR, 4 SIDE INTERIOR PLYWOOD, 1 ROW TIGHTENING BAR, 4 PC ROOF TOP STAINLESS STEEL ROUND BAR, LED LIGHTS, HORN (INCLUDING LABOUR AND LTA INSPECTION). | | 4,800.00 | 4,100.00 |
| | | | 18,380.00 | 12,840.00 |
| | GRAND TOTAL | | 19,148.01 | 13,016.84 |

Report Ref No. CS3/SMO22004488/Uqy3e2-1

CHUA KANG SENG

Licensed Appraiser