

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122007011/EQY3Q2**Date:** 14/09/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SBS6327U**Insured Vehicle No :** GX4251G

Date of Loss: 21/07/2022

Nature of Claim:

TP

Claim No: CDMCG22001446

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SBS6327U**

Make & Model: MERCEDES-BENZ CITARO O530, 6.4 D (A)

Engine No: 90292600943163

Reg. Date: 01/11/2012 (Man. Year: 2012)

Chassis No: WEB62808323123807

Colour: Multi-colour

Odometer: 553653 km

Engine Capacity: 6374 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size: 295/80 R22.5

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	856.63	770.97	85.66	10.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,580.00	1,650.00	930.00	36.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,436.63	2,420.97	1,015.66	29.55
+ GST 7.00/7.00% (S\$)	240.56	169.47	71.09	29.55
Nett Amount (S\$)	3,677.19	2,590.44	1,086.75	29.55

INSPECTION

Date of Assignment: 22/07/2022

Date Inspected: 22/07/2022

Inspected At:

Tower Transit Singapore Pte Ltd (HQ)

21 Bulim Drive, Bulim Bus Depot

Singapore 648170

Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

DIFFERENT 1 CENTS-FINALISE CONFIRM AMOUNT:\$2,420.96

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 12 Sep 2022)	
Parts:	N/A	MERCEDES-BENZ CITARO O530 6.4 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBS6327U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NS GLASS QUARTER	Broken	808.63 F	*808.63 FL
2	2		*SIKAFLEX BLACK	Necessary	48.00 F	*48.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$)					856.63	856.63
- List Item Discount on L Items 0.00/10.00% (\$)					0.00	85.66
Total Parts (\$)					856.63	770.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE: ITEM 1-2	New	650.00	650.00
2	TO REMOVE & INSTALL PARTS AND TO PERFORM REPAIR WORKS : NSF CORNER BUMPER	New	650.00	300.00
3	SPRAY PAINTING: NSF CORNER BUMPER WITH 3 COLORS	New	1,280.00	700.00
Gross Labour Cost (\$)			2,580.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >