



Your Ref: 2022 - 18

Date: 01<sup>st</sup> July 2022

Our Ref: CS1/SCD22007013/Eqy3e2

**M/s Singapore Civil Defence Force (MHA05)**

91 Ubi Ave 4

Singapore 408827

(The Motor Claims Department)

Attn: Ralf Tay Gim Chye

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLS 2665B**

**INSURED VEHICLE: QX 1504D**

**ACCIDENT DATE: 09/03/2022**

We thank you for your instruction on 19/07/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLS 2665B from M/s Republic Auto Pte Ltd.
- b) Survey report by MSIG Insurance (Singapore) Pte Ltd with colour photographs.
- c) Final Repair Bill of SLS 2665B from M/s Republic Auto Pte Ltd.
- d) Singapore Accident Statement and Police Report of Vehicles SLS 2665B.
- e) Colour damaged vehicle photographs of SLS 2665B.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLS 2665B
Make & Model	: KIA Cerato K3 1.6A Sunroof
Chassis Number	: KNAFZ411MJ5744848
Year of Registration	: 2017
Engine Capacity	: 1591 cc

- 2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## OPINION ON REPAIR COST FOR VEHICLE NO. SLS 2665B

Qty	Description of Parts	Condition	Recommended (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>		
1	SUNDRIES (SN)	NECESSARY	20.00
1	LAMP ASSY-HEAD, LH (SN)	CRACKED	2,209.00
1	PANEL-FENDER, LH (SN)	BUCKLED	482.00
1	COVER-FR BUMPER (SN)	TORN	633.00
1	ORNAMENT-KIA NO.115 (SN)	NECESSARY	32.00
1	BRACKET-FR BUMPER SIDE MTG, LH (SN)	CRACKED	13.00
1	WHEEL ASSY-ALUMINIUM (SN)	GRAZED / CUT	833.00
1	NEW K3 SNOW WHITE PEARL SWP (SN)	CRACKED	1,177.00
			5,399.00
	<b><u>LABOUR</u></b>		
	RENEW FRONT BUMPER, BODY KIT & LH FRONT FENDER.		1,280.00
	SPRAY PAINT FRONT BUMPER BODY KIT & LH FRONT FENDER.		1,375.00
	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM.		20.00
	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM.		280.00
	SUPPLY BODY PANEL SEALANT.		40.00
	RENEW LH FRONT SPORT RIM & TRANSFER TYRE. SUPPLY LABOUR FOR ONE TYRE AND RIM.		50.00
			3,045.00
<b>GRAND TOTAL</b>			<b>8,444.00</b>

<b>RECOMMENDED COST OF REPAIRS</b>	<b>8,444.00</b>
------------------------------------	-----------------

Report Ref No. CS1/SCD22007013/Eqy3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.