

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22007024/ACM4**Date:** 23/11/2022REFERENCE

Insured/Claimant:	WEE LYE KIM	Policy No:	1900159593-02	
Date of Loss:	18/07/2022	Nature of Claim:	OD	Claim No: 0168619911SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCH8823L		Engine No:	CHZC35553
Make & Model:	AUDI Q2, 999cc 1.0 TFSI S TRONIC (A)		Chassis No:	WAUZZZGA6LA000984
Reg. Date:	13/09/2019 (Man. Year: 2019)		Odometer:	25026 km
Colour:	Grey			
Engine Capacity:	999 cc			
Market Value/New Car Price:	S\$120,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,021.00	1,630.40	3,390.60	67.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,072.00	1,522.00	2,550.00	62.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,093.00	3,152.40	5,940.60	65.33
+ GST 7.00/7.00% (S\$)	636.51	220.67	415.84	65.33
Nett Amount (S\$)	9,729.51	3,373.07	6,356.44	65.33

INSPECTION

Date of Assignment:	25/07/2022		
Date Inspected:	22/07/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,363.00 FS	*1,090.40 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	81.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Cut	316.00 FS	*252.80 FS
4	1		*REAR BUMPER TOW EYE COVER	Not Necessary	48.00 FS	*- FS
5	1		*REAR BUMPER REFLECTOR - RH	Not Necessary	34.00 FS	*- FS
6	1		*REAR INNER TAIL LIGHT - RH	Not Necessary	1,469.00 FS	*- FS
7	1		*REAR INNER TAIL LIGHT TRIM - RH	Not Necessary	34.00 FS	*- FS
8	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	615.00 FS	*- FS
9	2		*REAR BUMPER HOLDING STRAP - LH /RH	Not Necessary	30.00 FS	*- FS
10	1		*REAR BUMPER GUIDE SECTION	Not Necessary	60.00 FS	*- FS
11	1		*REAR PARKING AID SENSOR - OUTER	Not Necessary	265.00 FS	*- FS
12	4		*REAR PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
13	1		*REAR VENT TRIM	Not Necessary	36.00 FS	*- FS
14	2		*REAR WHEEL COVER - RH / RH	N/s Necessary / O/s Cut	360.00 FS	*287.20 FS
15	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					5,021.00	1,630.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR RHS TAILLAMP PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,600.00	500.00
3	TO RESPRAY REAR BUMPER AND RHS TAILLAMP PANEL	New	2,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			4,072.00	1,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >