

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22007025/AQCE2**Date:** 30/01/2023**REFERENCE**

Insured/Claimant:	ANG BOON CHIN	Policy No:	2070153547		
Date of Loss:	11/06/2022	Nature of Claim:	OD	Claim No:	1983994762SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW571T				
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Engine No:	CZDC07007		
Reg. Date:	30/10/2020 (Man. Year: 2020)	Chassis No:	WAUZZZF37M1021122		
Colour:	White	Odometer:	20691 km		
Engine Capacity:	1395 cc				
Market Value/New Car Price:	S\$168,000.00				
Sum Insured (S\$):	Market Value/New Car Price				

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,418.00	3,308.96	19,109.04	85.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,752.00	2,652.00	7,100.00	72.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,170.00	5,960.96	26,209.04	81.47
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	31,370.00	5,160.96	26,209.04	83.55
+ GST 8.00/8.00% (S\$)	2,509.60	412.88	2,096.72	83.55
Nett Amount (S\$)	33,879.60	5,573.84	28,305.76	83.55

INSPECTION

Date of Assignment:	25/07/2022		
Date Inspected:	22/07/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Not Necessary	1,235.00 FS	*- FS
2	1	*FRONT BUMPER CLOSING ELEMENT - RH	Not Necessary	66.00 FS	*- FS
3	1	*FRONT BUMPER GRILLE - CENTER	Not Necessary	242.00 FS	*- FS
4	1	*FRONT BUMPER GRILLE - RH	Not Necessary	124.00 FS	*- FS
5	1	*FRONT BUMPER CLOSING ELEMENT	Not Necessary	212.00 FS	*- FS
6	1	*FRONT BUMPER SPOILER	Cut	426.00 FS	*340.80 FS
7	1	*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	171.00 FS	*- FS
8	1	*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	43.00 FS	*- FS
9	1	*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	974.00 FS	*- FS
10	1	*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	114.00 FS	*- FS
11	1	*FRONT BUMPER TOP COVER	Not Necessary	137.00 FS	*- FS
12	1	*CAUTION STICKER	Not Necessary	16.00 FS	*- FS
13	1	*AIR COND STICKER	Not Necessary	9.00 FS	*- FS
14	1	*FRONT FENDER - RH	Dented	1,445.00 FS	*1,156.00 FS
15	1	*FRONT FENDER ATTACHMENT PARTS	Not Necessary	66.00 FS	*- FS
16	1	*FRONT FENDER BRACE - RH	Not Necessary	98.00 FS	*- FS
17	1	*FRONT FENDER BRACKET - RH	Not Necessary	39.00 FS	*- FS
18	1	*FRONT WHEEL HOUSING LINER	Not Necessary	260.00 FS	*- FS
19	1	*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	105.00 FS	*- FS
20	1	*FRONT WHEEL HOUSING LINER COVER - RH	Not Necessary	18.00 FS	*- FS
21	1	*HEADLIGHT MOUNTING - RH	Not Necessary	132.00 FS	*- FS
22	1	*HEADLIGHT - RH	Not Necessary	5,952.00 FS	*- FS
23	1	*LIFT CYLINDER - RH	Not Necessary	231.00 FS	*- FS
24	1	*LIFT CYLINDER HOSE	Not Necessary	92.00 FS	*- FS
25	2	*FRONT WHEEL ARCH COVER - LH / RH	N/S Necessary / O/S Cut	566.00 FS	*452.00 FS
26	1	*FRONT DOOR - RH	Not Necessary	3,017.00 FS	*- FS
27	1	*FRONT DOOR OUTER SEAL - RH	Not Necessary	185.00 FS	*- FS
28	1	*FRONT DOOR ATTACHMENT PARTS	Not Necessary	164.00 FS	*- FS
29	1	*FRONT DOOR CATCH - RH (NPA)	Not Necessary	0.00 FS	*- FS
30	1	*FRONT DOOR COVER - RH	Cut	283.00 FS	*226.00 FS
31	1	*WING MIRROR MOUNTING - RH	Not Necessary	2,278.00 FS	*- FS
32	1	*WING MIRROR CAP - RH	Not Necessary	203.00 FS	*- FS
33	1	*WING MIRROR GLASS - RH	Not Necessary	1,052.00 FS	*- FS
34	1	*ALUMINIUM RIM	Cut	1,414.00 FS	*1,131.20 FS
35	1	*RUBBER VALVE	Necessary	4.00 FS	*2.96 FS
36	1	*NOISE INSULATION	Not Necessary	515.00 FS	*- FS
37	1	*STONE CHIP	Not Necessary	180.00 FS	*- FS
38	1	*SUNDRIES	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 22,418.00 3,308.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	400.00	0.00
4	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR, RHS WING MIRROR COVER AND RHS SILL PANEL	New	4,500.00	700.00
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
7	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR AND RHS HEADLIGHT. TO REPAIR RHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,500.00	1,000.00
Gross Labour Cost (\$\$)			9,752.00	2,652.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >