9/12/22, 8:34 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG22007031/KPA3Q2

12/09/2022 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle SMM9006C Insured Vehicle No: SMW3721H No:

Date of Loss: 19/07/2022 Nature of Claim: Claim No: 4666541728SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMM9006C

Make & Model: AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A) Engine No: DAX037943

Reg. Date: 10/09/2018 (Man. Year: 2018) Chassis No: WAUZZZFY2J2171074

Colour: Metallic Silver Odometer: 110465 km

Engine Capacity: 1984 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 235/55 R19 Rear Tyre Size: 235/55 R19 Front Left Side: Rear Left Side: Goodyear 8 mm Goodyear 8 mm Front Right Side: Goodyear 8 mm Rear Right Side: Goodyear 8 mm

The above values represent the remaining tyre treads depth

| Repairer's | Adjuster's | Difference | Diff % |
|---------------------|---|--|--|
| 6,270.21 | 3,520.76 | 2,749.45 | 43.85 |
| 0.00 | 0.00 | 0.00 | |
| 1,020.00 | 710.00 | 310.00 | 30.39 |
| 0.00 | 0.00 | 0.00 | |
| 0.00 | 0.00 | 0.00 | |
| 7,290.21 | 4,230.76 | 3,059.45 | 41.97 |
| | 3,350.00 | | |
| 7,290.21 | 3,350.00 | 3,940.21 | 54.05 |
| 510.31 | 234.50 | 275.81 | 54.05 |
| 7,800.52 | 3,584.50 | 4,216.02 | 54.05 |
| 100.00/day) (S\$) | 300.00 | | |
| Search Fee (S\$) | 2.00 | | |
| ett Liability (S\$) | 3,886.50 | | |
| | 6,270.21 0.00 1,020.00 0.00 0.00 7,290.21 7,290.21 510.31 | 6,270.21 3,520.76 0.00 0.00 1,020.00 710.00 0.00 0.00 7,290.21 4,230.76 3,350.00 7,290.21 3,350.00 7,290.21 3,350.00 7,800.52 3,584.50 100.00/day) (\$\$) Search Fee (\$\$) 2.00 | 6,270.21 3,520.76 2,749.45 0.00 0.00 0.00 1,020.00 710.00 310.00 0.00 0.00 0.00 0.00 0.00 0.00 7,290.21 4,230.76 3,059.45 3,350.00 7,290.21 3,350.00 3,940.21 510.31 234.50 275.81 7,800.52 3,584.50 4,216.02 100.00/day) (\$\$) 300.00 Search Fee (\$\$) 2.00 |

INSPECTION

Date of Assignment: 25/07/2022

Date Inspected: 25/07/2022 Inspected At: 9A Serangoon North Ave 5

Optima Werkz Pte Ltd (HQ)

Singapore 554500

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG Manager: **CHEW HSIAO TONG**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and

9/12/22, 8:34 AM Adjuster Report

 $ability\ but\ any\ other\ liability\ under\ any\ other\ circumstances\ is\ hereby\ expressly\ excluded.$

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|---|--|---------------|---|-------------------|-------------|--------------|
| 1 | 1 | | *REAR BUMPER | Buckled / Cracked | 1,584.70 FL | *1,525.60 FL |
| 2 | 1 | | *REAR BUMPER LOWER | Cracked | 1,067.40 FL | *956.80 FL |
| 3 | 1 | | *REAR BUMPER DIFFUSER | Serviceable | 774.50 FL | *- FL |
| 4 | 1 | | *REAR BUMPER REFLECTOR LAMP LH | Cracked | 583.80 FL | *559.20 FL |
| 5 | 1 | | *REAR BUMPER REFLECTOR LAMP RH | Cracked | 583.80 FL | *559.20 FL |
| 6 | 2 | | *REAR BUMPER REVERSE SENSOR | Serviceable | 970.40 FL | *- FL |
| 7 | 1 | | *REAR BUMPER REINFORCEMENT | Repair | 825.10 FL | *-FL |
| 8 | 1 | | *REAR BUMPER CLIPS | Necessary | 100.00 FS | *100.00 FS |
| 9 E=Era | 1 | nart S=SncN | *REAR BUMPER RIVET ett. L=ListItemDisc. | Not Necessary | 100.00 FS | *-FS |
| 1 -110 | IIIOIIIGE | part. 0-opciv | ett. E-Eistiembise. | Sub Total (S\$) | 6,589.70 | 3,700.80 |
| | - List Item Discount on L Items 5.00/5.00% (S\$) | | | 319.49 | 180.04 | |
| | | | | Total Parts (S\$) | 6,270.21 | 3,520.76 |
| Report was unsubmitted during this print-out. | | | | | | |

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-----|--|---------------|------------|--------|
| Lab | our Items | | | |
| 1 | LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST ACCIDENT AREAS | New | 400.00 | 250.00 |
| 2 | LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS | New | 400.00 | 400.00 |
| 3 | LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC | New | 120.00 | 60.00 |
| 4 | TO CHECK WIRING & ELECTRICAL DIAGNOSTIC | New | 100.00 | 0.00 |
| | Gross Labor | ur Cost (S\$) | 1,020.00 | 710.00 |
| | Report was unsubmitted during this | print-out. | | |

< END OF ESTIMATES >