

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA22007043/UQY3M4**Date:** 11/08/2022REFERENCE

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP309941
Claimant Vehicle No :	SJV2206B	Insured Vehicle No :	SLN2202E
Date of Loss:	22/07/2022	Nature of Claim:	TP
		Claim No:	MPC03562/JG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV2206B	Engine No:	1NZY016072
Make & Model:	TOYOTA VIOS, 1.5 (A)	Chassis No:	MR053HY9305144094
Reg. Date:	15/01/2010 (Man. Year: 2009)	Odometer:	101794 km
Colour:	Red		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Windforce 6 mm	Rear Left Side:	Windforce 6 mm
Front Right Side:	Windforce 6 mm	Rear Right Side:	Windforce 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,548.50	3,496.15	5,052.35	59.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,680.00	1,770.00	2,910.00	62.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,228.50	5,266.15	7,962.35	60.19
Approved Total (Overridden) (S\$)		4,200.00		
Nett Amount (S\$)	13,228.50	4,200.00	9,028.50	68.25

INSPECTION

Date of Assignment:	25/07/2022		Nineteen Autowerks Pte Ltd (HQ)
Date Inspected:	25/07/2022	Inspected At:	Block 436 Tampines Street 43, #07-97
Estimated Period of Repair:	5.0 days		Singapore 520436

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Aug 2022)
Parts:	143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJV2206B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent / Buckled	1,057.50 FL	*755.10 FL
2	1		*BOOTLID LOGO	Necessary	96.20 FL	*68.50 FL
3	1		*BOOTLID EMBLEM VIOS	Necessary	85.00 FL	*48.00 FL
4	1		*BOOTLID EMBLEM E	Necessary	35.00 FL	*35.00 FL
5	1		*BOOTLID GARNISH	Not Necessary	238.60 FL	*- FL
6	1		*BOOTLID INNER LOCK	Twisted	385.60 FL	*189.50 FL
7	2		*TAILLAMPS	Cracked	1,166.00 FL	*714.20 FL
8	2		*TAILLAMPS BRACKET	Not Necessary	135.80 FL	*- FL
9	1		*REAR BUMPER	Distorted	856.00 FL	*451.90 FL
10	2		*REAR BUMPER SIDE RETAINER	Bent	172.00 FL	*172.00 FL
11	1		*REAR BUMPER REFLECTOR	N/s Cracked (1Piece Only)	210.80 FL	*105.40 FL
12	1		*REAR BUMPER REINFORCEMENT	No such part	358.00 FL	*- FL
13	1		*REAR BUMPER SPLESH SHIELD N/S	Torn	176.50 FL	*68.50 FL
14	2		*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	251.40 FL	*- FL
15	1		*REAR END PANEL	Badly Dented	788.50 FL	*655.10 FL
16	1		*REAR END PANEL TOP GARNISH	Twisted	261.00 FL	*200.80 FL
17	2		*REAR FENDERS	Repair	1,851.00 FL	*- FL
18	1		*EXHAUST MUFFLER	Not Necessary	1,325.80 FL	*- FL
19	3		*EXHAUST MOUNTING	Not Necessary	203.10 FL	*- FL
20	1		*REAR FLOOR PANEL TOP BOARD	Torn	248.00 FL	*248.00 FL
21	2		*REAR FLOOR PANEL TOOL SPONGES	Torn	576.20 FL	*576.20 FL
22	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*40.00 FS
23	1		*SET REVERSE SENSOR WITH MODULE	Shorted	300.00 FS	*200.00 FS
24	1		*CARPLATE	Not Necessary	80.00 FS	*- FS
25	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*40.00 FS
26	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
27	1		*SUNDRIES	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,168.00	4,568.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,619.50	1,072.05
Total Parts (\$\$)	8,548.50	3,496.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,200.00	600.00
2	SPRAY PAINTING	New	1,800.00	980.00
3	REMOVE & REFIT BOOTLID COMPONENT	New	100.00	60.00
4	REMOVE & REFIT REVERSE SENSOR AND TEST	New	100.00	50.00
5	REMOVE & REFIT EXHAUST MUFFLER	New	280.00	0.00
6	CHECK WIRING SYSTEM AFTER DISCONNECT & CONNECT	New	100.00	20.00
7	TO APPLY UNDERCOATING FOR RUST ROOFING	New	100.00	60.00
Gross Labour Cost (\$\$)			4,680.00	1,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >