

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988

Our File No: CS/EGI22007047/KQY3Q2**Date:** 11/01/2023**REFERENCE**

Insured/Claimant: PACKAGING HUB (S) PTE.LTD. Policy No: DMCG21014266
Date of Loss: 18/07/2022 Nature of Claim: OD Claim No: CDMCG22001423

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YN9586Y**
Make & Model: MITSUBISHI CANTER, 3.0 D FEB21ER4SDEB (CBU) (M) Engine No: 4P10B85841
Reg. Date: 15/10/2015 (Man. Year: 2015) Chassis No: FEB21EA10588
Colour: Green Odometer: 125758 km
Engine Capacity: 2998 cc
Market Value/New Car Price: S\$36,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/85 R15 Rear Tyre Size: 195/85 R15 (D)
Front Left Side: Yokohama 9 mm Rear Left Side: Yokohama 6/6 mm
Front Right Side: Yokohama 9 mm Rear Right Side: Yokohama 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,042.00	7,381.00	1,661.00	18.37
Miscellaneous Items	1,035.00	35.00	1,000.00	96.62
Labour	1,853.82	1,817.97	35.85	1.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,930.82	9,233.97	2,696.85	22.60
+ GST 7.00/7.00% (S\$)	835.16	646.38	188.78	22.60
Nett Amount (S\$)	12,765.98	9,880.35	2,885.63	22.60

INSPECTION

Date of Assignment: 25/07/2022 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected: 26/07/2022 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Estimated Period of Repair: 6.0 days Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 11 Jan 2023)	
Parts:	N/A	mitsubishi canter 3.0 d feb21er4sdeb (cbu) (m) (model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN9586Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		7,770.00 F	*6,260.00 F
Supplementary #1						
2	1		*CAB SUPPORT	Bent	450.00 F	*450.00 F
					Sub Total (S\$)	8,220.00
					+ Margin on L,N Items 10.00/10.00% (S\$)	822.00
					Total Parts (S\$)	9,042.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	EXTRAS	1,035.00	35.00
Sub Total (\$\$)			1,035.00	35.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	1,111.50	1,066.50
2	SPRAY PAINTING	New	742.32	751.47
Gross Labour Cost (\$\$)			1,853.82	1,817.97

Report was unsubmitted during this print-out.

< END OF ESTIMATES >