



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBE 901A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
2	FRONT FORK TUBE ASSY (CONSISTENT)	NOT NECESSARY	640.00	-
1	FORK UNDER BRACKET (CONSISTENT)	NOT NECESSARY	185.00	-
1	FRONT WHEEL RIM (CONSISTENT)	NOT NECESSARY	380.00	-
1	FRONT RIM SHAFT (CONSISTENT)	NOT NECESSARY	45.00	-
1	FRONT RIM BEARING (CONSISTENT)	NOT NECESSARY	38.00	-
1	FRONT BRAKE DISC (CONSISTENT)	NOT NECESSARY	155.00	-
1	HANDLE-BAR (CONSISTENT)	BENT	88.00	88.00
1	HANDLE-BAR END (N/S) (CONSISTENT)	CUT	90.00	30.00
1	SET HAND GRIP (CONSISTENT)	TORN	55.00	40.00
1	SIDE MIRROR (N/S) (CONSISTENT)	CUT	110.00	60.00
1	CLUTCH LEVER (CONSISTENT)	CUT	42.00	42.00
1	FRONT SIGNALS (N/S) (CONSISTENT)	CRACKED	140.00	105.00
1	SET FAIRING ASSY (CONSISTENT)	CUT	525.00	480.00
1	FRONT FOOTREST BRACKET (CONSISTENT)	BENT	85.00	85.00
2	FRONT FOOTREST RUBBERS (CONSISTENT)	N/S TORN (1PIECE ONLY)	70.00	30.00
1	GEAR PEDAL (CONSISTENT)	BENT	58.00	58.00
2	REAR FOOTRESTS (CONSISTENT)	N/S CUT (1PIECE ONLY)	80.00	40.00
2	REAR FOOTREST BRACKETS (CONSISTENT)	SERVICEABLE	156.00	-
1	REAR LAMP (CONSISTENT)	CRACKED	325.00	205.00
1	REAR FENDER (CONSISTENT)	CRACKED	258.00	148.00
	LESS 10% DISCOUNT		-352.50	-141.10
			3,172.50	1,269.90
<u>SPECIAL NETT ITEMS</u>				
1	SET NUMBER PLATE (REAR) (SN) (CONSISTENT)	CRACKED	38.00	15.00
2	FORK OILS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN) (CONSISTENT)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN) (CONSISTENT)	NOT NECESSARY	90.00	-
1	E.R.P. IU (SN) (CONSISTENT)	SERVICEABLE	180.00	-
1	REAR BOX (SN) (CONSISTENT)	CUT	380.00	200.00

Report Ref No. CS/ASM22007055/Uvy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOX BRACKET (SN) (CONSISTENT)	BENT	180.00	100.00
			954.00	315.00
	<u>LABOUR</u> TO CHECK WIRING AND RESET HEADLAMP FOCUSING. TO REPAIR BODY FRAME. TO PROVIDE LABOUR.	NOT NECESSARY NOT NECESSARY	80.00	-
			480.00	-
			420.00	300.00
			980.00	300.00
GRAND TOTAL			5,106.50	1,884.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,500.00

Report Ref No. CS/ASM22007055/Uvy3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.