

ASS. REC. BY:

REF:

LPC / 22007036/KP

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SLX9067E

Yr Regn:

04, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kia Sorento

c.c

2199

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

118943

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KNAPH81BMJ 5448547

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F:

235/60 R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

21/7/22

D.O.I.

1/8/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Soon Seng Company (SG) Pte Ltd

160 Sin Ming Drive
#04-05
Sin Ming Autocity
S575722

Our client SLX9067E
TP claim against Lonpac Insurance (Your insured: GBE8624Y)

Repairer's estimate

Parts

1	Fender clips	10	3	30
2	Bumper retainer	2	80	160
3	Front bumper	1	1450	1,450
4	Bumper clips	10	3	30
5	Front bumper LH black trim	1	250	250
6	Front PDC sensor	2	200	400
7	Front bonnet	1	1640	1,640
8	Bonnet inner heat foam	1	580	580
9	Bonnet hinge	2	190	380
10	Bonnet damper	2	280	560
11	Front grille	1	650	650
12	Lower grille	1	420	420
13	LH front headlight	1	2800	2,800
14	LH front headlight bracket	1	275	275
15	LH front LED fog lamp + garnish	1	850	850
16	19" Sports Rims	1	1200	1,200
17	Front LH Tyre	1	600	600
18	LH Front fender	1	1230	1,230
19	LH Front fender shield	1	290	290
20	LH fender black trim	1	240	240
21	Fender / Bumper trim rivets	20	5	100
22	Front LH lower arm	1	690	690
23	Front LH control arm	1	650	650
24	Front LH wheel bearing	1	540	540
25	Front LH knuckle arm	1	1320	1,320
26	Front LH upper arm	1	750	750
27	Front LH driveshaft	1	1880	1,880
28	Front LH absorber	1	950	950
29	Front steering rack	1	1480	1,480
30	Front LH steering tie rod (mid link)	1	320	320
31	Front LH steering tie rod end	1	365	365
Parts Total:				\$ 23,080.00

Labor

1	Check wiring and system function	1	380	380
2	Rust proofing on affected areas	1	500	500
3	Wheel Alignment before and after repair	1	260	260
4	Programming of new headlight	1	350	350
5	Labor to remove and refit front fender, front bumper, (FRONT LH) lower arm and suspension components, rim and tyre, headlight, bonnet	1	2500	2,500
6	To respray damaged and refitted parts (Front fender, front bumper, bonnet)	1	1200	1,200
Labor Total:				\$ 5,190.00

TOTAL: \$ 28,270.00

*Supplementary items would be included if noticed during the course of repair

Contact:

James - 92960289
Mr Chai - 96250518

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Notified
Resurvey Began
5 days

Henrich
96910663

Wheel Alignment
regrind needed

201
301
601
?

4501

4401

108