

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/GRB22007059/KPA3Q2**Date:** 06/10/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447\_01  
**Claimant Vehicle No :** SMA8886Z **Insured Vehicle No :** SNF8566J  
 Date of Loss: 13/07/2022 Nature of Claim: TP Claim No: MFL2022D0003855

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA8886Z**  
 Make & Model: SUBARU FORESTER, 2.0 I-L CVT AWD SR (A) Engine No: FB20YD96884  
 Reg. Date: 26/06/2018 (Man. Year: 2018) Chassis No: JF1SJ5KC5JG110444  
 Colour: Metallic Grey Odometer: 146896 km  
 Engine Capacity: 1995 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R17 Rear Tyre Size: 225/60 R17  
 Front Left Side: Yokohama 9 mm Rear Left Side: Yokohama 9 mm  
 Front Right Side: Yokohama 9 mm Rear Right Side: Yokohama 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,159.60	3,045.28	2,114.32	40.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,050.00	830.00	1,220.00	59.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,209.60</b>	<b>3,875.28</b>	<b>3,334.32</b>	<b>46.25</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,100.00</b>		
<b>Nett Amount (S\$)</b>	<b>7,209.60</b>	<b>3,100.00</b>	<b>4,109.60</b>	<b>57.00</b>
<b>+ Loss of Use (5.0 x S\$100.00/day) (S\$)</b>		500.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>3,607.45</b>		

INSPECTION

Date of Assignment: 22/07/2022  
 Date Inspected: 03/08/2022 Inspected At: Kent Seng Car Services (HQ)  
 BLK 1017 YISHUN INDUSTRIAL PARK A #01-240  
 Singapore 768759  
 Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG    Version: 1.0 (Last Synchronised: 23 Sep 2022)

**Parts:** M1-SUV    SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's    (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMA8886Z)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	649.70 F	*649.70 FL
2	10		*FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
3	1		*FRONT BUMPER LEFT HAND SIDE RETAINER	Distorted	35.10 F	*35.10 FL
4	1		*FRONT BUMPER FOG LAMP GARNISH (LEFT)	Serviceable	66.90 F	*- FL
5	1		*FRONT BUMPER FOG LAMP CHROME (LEFT)	Serviceable	58.40 F	*- FL
6	1		*FRONT BUMPER FOG LAMP (LEFT)	Serviceable	281.70 F	*- FL
7	1		*FRONT LEFT SIDE FENDER	Bent	495.80 F	*495.80 FL
8	1		*FRONT LEFT SIDE FENDER INNER COWLING	Deformed	135.70 F	*135.70 FL
9	8		*FRONT LEFT SIDE FENDER INNER COWLING CLIPS	Necessary	40.00 F	*40.00 FL
10	1		*FRONT LEFT SIDE HEAD LAMP	Mtg Cracked	2,580.40 F	*2,400.30 FL
11	1		*FRONT LEFT SIDE TYRE RIM	Serviceable	765.90 F	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,159.60</b>	<b>3,806.60</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	0.00	761.32

<b>Total Parts (\$\$)</b>	<b>5,159.60</b>	<b>3,045.28</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	STRAIGHTENING ,REPAIRING AND REALIGNING ONTO THE FRONT AFFECTED AREA ,CUTTING FRONT LEFT SIDE FENDER ,DISMANTLE & REPLACE THE ABOVE MENTIONED PARTS	New	1,100.00	400.00
2	TO PUTTY AND RE-SPRAY PAINTING ON FRONT BUMPER ,FRONT LEFT SIDE FENDER & TOUCH UP FRONT LEFT SIDE DOOR	New	800.00	400.00
3	RUST PROOFING ON THE FRONT ACCIDENT AFFECTED PORTIONS	New	150.00	30.00
			<b>Gross Labour Cost (\$\$)</b>	<b>2,050.00</b>
				<b>830.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >