

Vehicle Damage Assessment Report for [SMA8886Z]

Estimate Created: 09/09/2022 08:30 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 12/09/2022 00:14 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	III	Claim Number	MFL2022D0003855
Claim Type	TP		
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number	

Vehicle Information

Brand	Subaru	Model	Forester
Engine Type			
License Plate Number	SMA8886Z	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram		Odometer	146,896.00 Km
		Tyres Condition	
		Front Left	YOKOHAMA 225/60 R17 9.0 mm
		Front Right	YOKOHAMA 225/60 R17 9.0 mm
		Rear Left	YOKOHAMA 225/60 R17 9.0 mm
		Rear Right	YOKOHAMA 225/60 R17 9.0 mm

Comments

- Final review base on information provide by LKK: Concluded the cost of repair at lump sum \$3100.00 with 4 days for repair

Insurlogic 1 (12/09/2022 00:13)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
FRONT BUMPER		1	649.70	-20.00 %	519.76
FRONT BUMPER CLIPS		1	50.00	-20.00 %	40.00
FRONT BUMPER RETAINER LH		1	35.10	-20.00 %	28.08
FRONT FENDER LH		1	495.80	-20.00 %	396.64
FRONT FENDER INNER COWLING LH		1	135.70	-20.00 %	108.56
FRONT FENDER INNER COWLING CLIPS		1	40.00	-20.00 %	32.00
HEADLAMP LH		1	2400.30	-20.00 %	1,920.24
Parts Subtotal					3,045.28

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
REPLACE FRONT FENDER LH, HEADLAMP LH AND FRONT BUMPER	RnR	400.00	0.00 %	400.00
ANTI RUST	RnR	30.00	0.00 %	30.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price	
FRONT BUMPER AND FENDER LH	Full spray	400.00	0.00 %	400.00	
Labor Rate	S\$ 50 / Hour	General Labor Subtotal		430.00	
				Paint Labor Subtotal	400.00
				Labor Subtotal	830.00

Summary

Repair Cost	3,875.28
Discount(20 %)	(775.28)
	3,100.00
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	3,100.00