

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	MS FIRST CAPITAL INSURANCE LTD		_	Ref:	CS3/FCI22007069/Vcy3m4	
	36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date:	31/08/2022	
				Code:	FCI2	
1.	1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	XD 8090G	Veh. Inspected		SMP 8533M	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	D22002259MFVS	Excess (\$)		0.00	
	Assign From	AINI BINTE	Assign Date		25/07/2022	
2. Vehicle Particulars & Condition						
	Make & Model	SUZUKI SWIFT SPORT	c.c		1371	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	ZC33S118621	Colour		BLUE	
	Odometer	67304 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/50 R16	BRIDGESTONE		8 mm	
	L/H Front Tyre	205/50 R16	BRIDGESTONE		8 mm	
	R/H Rear Tyre	205/50 R16	BRIDGESTONE		8 mm	
	L/H Rear Tyre	205/50 R16	BRIDGESTONE		8 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
5.	5. General Information					
	Accident Date	23/07/2022	Inspect Date / T	Time	26/07/2022 ( 05:00 PM )	
	Survey held at	GARAGE 13 PTE LTD				
		8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.				
5a.	5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$99,000.00					

Report Ref No. CS3/FCI22007069/Vcy3m4

Inspected By

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

Asst. Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser