

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22007070/VCY3E2**Date:** 30/12/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00083812100
<b>Claimant Vehicle No :</b>	GBF1892E	<b>Insured Vehicle No :</b>	YP7021M
Date of Loss:	18/07/2022	Nature of Claim:	TP
		Claim No:	SNM22D205047/C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBF1892E</b>	Engine No:	67196022680320
Make & Model:	SSANGYONG ACTYON, 2.0 2WD (A)	Chassis No:	KPADA1ETSGP271714
Reg. Date:	21/07/2016 (Man. Year: 2016)	Odometer:	48477 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/75 R16	Rear Tyre Size:	225/75 R16
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,075.00	1,075.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,075.00</b>	<b>1,075.00</b>	<b>0.00</b>	<b>0.00</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>75.25</b>	<b>75.25</b>	<b>0.00</b>	<b>0.00</b>
<b>Nett Amount (S\$)</b>	<b>1,150.25</b>	<b>1,150.25</b>	<b>0.00</b>	<b>0.00</b>

**INSPECTION**

Date of Assignment:	25/07/2022	
Date Inspected:	25/07/2022	Inspected At: Indeco Engineers Pte Ltd (upp Changi) (HQ) 7 Abingdon Road Singapore 499931
Estimated Period of Repair:	2.0 days	

**Adjuster:** Thevan Thomas Karthikesavan**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Dec 2022)
Parts:	M1-SUV	SSANGYONG ACTYON 2.0 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF1892E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING AND REPAIR REAR RHS FENDER }	New	1,075.00	1,075.00
2	PUTTY, SANDING, MASKING AND SPRAY PAINTING OF REAR RHS FENDER }	New	-	-
3	TOUCH UP ON REAR RHS BUMPER }	New	-	-
4	REMOVE BROKEN REAR RHS TAIL LAMP ASSEMBLY }	New	-	-
5	INSTALL NEW REAR RHS TAIL LAMP ASSEMBLY } (BROKEN)	New	-	-
6	CARRY OUT FUNCTIONAL TEST POST COMPLETION OF WORK }	New	-	-
<b>Gross Labour Cost (\$\$)</b>			<b>1,075.00</b>	<b>1,075.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >